

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EQI22003167/VTY3E2

Date: 20/05/2022

REFERENCE

Handling Insurer: EQ Insurance Company Ltd

Policy No:

Claimant Vehicle No : SHB4803T

Insured Vehicle No : GBE5553M

Date of Loss: 01/04/2022

Nature of Claim: TP

Claim No: DM22HO00510

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHB4803T**

Make & Model: TOYOTA PRIUS HYBRID, 1.8 CVT (A)

Engine No: 2ZRS054792

Reg. Date: 17/08/2017 (Man. Year: 2017)

Chassis No: JTDKB3FU703560854

Colour: Yellow

Odometer: 0 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: West Lake 5 mm

Rear Left Side: West Lake 5 mm

Front Right Side: West Lake 5 mm

Rear Right Side: West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,520.42	10,907.19	4,613.23	29.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,890.00	1,850.00	2,040.00	52.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,410.42	12,757.19	6,653.23	34.28
Approved Total (Overridden) (S\$)		10,200.00		
(S\$)	19,410.42	10,200.00	9,210.42	47.45
+ GST 7.00/7.00% (S\$)	1,358.73	714.00	644.73	47.45
Nett Amount (S\$)	20,769.15	10,914.00	9,855.15	47.45

INSPECTION

Date of Assignment: 05/04/2022 Present Location:

ComfortDelGro Engineering Pte Ltd (Loyang)

Date Inspected: 06/04/2022 Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)

59 Loyang Drive

Singapore 508969

Estimated Period of Repair: 4.0 days

Adjuster: Thevan Thomas Karthikesavan

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 May 2022)
Parts:	144	TOYOTA PRIUS HYBRID 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHB4803T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cut	503.04 FL	*503.04 FL
2	1		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
3	1		*REAR BUMPER LOWER COVER	Cut	654.96 FL	*654.96 FL
4	1		*REAR BUMPER UNDER SIDE CENTRE COVER	Cut	654.96 FL	*654.96 FL
5	1		*COVER FLOOR UNDER NO. 2	Missing	220.50 FL	*220.50 FL
6	1		*REAR BUMPER UNDER SIDE COVER RH	Cut	232.00 FL	*232.00 FL
7	1		*REAR BUMPER TOWING COVER	Cut	82.70 FL	*82.70 FL
8	1		*REAR BUMPER SIDE RETAINER LH	Necessary	112.70 FL	*112.70 FL
9	1		*REAR BUMPER SIDE RETAINER RH	Necessary	112.70 FL	*112.70 FL
10	1		*REAR BUMPER REINFORCEMENT	Dented	378.32 FL	*378.32 FL
11	1		*REAR BUMPER ARM ASSY LH	Dented	139.60 FL	*139.60 FL
12	1		*REAR BUMPER ARM ASSY RH	Dented	139.60 FL	*139.60 FL
13	1		*REAR BUMPER SIDE EXTENTION RH	Cut	148.40 FL	*148.40 FL
14	1		*REAR END PANEL	Serviceable	738.96 FL	*- FL
15	1		*REAR END PANEL GARNISH	Serviceable	165.80 FL	*- FL
16	1		*REAR WIRING ASSY	Serviceable	582.40 FL	*- FL
17	1		*REAR SPOILER SUB ASSY	Dented	1,787.79 FL	*1,787.79 FL
18	1		*ROOF TOP CENTER COVER-BLACK	Missing	956.30 FL	*956.30 FL
19	1		*BACK DOOR GARNISH SUB ASSY	Dented	1,054.71 FL	*1,054.71 FL
20	1		*REAR TRUNK LID LOGO (PRIUS)	Necessary	62.14 FL	*62.14 FL
21	1		*REAR TRUNK LID LOGO (HYBRID)	Necessary	62.14 FL	*62.14 FL
22	1		*REAR TRUNK LID LOGO (TOYOTA STAR)	Necessary	81.43 FL	*81.43 FL
23	1		*TAIL LAMP UPPER RH	Cracked	557.90 FL	*557.90 FL
24	1		*TAIL LAMP LOWER RH	Cracked	570.00 FL	*570.00 FL
25	1		*REAR SPARE TYRE PANEL	Not Necessary	667.70 FL	*- FL
26	1		*REAR WINDSCREEN GLASS WITH MOULDING	Necessary	1,884.32 FL	*1,884.32 FL
27	1		*REAR TRUNK LID COVER	Necessary	1,303.29 FL	*1,303.29 FL
28	1		*REAR TRUNK LID GLASS	Necessary	1,569.70 FL	*1,569.70 FL
29	1		*REAR TRUNK LID HINGE LH	Serviceable	69.32 FL	*- FL
30	1		*REAR TRUNK LID HINGE RH	Serviceable	69.32 FL	*- FL
31	1		*REAR TRUNK LID LOCK	Jammed	530.79 FL	*530.79 FL
32	1		*REAR TRUNK LID COVER TRIM BOARD	Serviceable	254.40 FL	*- FL
33	1		*BOOT LID TRIMBOARD CENTRE	Serviceable	159.60 FL	*- FL
34	1		*BOOTLID TRIMBOARD SIDE RH	Serviceable	92.50 FL	*- FL
35	1		*BOOT HANDLE	Serviceable	31.80 FL	*- FL
36	1		*REAR TRUNK LID RUBBER	Serviceable	365.20 FL	*- FL
37	1		*REAR TRUNK LID ABSORBER LH	Serviceable	287.50 FL	*- FL
38	1		*REAR TRUNK LID ABSORBER RH	Serviceable	287.50 FL	*- FL
39	1		*REAR TRUNK LID STOPPER LH	Serviceable	84.80 FL	*- FL
40	1		*REAR TRUNK LID STOPPER RH	Serviceable	84.80 FL	*- FL
41	1		*REAR EXHAUST PIPE CENTRE INSULATOR	Repair	498.60 FL	*- FL
42	1		*REAR EXHAUST PIPE HANGER	Serviceable	40.70 FL	*- FL
43	1		*REAR EXHAUST PIPE	Repair	1,163.40 FL	*- FL
44	1		*REPLACE REAR FENDER ADVERTISEMENT LOGO LH	Necessary	100.00 F	*100.00 F
45	1		*REPLACE REAR FENDER ADVERTISEMENT LOGO RH	Necessary	100.00 F	*100.00 F
46	1		*REPLACE REAR BUMPER ADVERTISEMENT LOGO	Necessary	50.00 F	*50.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*REVERSE CAMERA ASSY	Serviceable	380.00 F	*- F
48	1		*REAR TRUNK LID COMFORT & TEL NO. STICKER	Necessary	60.00 F	*60.00 F
49	1		*REAR TRUNK LID APPS STICKER	Necessary	40.00 F	*40.00 F
50	1		*REAR BUMPER RUBBER MAT	Necessary	55.00 F	*55.00 F
51	1		*REAR REVERSE SENSOR	Cut	135.70 F	*135.70 F

F=Franchise part. L=ListItemDisc.

	Sub Total (\$\$)	20,386.99	14,362.69
- List Item Discount on L Items 25.00/25.00% (\$\$)		4,866.57	3,455.50
	Total Parts (\$\$)	15,520.42	10,907.19

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,900.00	700.00
2	SPRAY PAINTING CHARGE	New	1,350.00	750.00
3	TOWING FEE - KING DOLLY	New	150.00	100.00
4	CHECK ALL LIGHTING	New	80.00	40.00
5	TUFF KOTE	New	80.00	40.00
6	REMOVE/ REFIX EXHAUST PIPE	New	150.00	70.00
7	REMOVE/ REFIX REAR WINDSCREEN GLASS	New	120.00	120.00
8	REMOVE/REFIX REVERSE SENSOR	New	60.00	30.00
Gross Labour Cost (\$\$)			3,890.00	1,850.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >