

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

India International Insurance Pte Ltd  
64 Cecil Street, #04-00 IOB Building  
Singapore 049711

**Our File No:** CS/III22003168/KVY3E2

**Date:** 29/04/2022

### REFERENCE

Insured/Claimant: COMFORTDELGRO RENT-A-CAR PTE LTD Policy No: D20MFL0000326\_01

Date of Loss: 25/03/2022

Nature of Claim: OD

Claim No: MFL2022D0001760

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SFH8800S**  
Make & Model: VOLVO V60, 2.0 T2 CROSS COUNTRY (A) Engine No: B4204T112215713  
Reg. Date: 16/11/2017 (Man. Year: 2017) Chassis No: YV1FZ40LDJ2045410  
Colour: White Odometer: 0 km  
Engine Capacity: 1969 cc  
Market Value/New Car Price: S\$90,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 235/50R18 Rear Tyre Size: 235/50R18  
Front Left Side: Davanti 4 mm Rear Left Side: Davanti 8 mm  
Front Right Side: Davanti 4 mm Rear Right Side: Davanti 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	33,891.75	26,367.75	7,524.00	22.20
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	3,210.00	2,260.00	950.00	29.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>37,112.75</b>	<b>28,638.75</b>	<b>8,474.00</b>	<b>22.83</b>
<b>+ GST 7.00/0.00% (S\$)</b>	<b>2,597.89</b>	<b>0.00</b>	<b>2,597.89</b>	<b>100.00</b>
<b>Nett Amount (S\$)</b>	<b>39,710.64</b>	<b>28,638.75</b>	<b>11,071.89</b>	<b>27.88</b>

### INSPECTION

Date of Assignment: 06/04/2022 Present Location: ComfortDelGro Engineering Pte Ltd (Braddell)  
Date Inspected: 06/04/2022 Inspected At: ComfortDelGro Engineering Pte Ltd (Braddell)  
205 Braddell Road  
Singapore 579701  
Estimated Period of Repair: 6.0 days

**Adjuster:** KENNETH KONG

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

(EXCLUDE CHECK ITEMS S\$5,508.00 NETT)

**TOTAL LOSS ASPECT**

Market Value :	\$90,000.00
OMV :	\$31,565.00
PARF Rebate (1) :	\$27,143.00
Quota Premium Paid :	\$57,000.00
COE Rebate (2) :	\$31,967.00
Total Rebate (1) + (2) = :	\$59,110.00

The total amount incurred will be Market Value \$90,000.00 minus Total Rebate \$59,110.00 = \$30,890.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

# REPAIR DETAILS

## Reference

<b>Part Source:</b>	(Last Synchronised: 28 Apr 2022)	
<b>Parts:</b>	N/A	VOLVO V60 2.0 T2 CROSS COUNTRY (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SFH8800S)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*DRIVER AIRBAG	Burst	2,550.00 FL	*2,550.00 FL
2	1		*DRIVER CLOCK SPRING	Necessary	450.00 FL	*450.00 FL
3	1		*DRIVER SEAT BELT	*Check	1,260.00 FL	*- FL
4	1		*DRIVER SEAT BELT BUCKLE	*Check	420.00 FL	*- FL
5	1		*PASSENGER AIRBAG	Burst	3,600.00 FL	*3,600.00 FL
6	1		*PASSENGER SEAT BELT	*Check	1,260.00 FL	*- FL
7	1		*PASSENGER SEAT BELT BUCKLE	*Check	420.00 FL	*- FL
8	1		*AIRBAG CONTROL UNIT	Necessary	2,850.00 FL	*2,850.00 FL
9	1		*LH ROOF CURTAIN AIRBAG	Burst	2,175.00 FL	*2,175.00 FL
10	1		*RH ROOF CURTAIN AIRBAG	Burst	2,175.00 FL	*2,175.00 FL
11	1		*ROOF LINING	Torn	2,700.00 FL	*2,700.00 FL
12	1		*DASH BOARD	Torn	5,775.00 FL	*5,775.00 FL
13	1		*LH FRT FENDER	Buckled	870.00 FL	*870.00 FL
14	1		*LH FRT FENDER ARCH GARNISH	Buckled	630.00 FL	*630.00 FL
15	1		*LH FRT FENDER INNER SHIELD	Cracked	442.50 FL	*442.50 FL
16	10		*LH FRT FENDER INNER SHIELD CLIPS	Necessary	55.00 FL	*55.00 FL
17	1		*LH ROCKER PANEL GARNISH	Missing	510.00 FL	*510.00 FL
18	1		*FRT BUMPER	Repair	1,650.00 FL	*- FL
19	1		*FRT BUMPER SIDE RETAINER LH	Serviceable	105.00 FL	*- FL
20	1		*FRT BUMPER SIDE RETAINER RH	Serviceable	105.00 FL	*- FL
21	1		*LH FRT LOWER ARM	Bent	375.00 FL	*375.00 FL
22	1		*LH FRT KUNCKLE ARM	Bent	1,050.00 FL	*1,050.00 FL
23	1		*LH FRT KUNCKLE BEARING	Necessary	510.00 FL	*510.00 FL
24	1		*LH FRT SHOCK ABSORBER	Bent	360.00 FL	*360.00 FL
25	1		*LH FRT RIM R18	Dented	1,800.00 FL	*1,800.00 FL
26	1		*LH FRT TYRE 235/50ZR 18 DAVANTI DX640 (40%)	Punctured	420.00 FS	*168.00 FS
27	1		*LH REAR TYRE 235/50ZR 18 DAVANTI DX640 (50%)	Cut	420.00 FS	*210.00 FS
28	1		*FRT WINDSCREEN GLASS	*Check	1,200.00 FL	*- FL
29	1		*LH REAR FENDER ARCH GARNISH	*Check	600.00 FL	*- FL
30	1		*LH B PILLAR INNER TOP TRIM	*Check	360.00 FL	*- FL
31	1		*RH B PILLAR INNER TOP TRIM	*Check	360.00 FL	*- FL
32	1		*SEALANT	*Check	40.00 FS	*- FS
33	1		*INNER SEAL	*Check	30.00 FS	*- FS
34	1		*ERP BRACKET	*Check	26.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>37,553.50</b>	<b>29,255.50</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	3,661.75	2,887.75
<b>Total Parts (\$\$)</b>	<b>33,891.75</b>	<b>26,367.75</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	1	OD/TP Case (Insurer)	11.00	11.00
			<b>Sub Total (\$\$)</b>	<b>11.00</b>

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND INSTALL FRT WINDSCREEN GLASS *Check	New	120.00	0.00
2	TO KNOCK, STRAIGHTEN AND RENEW ACCIDENT AREA SUCH AS FRT BUMPER, LH FRT FENDER, LH FRT DOOR, LH SIDE ROCKER PANEL GARNISH, LH REAR FENDER AND ETC	New	720.00	540.00
3	TO PUTTY AND RESRPAY ACCIDENT AREA SUCH AS FRT BUMPER, LH FRT FENDER, LH FRT DOOR, LH SIDE ROCKER PANEL GARNISH, LH REAR FENDER AND ETC	New	1,300.00	750.00
4	TO RESET AND PROGRAM AIRBAG SYSTEM	New	250.00	200.00
5	TO REMOVE AND INSTALL DRIVER AIRBAG, PASSENGER AIRBAG, ALL SEAT BELT AND CONTROL UNIT	New	250.00	200.00
6	TO REMOVE AND INSTALL DASH BORAD	New	250.00	250.00
7	TO REMOVE AND INSTALL LH FRT UNDER CARRIAGE	New	240.00	240.00
8	TO CONDUCT WHEEL ALGINMENT	New	80.00	80.00
			<b>Gross Labour Cost (\$\$)</b>	<b>3,210.00</b>
				<b>2,260.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >