

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMQ 8890B

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT DOOR N/S	DENTED / BENT	945.20	945.20
1	SET FRONT DOOR FRAME BLACK STICKER N/S	NECESSARY	45.80	45.80
1	FRONT DOOR INNER LOWER RUBBER N/S	NECESSARY	96.50	96.50
1	REAR DOOR N/S	DENTED / WARPED	895.60	895.60
1	REAR DOOR FRT RUBBER N/S	NECESSARY	95.30	95.30
1	SET REAR DOOR FRAME BLACK STICKER N/S	NECESSARY	45.80	45.80
1	REAR HUP CAP N/S	CUT	204.80	204.80
1	REAR FENDER N/S	TO REPAIR SEE LABOUR	915.20	-
1	REAR BUMPER	DEEP CUT	895.20	895.20
1	SET REAR BUMPER CLIPS	NECESSARY	50.00	50.00
1	ROCKER PANEL N/S	TO REPAIR SEE LABOUR	695.00	-
1	ROCKER PANEL GARNISH N/S	DEFORMED / TORN	650.00	650.00
1	SET ROCKER PANEL GARNISH CLIPS N/S	NECESSARY	50.00	50.00
	LESS 20% DISCOUNT		-	-794.84
			5,584.40	3,179.36
	LABOUR			
	TO CHECK WIRING.		50.00	20.00
	TO DISMANTLE & REFIX REAR REVERSE SENSOR.		80.00	50.00
	TO DISMANTLE & REFIX REAR CUSHION UPHOLSTERY.		120.00	80.00
	TO DISMANTLE & REFIX N/S BOTH DOOR MECHANISM.		150.00	120.00
	TO RESET & DIAGNOSTIC SYSTEM.		120.00	100.00
	TO SPRAY RUST PROOFING.		80.00	60.00
	LABOUR FOR PANEL BEATING & REPLACED PARTS. INCLUSIVE OF THE REPAIR OF REAR FENDER N/S AND ROCKER PANEL N/S.		800.00	550.00
	TO PUTTY & SPRAY PAINTING.		1,380.00	1,100.00
			2,780.00	2,080.00
	GRAND TOTAL		8,364.40	5,259.36

Report Ref No. CS/TP22003170/Uvy3e2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		4,200.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/TP22003170/Uvy3e2

CHUA KANG SENG
Licensed Appraiser