

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI22003173/KTY3E2

**Date:** 24/05/2022

### REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00136542100  
Claimant Vehicle No: SLT1223U Insured Vehicle No: SGN5599A  
Date of Loss: 02/04/2022 Nature of Claim: TP Claim No: SNM22D202283/C02/CHNGPW

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLT1223U  
Make & Model: HYUNDAI TUCSON, 2.0 GLS (A) Engine No: G4NAHU474086  
Reg. Date: 03/10/2017 (Man. Year: 2017) Chassis No: KMHJ3813MJU568296  
Colour: Metallic Grey Odometer: 81808 km  
Engine Capacity: 1999 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 225/60 R17 Rear Tyre Size: 225/60 R17  
Front Left Side: Bridgestone 8 mm Rear Left Side: Bridgestone 8 mm  
Front Right Side: Bridgestone 8 mm Rear Right Side: Bridgestone 8 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	815.00	815.00	0.00	0.00
Miscellaneous Items	215.00	135.00	80.00	37.21
Labour	239.40	264.60	-25.20	-10.53
Paintwork Labour	426.17	498.21	-72.04	-16.90
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>1,695.57</b>	<b>1,712.81</b>	<b>-17.24</b>	<b>-1.02</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>118.69</b>	<b>119.90</b>	<b>-1.21</b>	<b>-1.02</b>
<b>Nett Amount (S\$)</b>	<b>1,814.26</b>	<b>1,832.71</b>	<b>-18.45</b>	<b>-1.02</b>

### INSPECTION

Date of Assignment: 06/04/2022 Present Location: Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)  
Date Inspected: 18/04/2022 Inspected At: Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)  
160 Sin Ming Drive #04-01, Sin Ming AutoCity  
Singapore 575722  
Estimated Period of Repair: 4.0 days

**Adjuster:** KENNETH KONG

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 May 2022)
Parts:	M1-SUV	HYUNDAI TUCSON 2.0 GLS (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLT1223U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Spare Parts		790.00 F	*790.00 F
<u>Supplementary #1</u>						
2	1		*REAR MANUFACT BADGE	Necessary	25.00 F	*25.00 F
F=Franchise part.						
Total Parts (S\$)					815.00	815.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	Extra	215.00	135.00
Sub Total (\$\$)			215.00	135.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	Total Paint Including Material	New	426.17	498.21
<u>Labour Items</u>				
2	Total of Labour	New	239.40	264.60
Gross Labour Cost (\$\$)			665.57	762.81

Report was unsubmitted during this print-out.

< END OF ESTIMATES >