



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGR 5129C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	LED FOG LAMP SET (SN)	NOT NECESSARY	396.30	-
1	COVER,FR BUMPER,L (SN)	CUT	525.80	525.80
10	PIECE,RR BUMPER (SN)	NECESSARY	43.00	43.00
1	RETAINER,FR BUMPER (SN)	NOT NECESSARY	106.70	-
1	RETAINER,FR BUMPER (SN)	NOT NECESSARY	106.70	-
1	FENDER SUB-ASSY,FR (SN)	DENTED	809.10	809.10
1	LINER,FR FENDER,LH (SN)	NOT NECESSARY	222.80	-
10	CLIP (SN)	NOT NECESSARY	29.00	-
1	WHEEL DISC (SN)	CUT	1,857.30	1,857.30
1	HEADLAMP ASSY,LH (SN)	NOT NECESSARY	1,364.40	-
1	SUNDRY (SN)	NECESSARY	100.00	50.00
			5,561.10	3,285.20
	<u>LABOUR</u>			
	CHECK WIRING AND CONDUCT WATER TEST.		122.40	122.40
	TO RESET ECU AND REPROGRAMME.		180.00	180.00
	TO CONDUCT FULL WHEEL ALIGNMENT.		180.00	180.00
	REPLACE RIM AND WHEEL BALANCING.		144.00	144.00
	REPLACE ACC DAMAGED PARTS AND STRAIGHTEN/REALIGN ACC AFFECTED AREAS.		2,160.00	1,440.00
	RESPRAY ACC AFFECTED AREAS.		1,770.00	1,180.00
			4,556.40	3,246.40
	GRAND TOTAL		10,117.50	6,531.60
	RECOMMENDED COST OF REPAIRS			6,531.60

Report Ref No. CS/AIS22003176/Evy3n2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.