

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22003184/RTY3N2**Date:** 13/05/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00138722103	
Claimant Vehicle No :	SMS1392H	Insured Vehicle No :	GBH9935C	
Date of Loss:	05/04/2022	Nature of Claim:	TP	Claim No: SNM22D202330/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMS1392H		Engine No:	CZCC05605
Make & Model:	VOLKSWAGEN GOLF, 1.4 (A)		Chassis No:	WVWZZZAUZKW189998
Reg. Date:	12/02/2020 (Man. Year: 2019)		Odometer:	73604 km
Colour:	White			
Engine Capacity:	1395 cc			
Market Value/New Car Price:	N/A			
Sum Insured (\$\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45R17	Rear Tyre Size:	225/45R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,766.49	1,124.14	642.35	36.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,720.00	1,710.00	1,010.00	37.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	4,486.49	2,834.14	1,652.35	36.83
+ GST 7.00/7.00% (\$\$)	314.05	198.39	115.66	36.83
Nett Amount (\$\$)	4,800.54	3,032.53	1,768.01	36.83

INSPECTION

Date of Assignment:	08/04/2022		
Date Inspected:	08/04/2022	Inspected At:	Volkswagen Centre Singapore (HQ) 247 Alexandra Road Singapore 159934
Estimated Period of Repair:	2.0 days		

Adjuster: MOHD RASUL**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 May 2022)
Parts:	144	VOLKSWAGEN GOLF 1.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMS1392H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR VIEW MIRROR HOUSING	Distorted	631.57 FS	*631.57 FS
2	1		*MIRROR CAP PRIMED	Repair	181.52 FS	*- FS
3	1		*MIRROR GLASS	Not Necessary	205.00 FS	*- FS
4	1		*SIDE WINDOW QUARTER GLASS C/W RUBBER SEAL	Scratched	165.17 FS	*165.17 FS
5	1		*WINDOW SLOT SEAL BLACK	Scratched	94.63 FS	*94.63 FS
6	1		*GLASS CHANNEL BLACK	Not Necessary	255.83 FS	*- FS
7	1		*1K WINDOW ADHESIVE	Necessary	51.35 FS	*51.35 FS
8	1		*ALL PURPOSE CLEANER	Necessary	102.65 FS	*102.65 FS
9	1		*ACTIVATOR	Necessary	26.23 FS	*26.23 FS
10	2		*APPLICATOR	Necessary	22.32 FS	*22.32 FS
11	1		*PRIMER	Necessary	30.22 FS	*30.22 FS
					Total Parts (S\$)	1,766.49 1,124.14

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	B&P CHECK SHORT CIRCUIT/HARNESS REPAIR	New	280.00	0.00
2	B&P DIAGNOSIS AND PROGRAMMING	New	480.00	480.00
3	LABOUR	New	840.00	530.00
4	SPRAY PAINTING	New	280.00	280.00
5	R&R SIDE WINDOW	New	840.00	420.00
Gross Labour Cost (\$)			2,720.00	1,710.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >