

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22003186/VQY3E2

Date: 21/06/2022

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00115072100
Claimant Vehicle No : XD9966Z **Insured Vehicle No :** GBH8957X
Date of Loss: 02/04/2022 Nature of Claim: TP Claim No: SNM22D202322/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **XD9966Z**
Make & Model: MITSUBISHI FUSO, 11.1 D FP418D (M) Engine No: OM457LA457972C0329775
Reg. Date: 18/08/2016 (Man. Year: 2016) Chassis No: FV51SJA20054
Colour: Multi-colour Odometer: 0 km
Engine Capacity: 11967 cc
Market Value/New Car Price: N/A
Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 295/80 R22.5 Rear Tyre Size: 295/80 R22.5
Front Left Side: Giti 5 mm Rear Left Side: Giti 5 mm
Front Right Side: Giti 5 mm Rear Right Side: Giti 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,206.43	8,627.57	8,578.86	49.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,510.00	1,270.00	2,240.00	63.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	20,716.43	9,897.57	10,818.86	52.22
Approved Total (Overridden) (\$\$)		7,900.00		
Nett Amount (\$\$)	20,716.43	7,900.00	12,816.43	61.87

INSPECTION

Date of Assignment: 06/04/2022
Date Inspected: 06/04/2022 Inspected At: Carsmith Private Limited (HQ)
13 KAKI BUKIT ROAD 4 #01-20 BARTLEY BIZ CENTRE
Singapore 417807
Estimated Period of Repair: 5.0 days

Adjuster: Thevan Thomas Karthikesavan

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 17 Jun 2022)	
Parts:	N/A	mitsubishi fuso 11.1 D FP418D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for XD9966Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Dented	2,386.40 FL	*2,200.00 FL
2	1		*FRONT BUMPER CENTRE GARNISH (2PCS)	Dented (1Pc Only)	594.60 FL	*297.30 FL
3	1		*FRONT BUMPER SIDE LAMP (2PCS)	Cracked (1Pc Only)	432.80 FL	*216.40 FL
4	1		*FRONT BUMPER SIDE LAMP GARNISH (2PCS)	Cut (1Pc Only)	392.80 FL	*196.40 FL
5	1		*FRONT BUMPER BRACKET (2PCS)	Necessary (1Pc Only)	515.20 FL	*257.60 FL
6	1		*FRONT BUMPER INNER BEAM	Dented	976.20 FL	*850.00 FL
7	1		*HEADLAMP (2PCS)	Cracked (1Pc Only)	1,397.40 FL	*698.70 FL
8	1		*HEADLAMP GARNISH (2PCS)	Cut (1Pc Only)	595.20 FL	*210.00 FL
9	1		*HEADLAMP TOP BRACKET (2PCS)	Necessary (1Pc Only)	392.80 FL	*150.00 FL
10	1		*FRONT CENTRE PANEL	Serviceable	4,286.10 FL	*- FL
11	1		*FRONT CENTRE PANEL LOGO	Necessary	78.40 FL	*78.40 FL
12	1		*FRONT CENTRE PANEL LOCK	Serviceable	216.50 FL	*- FL
13	2		*FRONT CORNELL PANEL	Serviceable	857.20 FL	*- FL
14	2		*FRONT CORNER PANEL LAMP	Serviceable	397.20 FL	*- FL
15	2		*FRONT CORNER PANEL SIDE BRACKET	Serviceable	236.40 FL	*- FL
16	1		*FRONT LH DOOR	Dented	3,976.40 FL	*3,652.00 FL
17	1		*FRONT LH DOOR SIGNAL	Cracked	250.00 FL	*200.00 FL
18	1		*FRONT NUMBER PLATE	Cracked	60.00 FS	*40.00 FS
19	1		*SET FRONT GRILLE CLIPS	Necessary	80.00 FS	*40.00 FS
20	1		*FRONT BUMPER CENTRE TOP GARNISH	Cut	596.10 FL	*298.00 FL
21	1		*FRONT BUMPER SIGNAL LAMP (2PCS)	Cracked (1Pc Only)	385.00 FL	*192.50 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	19,102.70	9,577.30
- List Item Discount on L Items 10.00/10.00% (S\$)	1,896.27	949.73
Total Parts (S\$)	17,206.43	8,627.57

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE / RENEW THE ACCIDENT DAMAGED PORTION. TO PANEL BEAT, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIR / REPLACEMENT PARTS	New	1,500.00	600.00
2	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS, RECONNECT AND CHECK FUNCTIONS	New	80.00	30.00
3	TO REMOVE AND REFIT INTERIOR DASHBOARD TO FACILITATE THE REPAIR	New	480.00	0.00
4	TO REMOVE AND REFIT FRONT WINDSCREEN TO FACILITATE THE REPAIR	New	250.00	0.00
5	TO APPLY UNDERCOATING ON THE ACCIDENT REPAIR AND REPLACED PANEL FOR RUST PROTECTION	New	200.00	40.00
6	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY FRONT BUMPER, CENTRE PANEL, SIDE PANEL O/S FRONT DOOR AND OTHER AFFECTED AREA / PANEL	New	1,000.00	600.00
Gross Labour Cost (\$\$)			3,510.00	1,270.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >