

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 6507A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR TRUNK OUTER GARNISH	TO REPAIR SEE LABOUR	1,054.71	-
1	REAR TRUNK LID LOGO (PRIUS)	NECESSARY	62.14	62.14
1	REAR TRUNK LID LOGO (HYBRID)	NECESSARY	62.14	62.14
1	REAR TRUNK LID LOGO (TOYOTA STAR)	NECESSARY	81.43	81.43
1	REAR BUMPER- G4A	DENTED	551.89	551.89
1	REAR BUMPER RE-INFORCEMENT	SERVICEABLE	378.32	-
1	REAR BUMPER LOWER COVER-BLACK	DENTED	654.96	654.96
10	REAR BUMPER CLIPS @\$2.20	NECESSARY	22.00	22.00
	LESS 25% DISCOUNT		-716.90	-358.64
			2,150.69	1,075.92
	NETT ITEMS			
1	REVERSE SENSOR (N)	CUT	135.70	135.70
1	REAR TRUNK COMFORTDELGRO (N)	NECESSARY	30.00	30.00
1	REAR TRUNK 65521111 (N)	NECESSARY	30.00	30.00
1	REAR TRUNK APPS (N)	NECESSARY	40.00	40.00
	LESS 10% DISCOUNT		-23.57	-23.57
			212.13	212.13
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR TRUNK OUTER GARNISH.		800.00	700.00
	SPRAY PAINTING CHARGE.		600.00	500.00
	WIRING CHARGE.		40.00	20.00
	TUFF KOTE.		40.00	20.00
	REMOVE/REFIX REVERSE SENSOR,		120.00	30.00
			1,600.00	1,270.00
	GRAND TOTAL		3,962.82	2,558.05

Report Ref No. NS/INC22003189/Vqcn2





Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		2,050.00
(TO ITS PRE-ACCIDENT CONDITION)		
(CONFIRMED)		

Report Ref No. NS/INC22003189/Vqcn2



THEVAN THOMAS KARTHIKESAVAN



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser