10/7/22, 5:00 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22003194/UNY3M4

07/10/2022 Date:

REFERENCE

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No:

DMPCSNW00039572200

Claimant Vehicle

GBK8285K

Insured

No:

Vehicle No:

SML3379X

Date of Loss:

30/03/2022

Nature of Claim: TP

Claim

SNM22D202222/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

GBK8285K Reg No:

Make & Model: NISSAN NV350, 2.5 PANEL VAN 5MT 5DR (M) Engine No:

YD25081014B

Reg. Date: Colour:

10/12/2020 (Man. Year: 2020)

Chassis No: Odometer:

JN1MC2E26Z0032434 38827 km

Yes

Engine Capacity:

Grey 2488 cc

Market Value/New Car Price:

N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable):

Handbrake (Serviceable): **Engine Modification:** Pre-accident Condition: Yes Nο

CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 195 R15 Front Left Side: Rear Left Side: Dunlop 6 mm Dunlop 6 mm Front Right Side: Rear Right Side: Dunlop 6 mm Dunlop 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|------------------------|------------|------------|------------|--------|
| Parts | 1,318.08 | 0.00 | 1,318.08 | 100.00 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 1,833.00 | 873.00 | 960.00 | 52.37 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Gross Total (S\$) | 3,151.08 | 873.00 | 2,278.08 | 72.30 |
| + GST 7.00/7.00% (S\$) | 220.58 | 61.11 | 159.47 | 72.30 |
| Nett Amount (S\$) | 3,371.66 | 934.11 | 2,437.55 | 72.30 |

INSPECTION

Date of Assignment: 06/04/2022

Autolution Industrial Pte Ltd (Ubi)

Date Inspected: 20/04/2022 19 Ubi Road 4 Singapore 408623

Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA Manager: **HUEY YON**

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Inspected At:

THE VEHICLE HAS NOT SEND IN FOR REPAIRS.

(REPAIR COST NOT CONCLUDE)

10/7/22, 5:00 PM Adjuster Report

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 07 Oct 2022)

Parts: N/A NISSAN NV350 2.5 PANEL VAN 5MT 5DR (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GBK8285K)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

| Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|--|------------------|------------------|--|---|--|
| 1 | | *FRT LH HEADLAMP | Serviceable | 429.10 FN | *- FN |
| 1 | | *FRT LH DOOR | Repair | 1,156.00 FN | *- FN |
| 1 | | *SUNDRIES | Not Necessary | 50.00 FS | *- FS |
| nchise | part. S=SpcNett. | N=NettItemDisc. | | | |
| | | | Sub Total (S\$) | 1,635.10 | 0.00 |
| - Nett Item Discount on N Items 20.00/20.00% (S\$) | | 317.02 | 0.00 | | |
| | | | Total Parts (S\$) | 1,318.08 | 0.00 |
| | 1 1 1 | 1 | 1 *FRT LH HEADLAMP 1 *FRT LH DOOR 1 *SUNDRIES anchise part. S=SpcNett. N=NettItemDisc. | 1 *FRT LH HEADLAMP Serviceable 1 *FRT LH DOOR Repair 1 *SUNDRIES Not Necessary Inchise part. S=SpcNett. N=NettItemDisc. Sub Total (S\$) - Nett Item Discount on N Items 20.00/20.00% (S\$) | 1 *FRT LH HEADLAMP Serviceable 429.10 FN 1 *FRT LH DOOR Repair 1,156.00 FN 1 *SUNDRIES Not Necessary 50.00 FS Inchise part. S=SpcNett. N=NettItemDisc. Sub Total (S\$) 1,635.10 - Nett Item Discount on N Items 20.00/20.00% (S\$) 317.02 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|------------|--|-------------------|------------|--------|
| <u>Lab</u> | our Items | | | |
| 1 | LABOR CHARGES TO REPAIR FRT BUMPER & FRT LH SIDE ST RENEW FRT LH DOOR | EP , New | 840.00 | 560.00 |
| 2 | CHARGES TO SPRAY PAINTING FRT LH DOOR | New | 750.00 | 250.00 |
| 3 | APPLY SEALANT TO FRT LH DOOR | New | 100.00 | 0.00 |
| 4 | SUPPLY FRT LH DOOR STICKER | New | 15.00 | 15.00 |
| 5 | REMOVE AND TRANSFER FRT LH DOOR MECHANISM | New | 80.00 | 0.00 |
| 6 | CHECK FRT LH HEADLAMP WIRING | New | 48.00 | 48.00 |
| | Gross L | abour Cost (S\$) | 1,833.00 | 873.00 |
| | Report was unsubmitted durin | g this print-out. | | |

< END OF ESTIMATES >