

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG22003195/UQY3E2

Date: 18/05/2022

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29102895QMY
Claimant Vehicle No :	SMT376G	Insured Vehicle No :	SLA968K
Date of Loss:	05/04/2022	Nature of Claim:	TP
		Claim No:	640935

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMT376G	Engine No:	67391002094945
Make & Model:	SSANGYONG TIVOLI, 1.6 G 6AT ABS 2WD (A)	Chassis No:	KPT30A1USLP318114
Reg. Date:	25/03/2020 (Man. Year: 2020)	Odometer:	26299 km
Colour:	Orange		
Engine Capacity:	1597 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/65 R16	Rear Tyre Size:	205/65 R16
Front Left Side:	Nexen 7 mm	Rear Left Side:	Nexen 7 mm
Front Right Side:	Nexen 7 mm	Rear Right Side:	Nexen 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,714.00	3,492.84	11,221.16	76.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,920.00	1,770.00	2,150.00	54.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,634.00	5,262.84	13,371.16	71.76
Approved Total (Overridden) (S\$)		4,200.00		
(S\$)	18,634.00	4,200.00	14,434.00	77.46
+ GST 7.00/7.00% (S\$)	1,304.38	294.00	1,010.38	77.46
Nett Amount (S\$)	19,938.38	4,494.00	15,444.38	77.46

INSPECTION

Date of Assignment:	19/04/2022		
Date Inspected:	06/04/2022	Inspected At:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883
Estimated Period of Repair:	4.0 days		

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 21 Apr 2022)

Parts: M1-SUV SSANGYONG TIVOLI 1.6 G 6AT ABS 2WD (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMT376G)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER TOP	Distorted	1,455.00 F	*945.00 FL
2	1		*REAR BUMPER LOWER	Distorted	1,050.00 F	*620.00 FL
3	1		*REAR BUMPER CENTRE LAMP	Cracked	450.00 F	*193.50 FL
4	1		*REAR BUMPER REFLECTOR N/S	Broken	388.00 F	*99.18 FL
5	1		*REAR BUMPER SIDE RETAINERS	N/S Bent	160.00 F	*62.00 FL
6	1		*REAR BUMPER REINFORCEMENT	Cracked	490.00 F	*490.00 FL
7	2		*REAR BUMPER REINFORCEMENT BRACKETS	Cracked	90.00 F	*90.00 FL
8	1		*REAR BUMPER BRACKET N/S	Bent	205.00 F	*161.00 FL
9	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
10	1		*REAR END PANEL	Dented	1,188.00 F	*599.25 FL
11	1		*REAR END PANEL TOP GARNISH	Not Necessary	302.00 F	*- FL
12	1		*REAR FENDER N/S	Repair	1,900.00 F	*- FL
13	1		*REAR FENDER OUTER PROTECTOR N/S	Torn	450.00 F	*288.00 FL
14	1		*TAILGATE	Repair	1,820.00 F	*- FL
15	1		*TAILGATE SSANG YONG EMBLEM	Necessary	106.00 F	*98.00 FL
16	1		*TAILGATE TIVOLI EMBLEM	Necessary	105.00 F	*85.00 FL
17	1		*TAILLAMP N/S	Serviceable	845.00 F	*- FL
18	1		*REAR EXHAUST CLEAN TANK	Repair	2,850.00 F	*- FL
19	1		*REAR BUMPER LICENCE PLATE	Damaged	50.00 FS	*40.00 FS
20	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
21	1		*REAR WINDSCREEN SEALANT	Not Necessary	50.00 FS	*- FS
22	1		*SET REAR BUMPER REVERSE SENSOR	Not fitted	280.00 FS	*- FS
23	1		*SET REAR REVERSE CAMERA	Not Necessary	380.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	14,714.00	3,870.93
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	378.09
Total Parts (\$\$)	14,714.00	3,492.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	30.00
2	TO DISMANTLE & REFIX REVERSE CAMERA	New	100.00	50.00
3	TO DISMANTLE & REFIX REAR WINDSCREEN	New	120.00	0.00
4	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	120.00	80.00
5	TO DISMANTLE & REFIX REAR EXHAUST CLEAN TANK	New	200.00	100.00
6	TO RESET & DIAGNOSTIC SYSTEM	New	250.00	80.00
7	TO SPRAY RUST PROOFING	New	80.00	30.00
8	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,500.00	600.00
9	TO PUTTY & SPRAY PAINTING	New	1,500.00	800.00
Gross Labour Cost (\$)			3,920.00	1,770.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >