

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22003197/ANY3E2

Date: 22/07/2022

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00053892200

Claimant Vehicle No : SLA5802Y

Insured Vehicle No : SMK3125S

Date of Loss: 05/04/2022

Nature of Claim: TP

Claim No: SNM22D202347/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLA5802Y**

Make & Model: BMW 116D, 1.5 D 5DR HATCH DSC LED (A)

Engine No: 30879506B37D15A

Reg. Date: 07/03/2016 (Man. Year: 2016)

Chassis No: WBA1V720X0V724158

Colour: Blue

Odometer: 103030 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,810.98	5,820.15	6,990.83	54.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,340.00	1,300.00	2,040.00	61.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,150.98	7,120.15	9,030.83	55.92
Approved Total (Overridden) (S\$)		5,700.00		
Nett Amount (S\$)	16,150.98	5,700.00	10,450.98	64.71

INSPECTION

Date of Assignment: 07/04/2022

Date Inspected: 07/04/2022 Inspected At:

HD Perfect Autowork Pte Ltd (HQ)

8 Kaki Bukit Ave 4, #08-09 Premier @ Kaki Bukit
Singapore 415875

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 22 Jul 2022)

Parts: 144 BMW 116D 1.5 D 5DR HATCH DSC LED (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLA5802Y)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,074.65 FL	*1,074.65 FL
2	1		*FRONT BUMPER FOGLAMP LH	Cracked	298.60 FL	*298.60 FL
3	1		*FRONT BUMPER FOGLAMP COVER LH	Deformed	118.45 FL	*118.45 FL
4	1		*FRONT BUMPER LOWER BRACKET	Not Necessary	174.40 FL	*- FL
5	1		*FRONT BUMPER LOWER BEAM	Not Necessary	128.60 FL	*- FL
6	1		*FRONT BUMPER TOP GARNISH RUBBER	Not Necessary	35.45 FL	*- FL
7	1		*FRONT BUMPER SPONGE	Cracked	194.65 FL	*194.65 FL
8	2		*FRONT BUMPER SIDE BRACKET	Not Necessary	93.60 FL	*- FL
9	1		*FRONT BUMPER REINFORCEMENT	Dented	894.35 FL	*894.35 FL
10	1		*FRONT AIR GUARD	Not Necessary	265.55 FL	*- FL
11	1		*FRONT BUMPER LOGO	Necessary	76.85 FL	*76.85 FL
12	1		*FRONT GRILLE C/W CHROME LH	Cracked	490.35 FL	*490.35 FL
13	1		*FRONT LOWER GRILLE	Cracked	143.90 FL	*143.90 FL
14	1		*FRONT LOWER GRILLE CENTER MOULDING	Not Necessary	117.65 FL	*- FL
15	1		*HEADLAMP (HID)	N/s Cracked	4,873.10 FL	*2,436.55 FL
16	1		*BONNET	Not Necessary	1,496.75 FL	*- FL
17	2		*BONNET HINGE	Not Necessary	169.40 FL	*- FL
18	2		*BONNET LOCK	Not Necessary	396.50 FL	*- FL
19	1		*BONNET INSULATOR	Not Necessary	183.35 FL	*- FL
20	1		*FRONT SUPPORT PANEL	Not Necessary	790.85 FL	*- FL
21	2		*FRONT AIR GUARD SIDE GARNISH	Not Necessary	151.40 FL	*- FL
22	1		*FRONT FENDER LH	Buckled	560.00 FL	*560.00 FL
23	1		*FRONT FENDER INNER COWLING LH	Not Necessary	210.00 FL	*- FL
24	1		*HORN	Cracked	210.00 FL	*89.60 FL
25	1		*FRONT NUMBER PLATE	Dented	50.00 FS	*50.00 FS
26	1		*SET FRONT BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
27	1		*SET FRONT BUMPER BOTTOM SIDE GARNISH CLIP	Not Necessary	30.00 FS	*- FS
28	1		*BONNET SEALANT	Not Necessary	80.00 FS	*- FS
29	1		*SET BONNET INSULATOR CLIP	Not Necessary	50.00 FS	*- FS
30	1		*SET FRONT AIR GUARD SIDE GARNISH CLIP	Not Necessary	30.00 FS	*- FS
31	1		*SET FRONT AIR GUARD TOP GARNISH CLIP	Not Necessary	30.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	13,468.40	6,457.95
- List Item Discount on L Items 5.00/10.00% (\$\$)	657.42	637.80
Total Parts (\$\$)	12,810.98	5,820.15

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING,REMOVING AND REPLACING PARTS	New	1,200.00	600.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,200.00	500.00
3	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	New	120.00	0.00
4	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	New	80.00	0.00
5	REFOCUS HEADLAMP BEAM	New	60.00	0.00
6	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC	New	680.00	200.00
Gross Labour Cost (\$\$)			3,340.00	1,300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >