

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. EB 111T

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER (SN)	DEFORMED	990.00	990.00
2	FRONT BUMPER SIDE GUIDE - LH / RH (SN)	* CHECK	77.00	-
2	FRONT BUMPER SIDE GUIDE - LH / RH LOWER (SN)	* CHECK	62.00	-
2	FRONT BUMPER SIDE AIR DUCT - LH / RH (SN)	* CHECK	121.00	-
1	FRONT BUMPER LOGO "BMW" (SN)	NECESSARY	83.00	83.00
2	RADIATOR GRILLE - LH / RH (SN)	SCRATCHED	616.00	616.00
2	FRONT FOG LAMP COVER - LH / RH (SN)	* CHECK	154.00	-
2	FRONT BUMPER LOWER SPOILER - LH / RH (SN)	* CHECK	2,332.00	-
1	FRONT BUMPER LOWER GRILLE (SN)	* CHECK	88.00	-
1	SUNDRIES (SN)	* CHECK	200.00	-
			4,723.00	1,689.00
	<u>LABOUR</u>			
	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.		150.00	150.00
	TO DISMANTLE AND RENEW FRONT BUMPER. RE- ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.		400.00	200.00
	TO RESPRAY FRONT BUMPER.		400.00	200.00
	TO CARRY OUT DIAGNOSTIC CHECK.		150.00	150.00
			1,100.00	700.00
	GRAND TOTAL		5,823.00	2,389.00
	RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE)			2,389.00

(EXCLUDE CHECK ITEMS S\$3,034.00 NETT)

Report Ref No. CS6/AIS22003199/Gvy3e2

**XING GUO QIANG** 

M.MATAI, AMSAE-A **Automotive Assessor** 

**ADRIAN LING WAI PING** 

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

**Licensed Appraiser** 

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.