



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN: KOH JANICE			Ref: CS/ASM22003202/Kvy3e2 Date: 10/05/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SH 9251R	Veh. Inspected	SKU 8860R
	Policy No.	VFX/P2419138	Coverage (\$)	0.00
	Claim No.	S2M03XWE	Excess (\$)	0.00
	Assign From	KOH JANICE	Assign Date	07/04/2022
2. Vehicle Particulars & Condition				
	Make & Model	HYUNDAI I30 (A)	c.c	1591
	Engine No.	HIDDEN	Year of Reg.	2009
	Chassis No.	KMHDC51DR9U187939	Colour	METALLIC GREY
	Odometer	163088 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/45 R17	LING LONG	8 mm
	L/H Front Tyre	215/45 R17	LING LONG	8 mm
	R/H Rear Tyre	215/45 R17	MICHELIN	3 mm
	L/H Rear Tyre	215/45 R17	MICHELIN	3 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	05/04/2022	Inspection Date	11/04/2022
	Survey held at	KIEN CHEONG MOTOR WORKS BLK 9 SIN MING IND EST SECTOR C #01-26 SINGAPORE 575644		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	