

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22003203/BPA3Q2**Date:** 06/07/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7990000127
Claimant Vehicle No :	SGW5245Z	Insured Vehicle No :	SND6530K
Date of Loss:	31/03/2022	Nature of Claim:	TP
		Claim No:	8899521450SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGW5245Z	Engine No:	3ZZ4676703
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Chassis No:	MR053ZEC107151252
Reg. Date:	23/07/2007 (Man. Year: 2007)	Odometer:	197102 km
Colour:	Silver		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/70 R14	Rear Tyre Size:	185/70 R14
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,531.40	4,114.82	6,416.58	60.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,230.00	2,350.00	2,880.00	55.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,761.40	6,464.82	9,296.58	58.98
Approved Total (Overridden) (S\$)		5,050.00		
(S\$)	15,761.40	5,050.00	10,711.40	67.96
+ GST 7.00/7.00% (S\$)	1,103.30	353.50	749.80	67.96
Nett Amount (S\$)	16,864.70	5,403.50	11,461.20	67.96
+ Loss of Use (11.0 x S\$60.00/day) (S\$)		660.00		
(S\$)		6,063.50		
Liabe Amount (80.00%) (S\$)		4,850.80		
+ Doc/Search Fee (S\$)		31.00		
Nett Liability (S\$)		4,881.80		
Global Sum Settlement (S\$)		4,880.00		

INSPECTION

Date of Assignment:	07/04/2022	Team Autopro Pte Ltd (sin Ming) (HQ)
Date Inspected:	07/04/2022 Inspected At:	160 SIN MING DRIVE, #01-14 SIN MING AUTOCITY
Estimated Period of Repair:	9.0 days	Singapore 575722

Adjuster: Lim Teow Guan**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR RH	Not Damaged	927.00 FL	*- FL
2	1		*FRONT DOOR BLACK TAPE	Not Damaged	85.00 FL	*- FL
3	1		*FRONT DOOR PROTECTOR RH	Not Damaged	358.00 FL	*- FL
4	1		*REAR DOOR RH	Dented	915.70 FL	*915.70 FL
5	1		*REAR DOOR BLACK TAPE	Necessary	85.00 FL	*85.00 FL
6	1		*REAR DOOR PROTECTOR RH	Necessary	358.00 FL	*109.50 FL
7	1		*REAR DOOR OUTER HANDLE	Cut	350.00 FL	*350.00 FL
8	1		*REAR DOOR WEATHERSTRIP	Torn	215.00 FL	*180.00 FL
9	1		*REAR DOOR INNER LOCK	Jammed	415.00 FL	*280.00 FL
10	1		*REAR DOOR INNER LOCK STRIKER	Not Damaged	48.00 FL	*- FL
11	1		*REAR DOOR INNER TRIMBOARD	Broken	542.00 FL	*355.80 FL
12	1		*REAR DOOR GLASS REGULATOR	Bent	356.00 FL	*253.20 FL
13	1		*REAR DOOR GLASS REGULATOR MOTOR	Not Damaged	750.00 FL	*- FL
14	1		*REAR DOOR GLASS CHANNEL BRACKET	Bent	185.00 FL	*185.00 FL
15	2		*REAR DOOR HINGE	Not Damaged	230.00 FL	*- FL
16	1		*ROCKER PANEL RH	Dented	789.00 FL	*490.00 FL
17	1		*REAR FENDER RH	Dented	845.80 FL	*845.80 FL
18	1		*REAR FENDER INNER COWLING RH	Not Damaged	87.00 FL	*- FL
19	1		*REAR WINDSCREEN MOULDING	Necessary	241.60 FL	*105.10 FL
20	1		*REAR BUMPER	Cracked	782.40 FL	*398.00 FL
21	1		*REAR SHOCK ABSORBER RH	Not Damaged	499.30 FL	*- FL
22	1		*REAR AXLE	Not Damaged	1,088.00 FL	*- FL
23	1		*REAR WHEEL BEARING RH	Jammed	452.00 FL	*248.00 FL
24	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
25	1		*FRONT DOOR SEALANT	Not Necessary	100.00 FS	*- FS
26	1		*FRONT DOOR PROTECTOR CLIPS	Not Necessary	50.00 FS	*- FS
27	1		*REAR DOOR SEALANT	Necessary	100.00 FS	*30.00 FS
28	1		*REAR DOOR INNER TRIMBOARD CLIPS	Necessary	50.00 FS	*30.00 FS
29	1		*REAR DOOR PROTECTOR CLIPS	Not Necessary	50.00 FS	*- FS
30	1		*ROCKER PANEL SEALANT	Not Necessary	100.00 FS	*- FS
31	1		*REAR FENDER SEALANT	Not Necessary	100.00 FS	*- FS
32	1		*REAR FENDER INNER COWLING CLIPS	Not Necessary	50.00 FS	*- FS
33	1		*REAR WINDSCREEN SEALANT	Necessary	100.00 FS	*40.00 FS
34	1		*REAR WINDSCREEN INNER SEAL	Not Necessary	80.00 FS	*- FS
35	1		*REAR WINDSCREEN PRIMER & CLEANER	Not Necessary	60.00 FS	*- FS
36	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
37	2		*REAR BUMPER SIDE RETAINER	Necessary	147.80 FS	*134.00 FS
38	1		*REAR ALLOY RIM RH	Cut	980.00 FS	*250.00 FS
39	1		*REAR TYRE RH	Not Damaged	480.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	13,182.60	5,315.10
- List Item Discount on L Items 25.00/25.00% (S\$)	2,651.20	1,200.28
Total Parts (S\$)	10,531.40	4,114.82

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	R&R FRONT DOOR COMPONENT	New	150.00	0.00
2	R&R REAR DOOR COMPONENT	New	150.00	80.00
3	R&R REAR REVERSE SENSOR	New	150.00	60.00
4	R&R REAR UNDER CARRIAGE	New	300.00	120.00
5	R&R REAR TYRE AND BALANCING	New	100.00	30.00
6	WHEEL ALIGNMENT	New	180.00	60.00
7	CHECK WIRING	New	100.00	0.00
8	UPHOLSTERY	New	300.00	0.00
9	PANEL BEATING	New	1,800.00	1,200.00
10	RUST PROOFING	New	200.00	0.00
11	SPRAY PAINTING	New	1,800.00	800.00
Gross Labour Cost (S\$)			5,230.00	2,350.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >