

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/GRB22003206/TYA3Q2**Date:** 13/06/2023**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447\_01

**Claimant Vehicle No :** YP1478T **Insured Vehicle No :** SMJ4117P

Date of Loss: 29/03/2022 Nature of Claim: TP Claim No: MFL2022D0001553

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **YP1478T**  
 Make & Model: MITSUBISHI FEB21CR4SDEB, 3.0 D (M) Engine No: 4P10B86506  
 Reg. Date: 15/02/2016 (Man. Year: 2015) Chassis No: FEB21CA10048  
 Colour: White Odometer: 230140 km  
 Engine Capacity: 2998 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 195 R15 Rear Tyre Size: 195 R15 (D)  
 Front Left Side: Austone 6 mm Rear Left Side: Austone 6/6 mm  
 Front Right Side: Austone 6 mm Rear Right Side: Austone 6/6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,045.03	675.88	369.15	35.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	670.00	200.00	470.00	70.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>1,715.03</b>	<b>875.88</b>	<b>839.15</b>	<b>48.93</b>
<b>Global Sum Settlement (S\$)</b>		<b>0.00</b>		

**INSPECTION**

Date of Assignment: 07/04/2022  
 Date Inspected: 07/04/2022 Inspected At: Venda Engineering & Trading Pte Ltd (Pioneer)  
 Estimated Period of Repair: 1.0 days No. 8 Tuas Avenue 18, Level 3  
 Singapore 638892

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** Ezlyna

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 13 Jun 2023)	
Parts:	N/A	MITSUBISHI FEB21CR4SDEB 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YP1478T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT SIGNAL LAMP ,RH	Cracked	317.01 FL	*317.01 FL
2	1		*FRONT HEADLAMP RH	Not Necessary	492.21 FL	*- FL
3	1		*FRONT HEADLAMP SIDE COVER ,RH	Cracked	276.19 FL	*276.19 FL
4	1		*FRONT BUMPER SIDE COVER RH	Cut	307.97 FL	*307.97 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	1,393.38	901.17
- List Item Discount on L Items 25.00/25.00% (S\$)	348.35	225.29
Total Parts (S\$)	1,045.03	675.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REMOVE & RENEW PARTS ,PANEL BEAT & RE-ALIGN FRONT RH PORTION	New	450.00	200.00
2	SPRAY PAINT FRONT RH BUMPER SIDE COVER & FRONT RH DOOR	New	220.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>670.00</b>	<b>200.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >