

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG22003209/AVCE2

**Date:** 22/07/2022

### REFERENCE

Insured/Claimant: EUGENE TAN KEAT MENG (EUGENE CHEN JIEMING)

Policy No: 1900251582-01

Date of Loss: 30/03/2022

Nature of Claim:

OD

Claim No: 0763691452SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLC930H

Make & Model: AUDI Q3, 1.4 TFSI (A)

Engine No: CZD886134

Reg. Date: 29/11/2019 (Man. Year: 2019)

Chassis No: WAUZZZF33L1010150

Colour: White

Odometer: 22071 km

Engine Capacity: 1395 cc

Market Value/New Car Price: S\$150,000.00

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 235/55 R18

Rear Tyre Size: 235/55 R18

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,691.00	6,949.12	5,741.88	45.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,192.00	4,162.00	4,030.00	49.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>20,883.00</b>	<b>11,111.12</b>	<b>9,771.88</b>	<b>46.79</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,461.81</b>	<b>777.78</b>	<b>684.03</b>	<b>46.79</b>
<b>Nett Amount (S\$)</b>	<b>22,344.81</b>	<b>11,888.90</b>	<b>10,455.91</b>	<b>46.79</b>

### INSPECTION

Date of Assignment: 07/04/2022

Date Inspected: 06/04/2022

Inspected At:

Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1

Singapore 408699

Estimated Period of Repair: 4.0 days

**Adjuster:** ADRIAN LING

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,738.00 FS	*1,390.40 FS
2	1		*REAR BUMPER FIXING PART REAR	Not Necessary	220.00 FS	*- FS
3	1		*REAR BUMPER SPOILER	Deformed	510.00 FS	*408.00 FS
4	1		*REAR TOW EYE COVER	Not Necessary	48.00 FS	*- FS
5	1		*REAR CROSS REINFORCEMENT BRACKET CENTRE	Not Necessary	108.00 FS	*- FS
6	1		*REAR BUMPER BRACKET	Not Necessary	53.00 FS	*- FS
7	2		*REAR LIGHT REFLECTOR LH / RH	Not Necessary	92.00 FS	*- FS
8	1		*REAR ANTENNA AERIAL	Not Necessary	79.00 FS	*- FS
9	1		*REAR LID CONTROL UNIT	Not Necessary	454.00 FS	*- FS
10	1		*REAR BUMPER REINFORCEMENT BEAM	Not Necessary	693.00 FS	*- FS
11	2		*REAR BUMPER HOLDING STRAP LH / RH	Not Necessary	64.00 FS	*- FS
12	2		*REAR BUMPER GUIDE SECTION LH / RH	Not Necessary	142.00 FS	*- FS
13	2		*REAR PARKING AID SENSOR	Not Necessary	998.00 FS	*- FS
14	4		*REAR SENSOR SEAL RING	Not Necessary	10.00 FS	*- FS
15	1		*REAR LID	Dented	3,767.00 FS	*3,013.60 FS
16	1		*REAR LID PACKING ADHESIVE	Necessary	21.00 FS	*16.72 FS
17	4		*BOLTS AND NUTS	Not Necessary	18.00 FS	*- FS
18	1		*REAR LID ATTACHMENTS PARTS	Not Necessary	393.00 FS	*- FS
19	1		*REAR LID GASKET	Not Necessary	229.00 FS	*- FS
20	1		*REAR LID LOCK - COVER	Not Necessary	8.00 FS	*- FS
21	1		*AUDI CHROME LOGO	Necessary	144.00 FS	*114.80 FS
22	1		*AUDI Q3 CHROME EMBLEM	Necessary	104.00 FS	*82.80 FS
23	1		*REAR WINDSCREEN	Necessary	1,064.00 FS	*851.20 FS
24	1		*REAR WINDSCREEN PRIMER	Necessary	22.00 FS	*17.36 FS
25	2		*REAR WINDSCREEN SPOILER LH / RH	Necessary	470.00 FS	*375.20 FS
26	2		*REAR LID SPOILER ATTACHEMENTS PARTS	Necessary	16.00 FS	*12.64 FS
27	2		*REAR WHEEL COVER REAR LH / RH	Necessary	566.00 FS	*452.00 FS
28	1		*REAR WINDSCREEN SEALANT	Necessary	200.00 FS	*200.00 FS
29	1		*REAR NO PLATE	Not Necessary	60.00 FS	*- FS
30	1		*SUNDRIES	Necessary	400.00 FS	*14.40 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 12,691.00 6,949.12

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR	New	360.00	360.00
2	TO REMOVE AND TRANSFER REAR LIDS CONVENIENCE LOCK SYSTEM, WIRE HARNESS FOR TAILLIGHTS AND REAR LID WIPER ASSY	New	480.00	480.00
3	TO RENEW REAR WINDSCREEN TO FACILITATE THE RENEWAL OF REAR LID	New	480.00	480.00
4	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN	New	400.00	400.00
5	TO CARRY WATER SEEPAGE TEST FOR REAR WINDSCREEN	New	200.00	150.00
6	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. TO REPAIR REAR END PANELLING. REORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,800.00	1,000.00
7	TO RESPRAY REAR BUMPER, REAR LID AND REAR END PANELLING	New	3,000.00	1,100.00
8	TO CARRY OUT TOWING FROM ACCIDENT SCENE	New	280.00	0.00
9	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (\$\$)</b>			<b>8,192.00</b>	<b>4,162.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >