

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22003210/UEA3Q2**Date:** 27/07/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100396824
Claimant Vehicle No :	SKZ8542H	Insured Vehicle No :	SKQ7758G
Date of Loss:	06/04/2022	Nature of Claim:	TP
		Claim No:	2786226893SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKZ8542H	Engine No:	L15B4028054
Make & Model:	HONDA VEZEL, 1.5 X (A)	Chassis No:	RU11108050
Reg. Date:	04/02/2016 (Man. Year: 2015)	Odometer:	128537 km
Colour:	Maroon		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,669.90	6,604.24	11,065.66	62.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,180.00	2,170.00	2,010.00	48.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,849.90	8,774.24	13,075.66	59.84
Approved Total (Overridden) (S\$)		7,000.00		
(S\$)	21,849.90	7,000.00	14,849.90	67.96
+ GST 7.00/7.00% (S\$)	1,529.49	490.00	1,039.49	67.96
Nett Amount (S\$)	23,379.39	7,490.00	15,889.39	67.96
+ Loss of Use (6.0 x S\$60.00/day) (S\$)		360.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		7,852.00		

INSPECTION

Date of Assignment:	07/04/2022	
Date Inspected:	07/04/2022	Inspected At: Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883
Estimated Period of Repair:	5.0 days	

Adjuster: MARCUS CHUA**Manager:** Asher Sng Rong Yi*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Necessary	110.20 F	*110.20 FL
2	1		*TAILGATE	Badly Dented	1,299.20 F	*998.20 FL
3	1		*TAILGATE VEZEL EMBLEM	Necessary	66.80 F	*66.80 FL
4	1		*TAILGATE H LOGO	Not Necessary	45.00 F	*- FL
5	1		*TAILGATE OUTER HANDLE GARNISH	Not Necessary	450.00 F	*- FL
6	2		*TAILGATE REFLECTORS	Scratched/Cracked	772.40 F	*640.80 FL
7	1		*TAILGATE INNER LOCK	Bent	399.80 F	*180.20 FL
8	1		*TAILGATE LOCK STRIKER	Not Necessary	66.00 F	*- FL
9	1		*TAILGATE INNER TRIM BOARD	Deformed/Cracked	435.00 F	*366.10 FL
10	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 F	*50.00 FL
11	1		*TAILGATE WEATHERSTRIP	Twisted	288.00 F	*162.30 FL
12	1		*REAR BUMPER	Distorted	980.00 F	*760.00 FL
13	2		*REAR BUMPER SIDES	Repair	470.20 F	*- FL
14	2		*REAR BUMPER REFLECTORS	Cracked	302.00 F	*302.00 FL
15	1		*REAR BUMPER UNDER COVER	Deformed/Twisted	541.00 F	*311.20 FL
16	1		*SET REAR BUMPER UNDER COVER CLIPS	Necessary	50.00 F	*50.00 FL
17	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
18	1		*REAR END PANEL	Badly Dented	665.20 F	*586.20 FL
19	1		*REAR END PANEL TOP GARNISH	Twisted	341.10 F	*166.80 FL
20	2		*TAILLAMPS	Scratched/Cracked	1,300.00 F	*964.00 FL
21	2		*TAILLAMP HOUSING PANELS	Repair	700.00 F	*- FL
22	1		*REAR BUZZLE SENSOR	Cracked	98.00 F	*98.00 FL
23	2		*REAR FENDERS	Repair	2,180.00 F	*- FL
24	2		*REAR FENDER OUTER PROTECTORS	Deformed/Torn	760.00 F	*416.00 FL
25	2		*REAR FENDER INNER TRIM BOARDS	Deformed/Twisted	790.00 F	*732.40 FL
26	1		*REAR FLOOR PANEL	Repair	1,280.00 F	*- FL
27	1		*REAR FLOOR PANEL TOP BOARD	Warped/Torn	522.00 F	*381.10 FL
28	1		*REAR FLOOR PANEL TOOLS SPONGE	Torn	785.00 F	*450.50 FL
29	1		*REAR EXHAUST	Repair	765.00 F	*- FL
30	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	108.00 F	*- FL
31	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
32	1		*REAR WINDSCREEN INNER SEAL	Necessary	50.00 FS	*40.00 FS
33	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
34	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
35	1		*SET REAR REVERSE CAMERA	Not Necessary	450.00 FS	*- FS
36	1		*SET REAR FLOOR PANEL INSULATOR	Not Necessary	120.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	17,669.90	8,172.80
- List Item Discount on L Items 0.00/20.00% (S\$)	0.00	1,568.56
Total Parts (S\$)	17,669.90	6,604.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REPLACED REVERSE SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	120.00
4	TO TRANSFER TAILGATE MECHANISM	New	100.00	60.00
5	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	120.00	80.00
6	TO RESET & REPROGRAMME DIAGNOSIS SYSTEM	New	180.00	0.00
7	TO DISMANTLE & REFIX REAR EXHAUST	New	100.00	0.00
8	TO SPRAY RUST PROOFING	New	100.00	60.00
9	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,800.00	800.00
10	TO PUTTY & SPRAY PAINTING	New	1,500.00	980.00
Gross Labour Cost (\$\$)			4,180.00	2,170.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >