

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22003211/AEA3Q2**Date:** 02/08/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100478096
Claimant Vehicle No :	SDU80K	Insured Vehicle No :	SGN9999C
Date of Loss:	02/04/2022	Nature of Claim:	TP
		Claim No:	3561717889SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDU80K	Engine No:	F449K198B48B20B
Make & Model:	BMW 630I, 2.0 GT LED NAV (A)	Chassis No:	WBAJX62040BX07460
Reg. Date:	28/08/2020 (Man. Year: 2019)	Odometer:	17507 km
Colour:	White		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	275/40R19	Rear Tyre Size:	275/40R19
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,297.19	4,081.93	7,215.26	63.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,100.00	940.00	3,160.00	77.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,397.19	5,021.93	10,375.26	67.38
Approved Total (Overridden) (S\$)		4,000.00		
Nett Amount (S\$)	15,397.19	4,000.00	11,397.19	74.02
+ Car Rental (3.0 x S\$140.00/day) (S\$)		420.00		
Nett Liability (S\$)		4,420.00		

INSPECTION

Date of Assignment:	06/04/2022	JL Perfect Autowork Pte Ltd (HQ)
Date Inspected:	06/04/2022 Inspected At:	8 Kaki Bukit Avenue 4, #08-09 Premier@Kaki Bukit
Estimated Period of Repair:	3.0 days	Singapore 415875

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,964.80 FL	*1,964.80 FL
2	1		*REAR BUMPER LOWER	Deformed	854.30 FL	*653.00 FL
3	1		*REAR BUMPER TOWING COVER	Not Necessary	22.65 FL	*- FL
4	1		*REAR BUMPER TOP BEAM	Deformed	395.00 FL	*258.00 FL
5	1		*REAR BUMPER REINFORCEMENT	Dented	829.80 FL	*829.80 FL
6	1		*REAR BUMPER REINFORCEMENT COVER GARNISH	Cracked	245.65 FL	*245.65 FL
7	2		*REAR BUMPER SIDE BRACKET (PLASTIC)	Not Necessary	281.50 FL	*- FL
8	1		*REAR BUMPER BOTTOM CENTER GARNISH	Not Necessary	256.10 FL	*- FL
9	1		*REAR BUMPER CENTER BRACKET (CENTER)	Not Necessary	185.00 FL	*- FL
10	1		*REAR BUMPER SENSOR (4 Pcs)	Damaged	901.80 FL	*450.90 FL
11	4		*REAR BUMPER SENSOR HOLDER	Necessary	248.20 FL	*100.00 FL
12	1		*REAR BUMPER SENSOR DETECTOR	Not Necessary	410.00 FL	*- FL
13	1		*REAR BUMPER SENSOR WIRE HARNESS	Not Necessary	2,051.00 FL	*- FL
14	1		*REAR BUMPER LOWER GARNISH (SIDE) RH	Not Necessary	95.00 FL	*- FL
15	1		*REAR BUMPER SMART SENSOR CONTROL UNIT	Not Necessary	374.00 FL	*- FL
16	1		*REAR BUMPER SMART SENSOR	Not Necessary	169.00 FL	*- FL
17	1		*REAR BUMPER SMART SENSOR MOTOR C/W CABLE	Not Necessary	279.00 FL	*- FL
18	2		*TAIL LAMP	Not Necessary	962.40 FL	*- FL
19	1		*REAR END PANEL	Not Necessary	740.00 FL	*- FL
20	1		*REAR END PANEL TOP GARNISH	Not Necessary	195.00 FL	*- FL
21	1		*SET REAR BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
22	1		*SET REAR BUMPER BOTTOM CENTER GARNISH CLIP	Not Necessary	30.00 FS	*- FS
23	1		*SET REAR BUMPER LOWER GARNISH (SIDE) CLIP	Not Necessary	30.00 FS	*- FS
24	1		*SET TAIL LAMP CLIP	Not Necessary	40.00 FS	*- FS
25	1		*SET REAR FENDER INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
26	1		*REAR END PANEL INSULATION SEAL	Not Necessary	150.00 FS	*- FS
27	1		*SET REAR END PANEL TOP GARNISH CLIP	Not Necessary	30.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	11,870.20	4,532.15
- List Item Discount on L Items 5.00/10.00% (\$)	573.01	450.22
Total Parts (\$)	11,297.19	4,081.93

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING,REMOVAL AND REPLACING PARTS	New	1,000.00	300.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,000.00	400.00
3	TUFF COAT	New	250.00	0.00
4	WIRING CHECK	New	380.00	30.00
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	New	380.00	0.00
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	60.00
7	REAR CHASSIS ALIGNMENT	New	250.00	0.00
8	CONDUCT WATER LEAKAGE TEST	New	80.00	0.00
9	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC	New	680.00	150.00
Gross Labour Cost (\$\$)			4,100.00	940.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >