

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

India International Insurance Pte Ltd
64 Cecil Street, #04-00 IOB Building
Singapore 049711

Our File No: CS/III22003213/KQY3E2

Date: 26/05/2022

REFERENCE

Insured/Claimant: COMFORTDELGRO RENT-A-CAR PTE LTD Policy No: D18MFL0003414_02

Date of Loss: 02/04/2022

Nature of Claim: OD

Claim No: MFL2022D0001796

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SML5596Y	Engine No:	2ZR2C23627
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Chassis No:	JTDKB3FU703081009
Reg. Date:	27/05/2019 (Man. Year: 2018)	Odometer:	239498 km
Colour:	Metallic Pearl White		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	S\$108,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Davanti 8 mm	Rear Left Side:	Davanti 8 mm
Front Right Side:	Davanti 8 mm	Rear Right Side:	Davanti 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,704.50	2,994.65	9,709.85	76.43
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	2,610.00	1,510.00	1,100.00	42.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,325.50	4,515.65	10,809.85	70.54
Approved Total (Overridden) (S\$)		3,400.00		
- Excess (S\$)	0.00	1,500.00	-1,500.00	
(S\$)	15,325.50	1,900.00	13,425.50	87.60
+ GST 7.00/7.00% (S\$)	1,072.79	133.00	939.79	87.60
Nett Amount (S\$)	16,398.29	2,033.00	14,365.29	87.60

INSPECTION

Date of Assignment:	07/04/2022	Present Location:	ComfortDelGro Engineering Pte Ltd (Braddell)
Date Inspected:	07/04/2022	Inspected At:	ComfortDelGro Engineering Pte Ltd (Braddell) 205 Braddell Road Singapore 579701
Estimated Period of Repair:	5.0 days		

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 May 2022)
Parts:	144	TOYOTA PRIUS 1.8 5DR HATCHBACK (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SML5596Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Buckled	547.10 FL	*547.10 FL
2	1		*FRT BUMPER SIDE RETAINER LH	Distorted	84.70 FL	*84.70 FL
3	1		*FRT BUMPER SIDE RETAINER RH	Serviceable	84.70 FL	*- FL
4	1		*FRT BUMPER UPPER REINFORCEMENT	Repair	758.70 FL	*- FL
5	1		*FRT BUMPER LOWER REINFORCEMENT	Repair	760.90 FL	*- FL
6	1		*FRT BUMPER UPPER SPONGE	Serviceable	84.70 FL	*- FL
7	1		*FRT BUMPER LOWER SPONGE	Serviceable	100.80 FL	*- FL
8	1		*FRT BUMPER FOG LAMP LH	Serviceable	1,009.10 FL	*- FL
9	1		*FRT BUMPER FOG LAMP RH	Serviceable	1,009.10 FL	*- FL
10	1		*FRT BUMPER TOP RUBBER	Serviceable	54.70 FL	*- FL
11	1		*HEADLAMP LH	Serviceable	2,661.70 FL	*- FL
12	1		*HEADLAMP LOWER BRACKET LH	Serviceable	79.00 FL	*- FL
13	1		*HEADLAMP RH	Serviceable	2,661.70 FL	*- FL
14	1		*HEADLAMP LOWER BRACKET RH	Serviceable	79.00 FL	*- FL
15	10		*FRT BUMPER CLIPS.	Necessary	55.00 FL	*55.00 FL
16	1		*FRT NUMBER PLATE WITH CASING	Dented	45.00 FS	*45.00 FS
17	1		*FRT NUMBER PLATE BASE(LONG)	Cracked	109.80 FL	*109.80 FL
18	1		*FRT GRILLE	Dented	367.20 FL	*367.20 FL
19	1		*FRT GRILLE LOGO	Necessary	96.60 FL	*96.60 FL
20	1		*FRT SUPPORT PANEL TOP	Repair	379.60 FL	*- FL
21	1		*FRT SUPPORT PANEL TOP RH	Repair	80.00 FL	*- FL
22	1		*FRT SUPPORT PANEL TOP LH	Repair	80.00 FL	*- FL
23	1		*FRT SUPPORT SIDE PANEL LH	Repair	255.00 FL	*- FL
24	1		*FRT SUPPORT SIDE PANEL RH	Repair	255.00 FL	*- FL
25	1		*FRT SUPPORT LOWER PANEL	Repair	435.00 FL	*- FL
26	1		*REAR BUMPER	Bent	469.50 FL	*469.50 FL
27	1		*REAR BUMPER LOWER GARNISH	Bent	380.50 FL	*380.50 FL
28	1		*REAR BUMPER TOW COVER RH	Missing	24.80 FL	*24.80 FL
29	1		*REAR BUMPER SIDE RETAINER RH	Distorted	98.60 FL	*98.60 FL
30	1		*REAR BUMPER SIDE RETAINER LH	Serviceable	98.60 FL	*- FL
31	1		*REAR BUMPER SIDE COVER RH	Serviceable	105.60 FL	*- FL
32	1		*REAR BUMPER REINFROCEMENT	Bent	353.10 FL	*353.10 FL
33	1		*REAR BUMPER LOWER COVER	Missing	353.10 FL	*353.10 FL
34	1		*REAR BUMPER SENSOR	Shorted	280.00 FS	*200.00 FS
35	10		*REAR BUMPER CLIPS	Necessary	55.00 FL	*55.00 FL
36	1		*REAR BUMPER LAMP RH	Serviceable	532.00 FL	*- FL
37	1		*REAR END PANEL	Repair	689.70 FL	*- FL
38	1		*TAILLAMP RH	Serviceable	479.60 FL	*- FL
39	1		*BOOTLID LOCK	Dented	495.60 FL	*495.60 FL
40	1		*BOOTLID WEATHER STRIP	Distorted / Dented	175.60 FL	*175.60 FL
41	1		*REAR BUMPER SIDE COVER LH	Serviceable	105.60 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	16,831.00	3,911.20
- List Item Discount on L Items 25.00/25.00% (\$\$)	4,126.50	916.55
Total Parts (\$\$)	12,704.50	2,994.65

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK, STRAIGHTEN AND RENEW ACCIDENT AREA SUCH BONNET, FRT BUMPER, BOTH HEADLAMPS, FRT SUPPORT PANEL AND ETC	New	480.00	240.00
2	TO KNOCK, STRAIGHTEN AND RENEW ACCIDENT AREA SUCH BOOTLID, REAR BUMPER, REAR END PANEL AND ETC	New	480.00	480.00
3	TO PUTTY AND RESRPAY ACCIDENT AREA SUCH AS FRT BUMPER, BONNET, FRT SUPPORT PANEL AND ETC	New	750.00	250.00
4	TO PUTTY AND RESRPAY ACCIDENT AREA SUCH AS REAR BUMPER, BOOTLID, REAR END PANEL AND ETC	New	750.00	500.00
5	TO CHECK WIRING AND LIGHTING	New	50.00	40.00
6	TO DISCHARGE AND CHARGE AIRCON GAS	New	100.00	0.00
Gross Labour Cost (\$\$)			2,610.00	1,510.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >