

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120**Our File No:** CC3/AIG22003216/ANCE2**Date:** 15/12/2022**REFERENCE**

Insured/Claimant:	ALESSANDRO PERROTTA	Policy No:	2100480662-05
Date of Loss:	01/04/2022	Nature of Claim:	OD
		Claim No:	5906276711SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLF5683Y	Engine No:	CYR012514
Make & Model:	AUDI Q7, 2.0 TFSI QU (A)	Chassis No:	WAUZZZ4M4GD060216
Reg. Date:	30/08/2016 (Man. Year: 2016)	Odometer:	48667 km
Colour:	White		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$134,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/55 R19	Rear Tyre Size:	255/55 R19
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	35,520.60	25,357.44	10,163.16	28.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	26,352.00	18,342.00	8,010.00	30.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	61,872.60	43,699.44	18,173.16	29.37
- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
(S\$)	60,872.60	42,699.44	18,173.16	29.85
+ GST 7.00/7.00% (S\$)	4,261.08	2,988.96	1,272.12	29.85
Nett Amount (S\$)	65,133.68	45,688.40	19,445.28	29.85

INSPECTION

Date of Assignment:	07/04/2022		
Date Inspected:	06/04/2022	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	16.0 days		

Adjuster: ADRIAN LING**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,451.00 FS	*1,160.80 FS
2	1		*REAR BUMPER COVER	Deformed	2,201.00 FS	*1,760.80 FS
3	1		*REAR BUMPER FIXING PARTS	Not Necessary	217.00 FS	*- FS
4	1		*REAR BUMPER SPOILER	Cut	1,407.00 FS	*1,125.60 FS
5	1		*REAR BUMPER GUIDE SECTION	Damaged	71.00 FS	*56.48 FS
6	1		*REAR BUMPER SENSOR (NPA)	Not Necessary	0.00 FS	*- FS
7	1		*REAR BUMPER SEAL RING	Not Necessary	10.00 FS	*- FS
8	1		*TAILLIGHT BULB	Not Necessary	402.00 FS	*321.60 FS
9	1		*LED TAILLIGHT	Cracked	2,279.00 FS	*1,823.20 FS
10	1		*REAR LID	Dented	6,480.00 FS	*5,184.00 FS
11	1		*REAR LID ATTACHMENTS PARTS	Not Necessary	359.00 FS	*- FS
12	2		*REAR LID HINGE LH / RH	Not Necessary	342.00 FS	*- FS
13	1		*FLAP LOCK COVER CAP	Not Necessary	13.00 FS	*- FS
14	1		*REAR LID GASKET	Not Necessary	325.00 FS	*- FS
15	1		*PACKING ADHESIVE	Necessary	21.00 FS	*16.72 FS
16	1		*AUDI CHROME LOGO	Necessary	144.00 FS	*114.80 FS
17	1		*AUDI CHROME Q7 EMBLEM	Necessary	104.00 FS	*82.80 FS
18	1		*AUDI CHROME TFSI EMBLEM	Necessary	104.00 FS	*82.80 FS
19	1		*AUDI CHROME QUATTRO EMBLEM	Necessary	104.00 FS	*82.80 FS
20	1		*REAR WINDSCREEN	Necessary	1,307.00 FS	*1,045.60 FS
21	2		*REAR WINDSCREEN PRIMER	Necessary	44.00 FS	*34.72 FS
22	2		*REAR WINDSCREEN SPOILER REAR LH / RH	Necessary	514.00 FS	*410.40 FS
23	1		*REAR WINDSCREEN FOAM STRIPS	Necessary	153.00 FS	*122.00 FS
24	1		*REAR SPOILER FIXING PARTS	Not Necessary	69.00 FS	*- FS
25	1		*SECTIONAL PARTS LH	Dented	7,776.00 FS	*6,220.80 FS
26	1		*1/4 GLASS	Necessary	1,053.00 FS	*842.40 FS
27	1		*SILL TRIM STRIP LH	Not Necessary	182.00 FS	*- FS
28	1		*SPOILER REAR LH	Not Necessary	40.00 FS	*- FS
29	1		*WHEEL HOUSING LINER	Not Necessary	347.00 FS	*- FS
30	2		*WHEEL COVER REAR LH / RH	Necessary	794.00 FS	*635.20 FS
31	1		*REAR DOOR COVER REAR LH UPPER / LH LOWER	Not Necessary	880.00 FS	*- FS
32	1		*ALUMINIUM RIM	Cut	2,266.00 FS	*1,812.80 FS
33	1		*RUBBER VALVE	Not Necessary	4.00 FS	*- FS
34	3		*STATIC MIXER	Necessary	27.60 FS	*27.60 FS
35	1		*2 PACK EPOXY ADHESIVE	Necessary	122.00 FS	*97.20 FS
36	1		*ALUMINIUM POWDER	Necessary	637.00 FS	*509.60 FS
37	1		*HARDENER	Necessary	232.00 FS	*185.20 FS
38	1		*ALUMINIUM PRIMER	Not Necessary	233.00 FS	*- FS
39	1		*CLEANING BLOCK	Necessary	96.00 FS	*64.16 FS
40	1		*SPARE PARTS GASKET LH	Not Necessary	157.00 FS	*- FS
41	1		*SPARE PARTS BASIC PLATE LH	Not Necessary	116.00 FS	*- FS
42	1		*SPARE PARTS ALUMINIUM FRONT LH	Not Necessary	288.00 FS	*- FS
43	1		*ACRYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
44	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
45	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
46	1		*METAL FILLER POWDER	Necessary	280.00 FS	*280.00 FS
47	1		*REAR WINDSCREEN SEALANT	Necessary	200.00 FS	*200.00 FS
48	1		*1/4 GLASS SEALANT	Necessary	100.00 FS	*100.00 FS
49	1		*SUNDRIES	Necessary	500.00 FS	*67.04 FS
50	1		*COUNTERSUNK RIVET (Supplementary)	Necessary	115.00 FS	*92.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
51	1		*POP RIVET (Supplementary)	Necessary	30.00 FS	*24.00 FS
52	1		*2PK PLASTIC ADHESIVE (Supplementary)	Necessary	62.00 FS	*49.12 FS
53	1		*REAR VENT TRIM (Supplementary)	Not Necessary	80.00 FS	*- FS
54	1		*SEAL FOR SILL PANEL LHS (Supplementary)	Necessary	282.00 FS	*225.20 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	35,520.60	25,357.44
--------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR	New	360.00	360.00
2	TO REMOVE AND TRANSFER REAR LIDS CONVENIENCE LOCK SYSTEM, WIRE HARNESS FOR TAIL LIGHTS AND REAR LID WIPER ASSY	New	480.00	480.00
3	TO RENEW REAR WINDSCREEN TO FACILITATE THE RENEWAL OF LHS REAR LID	New	480.00	480.00
4	TO RENEW LHS 1/4 GLASS TO FACILITATE RENEWAL OF LHS REAR FENDER	New	300.00	300.00
5	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN AND 1/4 GLASS	New	200.00	150.00
6	TO DISLodge AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY	New	1,600.00	1,600.00
7	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLodge ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC	New	1,600.00	1,600.00
8	TO SET UP AND PLACED VEHICLE IN ALUMINIUM BAY	New	1,800.00	1,800.00
9	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. TO CUT OUT AND WELD LHS REAR FENDER. TO REPAIR LHS REAR DOOR. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	7,500.00	5,900.00
10	TO RESPRAY REAR UPPER BUMPER, REAR LOWER BUMPER, REAR LID, HINGES, LHS REAR FENDER, LHS REAR DOOR, DOOR COVER, LHS SILL PANEL, ROOF CHANNEL, DOOR ENTRANCE, DRAIN CHANNEL, REAR END PANELLING, LHS REAR DOOR WHEEL ARCH TRIM AND BOTH REAR WHEEL ARCH TRIMS	New	9,500.00	3,900.00
11	TO CARRY OUT ALUMINIUM PRIMER WORKS	New	900.00	900.00
12	TO REMOVE AND REINSTALL LHS ROOF RAIL	New	280.00	0.00
13	TO REMOVE AND REINSTALL ROOFTOP PANEL CARRIER	New	480.00	0.00
14	TO RENEW RHS REA RIM. TO CARRY OUT PRE/POST WHEEL ALIGNMENT	New	280.00	280.00
15	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
16	TO APPLY SOLAR FILM ON REAR WINDSCREEN AND LH 1/4 GLASS (Supplementary)	New	400.00	400.00
Gross Labour Cost (S\$)			26,352.00	18,342.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >