6/2/22, 11:37 AM Adjuster Report

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI22003220/TQY3N2

02/06/2022 Date:

Chassis No:

**REFERENCE** 

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No: DMB1SNW00004992201

**Claimant Vehicle** 

SLT2545J

**Insured Vehicle** 

PZ5551S

No:

No:

Claim

Date of Loss:

Reg. Date:

05/04/2022

Nature of Claim: TP

SNM22D202346/C02/CSC No:

JTDKB3FUX03574487

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

**SLT2545J** Reg No:

TOYOTA PRIUS HYBRID, 1.8 CVT (A) Make & Model:

24/10/2017 (Man. Year: 2017)

Engine No: 2ZRS105306

Colour: Silver Odometer: 288574 km

**Engine Capacity:** 1798 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): **Engine Modification:** Pre-accident Condition: Yes Nο

**CONDITION OF TYRES** 

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15 Front Left Side: Rear Left Side: Dunlop 6 mm Dunlop 6 mm Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,043.00	1,737.00	306.00	14.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,120.00	8,105.00	1,015.00	11.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	11,163.00	9,842.00	1,321.00	11.83
+ GST 7.00/7.00% (S\$)	781.41	688.94	92.47	11.83
Nett Amount (S\$)	11,944.41	10,530.94	1,413.47	11.83

**INSPECTION** 

Date of Assignment: 02/06/2022

Borneo Motors (S) Pte Ltd (Pandan)

Date Inspected: 07/04/2022 Inspected At: 2 Pandan Crescent

Singapore 128462

Estimated Period of Repair: 10.0 days

Adjuster: MOHD TAUFIKH BIN HAMID Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

### REPAIR DETAILS

### Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 02 Jun 2022)

Parts: 144 TOYOTA PRIUS HYBRID 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLT2545J)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PANEL BONDING AD	Necessary	267.20 FS	*267.20 FS
2	1		*COVER,RR BUMPER	Deformed	469.50 FS	*469.50 FS
3	1		*RETAINER,RR BUMPER	Not Necessary	124.90 FS	*-FS
4	1		*FILLER,RR BUMPER	Not Necessary	131.10 FS	*-FS
5	1		*PANEL SUB-ASSY	Bent	925.90 FS	*925.90 FS
6	1		*PROTECTOR,QUARTER	Necessary	24.40 FS	*24.40 FS
7	1		*SUNDRIES	Necessary	100.00 FS	*50.00 FS
F=Fra	anchise	part. S=SpcNet	t.			
				Total Parts (S\$)	2,043.00	1,737.00

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items			
1	CHECK WIRING AND CONDUCT LEAK TEST	New	180.00	180.00
2	R/I INTERIOR UPHOLSTERY TO FAC REPAIR	New	720.00	720.00
3	REPL ACC AFF PARTS AND PANEL STRAIGHTEN AND REALLIC ACC AFF AREA	New	4,320.00	3,600.00
4	RESPRAY ACC AFF AREA	New	3,540.00	3,245.00
5	DRILL HOLE AND INSTALL REVERSE SENSOR	New	180.00	180.00
6	RESET ECU UPON COMPLETION OF REPAIR	New	180.00	180.00
	Gross L	abour Cost (S\$)	9,120.00	8,105.00
	Report was unsubmitted during	this print-out.		

< END OF ESTIMATES >