



ComfortDelGro Engineering

205 Braddell Road S(579701)

ACCIDENT REPAIR ESTIMATES

Our Ref:

Type of Claim : TPVehicle No. : YP4864SMake & Model : ISUZU NPR85UH5AYear of Manufacture : 2016Chassis No. : 4JJ12N2539Engine No. : JAANPR85HG7100327Policy No. : BVFCB0013702102Time of Accident : 1301

Ins Company : _____

Excess : _____

Date of Accident : 29/03/22

Suggested Days of Repair : _____

In-house Vehicle Assessor**Repair Estimates**Case Owner : BRENDA NG

Signature : _____

Parts (a) Cost / List Price Items \$ -

Plus/Less \$ -

Total of Cost / List \$ -

(b) Nett Price Items \$ -

Less _____

Total of Nett Item _____

(c) Special Nett Items \$ -

Total Parts Cost (Appendix A) \$ -

Labour (Appendix B) \$ 1,400.00

Total Repair Cost \$ 1,400.00

Contact No

Frt Counter Operation

63837103 - Patrick Tia

PatrickTia@sparkcarcare.com

63837730 - Brenda Ng

BrendaNg@sparkcarcare.com

63837466 - Rohani

RohaniM@sparkcarcare.com**Workshop Operation**

63837656 - Ngo Toh Wee

Ngotw@sparkcarcare.com

63838115 -

63837362 -

The above total will be subjected to 7% G.S.T.

Name of Surveyor : _____

Company : _____

Survey conducted on : _____ at _____

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : _____ day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : _____ Date: _____

Spark Car Care

ComfortDelGro Engineering Pte Ltd
205 Braddell Road S (579701)
Tel: 63837168 / 63837466 Fax:62815767

Spare Parts

Vehicle No : YP4864S Case Owner : BRENDA NG

Make & Model : ISUZU NPR85UH5A Year Manufacture : _____

Chassis No : 4JJ12N2539 Engine No : JAANPR85HG7100327

Sales Order : _____ Supplier : _____

Order By : _____ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	LH CORNER PANEL	1					
2	LEFT SIDE MIRROR ASSY	1					
3	LH SMALL MIRROR (ROUND)	4					
4	LH SIDE MIRROR ARM GARNISH	1					
5	LH BRACKET TOP COVER	1					
6	LH BRACKET TOP SIDE	1					
7	STICKER - LEFT CORNER STICKER (CLUE)	1					
8	0	1					
9	0	1					
10	0	1					
11	0	1					
12	0	1					
13	0	1					
14	0	1					
15	0	1					
16	0	1					
17	0	1					
18	0	1					
19	0	1					
20	0	1					
21	0	1					
22	0	1					
23	0	2					
24	0	1					
25	0	1					
26	0	1					
27	0	1					
28	0	1					
29	0	1					
30	0	1					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Tel: 63837168 / 63837466 Fax: 62815767

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.