

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22003221/KNY3E2**Date:** 14/03/2023REFERENCEHandling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00053122111

**Claimant Vehicle
No :** YP4864S**Insured Vehicle
No :** GBB5111X

Date of Loss: 29/03/2022

Nature of Claim: TP

Claim
No: SNM22D202195/C02/LEEPGDESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **YP4864S**

Make & Model: ISUZU NPR85UH5A, 3.0 D (M)

Engine No: 4JJ12N2539

Reg. Date: 01/11/2016 (Man. Year: 2016)

Chassis No: JAANPR85HG7100327

Colour: Blue

Odometer: 169099 km

Engine Capacity: 2999 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|-------------|------------------|-----------------|
| Front Tyre Size: | 195/65 R16 | Rear Tyre Size: | 195/65 R16 (D) |
| Front Left Side: | Delium 9 mm | Rear Left Side: | Yokohama 9/9 mm |
| Front Right Side: | Delium 9 mm | Rear Right Side: | Yokohama 9/9 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts | 1,014.00 | 873.90 | 140.10 | 13.82 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 1,400.00 | 500.00 | 900.00 | 64.29 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Gross Total (S\$) | 2,414.00 | 1,373.90 | 1,040.10 | 43.09 |
| + GST 8.00/8.00% (S\$) | 193.12 | 109.91 | 83.21 | 43.09 |
| Nett Amount (S\$) | 2,607.12 | 1,483.81 | 1,123.31 | 43.09 |

INSPECTION

Date of Assignment: 06/04/2022

Date Inspected: 07/04/2022 Inspected At:

ComfortDelGro Engineering Pte Ltd (Braddell)
205 Braddell Road
Singapore 579701

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

| | | |
|----------------------|--|---|
| Part Source: | (Last Synchronised: 14 Mar 2023) | |
| Parts: | N/A | ISUZU NPR85UH5A 3.0 D (M) (Model not available in database) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for YP4864S) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|---------------------------------------|------------|---|-----------------|
| 1 | 1 | | *LH CORNER PANEL | Mtg Broken | 320.00 F | *320.00 FL |
| 2 | 1 | | *LEFT SIDE MIRROR SQUARE | Missing | 90.00 F | *90.00 FL |
| 3 | 4 | | *LH SMALL MIRROR (ROUND) | Missing | 70.00 F | *70.00 FL |
| 4 | 1 | | *LH SIDE MIRROR ARM GARNISH | Missing | 12.00 F | *12.00 FL |
| 5 | 1 | | *LH BRACKET TOP COVER | Missing | 42.00 F | *42.00 FL |
| 6 | 1 | | *LH BRACKET TOP SIDE (HOLDER) | Missing | 400.00 F | *400.00 FL |
| 7 | 1 | | *STICKER - LEFT CORNER STICKER (CLUE) | Necessary | 80.00 FS | *80.00 FS |
| | | | | | Sub Total (\$\$) | 1,014.00 |
| | | | | | - List Item Discount on L Items 0.00/15.00% (\$\$) | 0.00 |
| | | | | | Total Parts (\$\$) | 873.90 |

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|-------------------------------|---|----------|-----------------|---------------|
| Labour Items | | | | |
| 1 | TO KNOCK, STRAIGHTEN AND RENEW ACCIDENT AREA SUCH FRONT LH CORNER PANEL, LH SIDE MIRROR AND AFFECTED AREA | New | 600.00 | 250.00 |
| 2 | TO PUTTY AND RESPRAY ON LH SIDE MIRROR, LH CORNER PANEL AND AFFECTED AREA | New | 600.00 | 200.00 |
| 3 | TO DO ART WORK | New | 200.00 | 50.00 |
| Gross Labour Cost (\$) | | | 1,400.00 | 500.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >