

06/04/2022

1st



ComfortDelGro Engineering

205 Braddell Road S(579701)

ACCIDENT REPAIR ESTIMATES

Our Ref:

Type of Claim : TPVehicle No. : YP4864SMake & Model : ISUZU NPR85UH5AYear of Manufacture : 2016Chassis No. : 4JJ12N2539Engine No. : JAANPR85HG7100327Policy No. : BVFCB0013702102Time of Accident : 1301

Ins Company : _____

Excess : _____

Date of Accident : 29/03/22

Suggested Days of Repair : _____

In-house Vehicle Assessor**Repair Estimates**Case Owner : BRENDA NG

Signature : _____

Parts (a) Cost / List Price Items \$ -

Plus/Less \$ -

Total of Cost / List \$ -

(b) Nett Price Items \$ -

Less _____

Total of Nett Item _____

(c) Special Nett Items \$ -

Total Parts Cost (Appendix A) \$ -

Labour (Appendix B) \$ 1,400.00

Total Repair Cost \$ 1,400.00

Contact No

Frt Counter Operation

63837103 - Patrick Tia

PatrickTia@sparkcarcare.com

63837730 - Brenda Ng

BrendaNg@sparkcarcare.com

63837466 - Rohani

RohaniM@sparkcarcare.com**Workshop Operation**

63837656 - Ngo Toh Wee

Ngotw@sparkcarcare.com

63838115 -

63837362 -

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth
 Company : CKC
 Survey conducted on : 8/4/22 at _____

Remarks By Surveyor(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.(b) Recommended Days of Repair : 02 day(s)(c) Resurvey : Required / ~~Not Required~~

(d) Excess : \$ _____

(e) Signature of surveyor : Le Date: 8/4/22

Spark Car Care

ComfortDelGro Engineering Pte Ltd
205 Braddell Road S (579701)
Tel: 63837168 / 63837466 Fax: 62815767

Spare Parts

Vehicle No : YP4864S Case Owner : BRENDA NG
Make & Model : ISUZU NPR85UH5A Year Manufacture : _____
Chassis No : 4JJ12N2539 Engine No : JAANPR85HG7100327
Sales Order : _____ Supplier : _____
Order By : _____ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	LH CORNER PANEL <i>mg Br</i>	1		320.00			✓
2	LEFT SIDE MIRROR <i>ASSY SQUARE MIT</i>	1		90.00			✓
3	LH SMALL MIRROR (ROUND) <i>MIT</i>	4		70.00			✓
4	LH SIDE MIRROR ARM GARNISH <i>MIT</i>	1		12.00			✓
5	LH BRACKET TOP COVER <i>MIT</i>	1		42.00			✓
6	LH BRACKET TOP SIDE (holder) <i>MIT</i>	1		400.00			✓
7	STICKER - LEFT CORNER STICKER (CLUE) <i>la</i>	1				80.00	✓
8	0	1					
9	0	1					
10	0	1					
11	0	1					
12	0	1					
13	0	1					
14	0	1					
15	0	1					
16	0	1					
17	0	1					
18	0	1					
19	0	1					
20	0	1					
21	0	1					
22	0	1					
23	0	2					
24	0	1					
25	0	1					
26	0	1					
27	0	1					
28	0	1					
29	0	1					
30	0	1					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

8 1373.90

06/04/2022

8:15 AM

Tel: 63837168 / 63837466 Fax: 62815767

2016

The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.