Date

: 13 February 2020

To

: NTUC Income Insurance Co-operative Limited

73 Bras Basah Road #05-01 NTUC Trade Union House

Singapore 189556

Attn

: Mr Thio Tse Kiat

AJAX Inspection Services Pte Ltd

120 Lower Delta Road #08-08, Cendex Centre Singapore 169208 Tel: +65 6255 0808

Fax: +65 6849 9155 info@ajaxinspection.com

Invoice No - AV23382

Company Reg No -201318067R GST Reg No - 201318067R

TAX INVOICE

YOUR REF / CLAIM NUMBER

: MT/1075097-001

OUR REF

AVS2019-21891/PN

TP VEHICLE NO

: SKR3527C

CLAIM TYPE

: PRE-REPAIR SURVEY

DATE OF SURVEY

: 11 December 2019

No.

Description

Amount (S\$)

1

Professional fee

100.00

Subtotal 100.00 GST 7.00% 7.00 **Total 107.00**

Payment Terms: 30 days from date of invoice

Please remit by electronic transfer as follows: Payee: AJAX Inspection Services Pte Ltd

United Overseas Bank Ltd Account No: 450-309-276-4

Email remittance advice to: accounts@ajaxadjusters.com





Inspection Services Pte Ltd

PRE-REPAIR SURVEY REPORT

NTUC Income Insurance Co-operative Ltd

73 Bras Basah Road #05-01 NTUC Trade Union House Singapore 189556

Attention: Mr Thio Tse Kiat

Assign Date:

10/12/2019

Survey Date:

11/12/2019

Adjustment Date:

11/02/2020

Accident Date:

2100420355

Our Ref:

AVS2019-21891/PN

Place of Survey:

06/12/2019

TP Policy No:

Your Ref:

MT/1075097-001

Sze Kang Automobile Spraying Services 10 Ang Mo Kio Industrial Park 2a, Autopoint #03-17

Claim Type:

Third Party

Singapore

568047

Claimant:

Goh Tze Kang Anthony

Description of Vehicle:

Veh. No: Colour:

SKR3527C Black

Make/Model:

Mercedes-Benz CLA180

Sum Insured (S\$):

Market Value

Engine Capacity:

1595 cc

Engine No: Chassis No: 27091030498415 WDD1173422N137418

Mkt Value (S\$):

Odometer:

109573

Reg. Date:

02/02/2015

Excess (S\$):

\$75,000.00 NA

Condition of Vehicle:

General:

Fair

Modification:

No

Steering:

Affected

Handbrake:

Affected

Footbrake:

Affected

Paint work:

Fair

Tyre Make:

Pirelli

Front Left Side:

6mm

Front Right Side:

6mm

Front Tyre Size: Rear Tyre Size:

235/40R18 235/40R18

Rear Left Side:

6mm

Rear Right Side:

6mm

Description of Damage:

The vehicle sustained damage on the front left portion.

Remarks:

Our recommended amount for the cost of contract lumpsum repair is \$\$870.00 with approximately three (3) working days to complete. However, no finalisation was agreed with the repairer.

Special Remarks:

We did not conduct the post-repair survey as the repairer did not notify us.

Patrick Ng Adjuster: Motor Appraiser COMPLETED 12 FEB 2020

Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.



No.	Qty	Description of Parts	Condition	Third Party Surveyor's Estimate S\$	Our Recommendation S\$
ist Iten	ns				
1	1	Front bumper	Repair		**
2	1	Front LH sport rim	Grazed	1,314.00	550.00
3	1	Front LH shock absorber	Not necessary	881.00	
4	1	Front LH shock absorber top mounting	Not necessary	322.00	
5	1	Front LH lower arm	Not necessary	592.00	
6	1	Front LH knuckle arm	Not necessary	1,014.00	
7	1	Front LH wheel hub & bearing	Not necessary	207.00	
8	1	Front stabilizer bar	Not necessary		25//
9	1	Front stabilizer bar LH link rod	Not necessary	84.00	**
10	1	Steering roack & pinion tie rod	Not necessary	189.00	2
			Sub Total:	4,603.00	550.00
			Discount (less 10%):	460.30	55.00
			Total Parts Price:	4,142.70	495.00

1	To remove, jack out, striaghten, panel beating, align and renew replaced parts.	500.00	400.00
2	To putty and respray painting on affected areas.	600.00	200.00
3	To remove, refix front LH damaged undercarriage.	250.00	221
4	To conduct computerise wheel alignment.	60.00	-
5	To supplied and applied anti rust treatment.	30.00	
	Sub Total:	1,440.00	600.00
	Grand Total:	5,582.70	1,095.00

Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd