

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | | | |
|---|--|--|-----------------|---------|----------------------|--|
| | ASCENTSIA LAW | CORPORATION | | Ref: | CS/LAW22003223/Kqce2 | |
| | 10 ANSON ROAD, PLAZA,SINGAPOR | #03-22, INTERNATIONAL RE 079903 | | Date: | 05/05/2022 | |
| | | | | Code: | L173 | |
| 1. | Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION) | | | | | |
| | Insured Veh. | GBA 5711U | Veh. Inspected | | SKR 3527C | |
| | Policy No. | | Coverage (\$) | | 0.00 | |
| | Claim No. | CK/YSY/19.022977 | Excess (\$) | | 0.00 | |
| | Assign From | LIM HUI YING | Assign Date | | 30/03/2022 | |
| 2. | 2. Vehicle Particulars & Condition | | | | | |
| | Make & Model | MERCEDES BENZ CLA180 (A) | c.c | | 1595 | |
| | Engine No. | HIDDEN | Year of Reg. | | 2015 | |
| | Chassis No. | WDD1173422N137418 | Colour | | METALLIC DARK PURPLE | |
| | Odometer | 169212 KM | Steering | | IN ORDER | |
| | Brakes | IN ORDER | Modification | | STANDARD ALLOY RIM | |
| | General | GOOD | | | | |
| 3. | 3. Conditions of Tyres | | | | | |
| | | Size | Make | | Balance | |
| | R/H Front Tyre | 235/40Z R18 | PIRELLI | | 9 mm | |
| | L/H Front Tyre | 235/40Z R18 | PIRELLI | | 9 mm | |
| | R/H Rear Tyre | 235/40Z R18 | PIRELLI | | 9 mm | |
| | L/H Rear Tyre | 235/40Z R18 | PIRELLI | | 9 mm | |
| 4. | Description of Damages | | | | | |
| | THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. | | | | | |
| | REPAIR CONDITION SEE DETAILS. | | | | | |
| 5. | General Information | | | | | |
| | Accident Date | 06/12/2019 | Inspection Date | 9 | 11/04/2022 | |
| | Survey held at | SZE KANG AUTOMOBILE SPRAYING SERVICES | | | | |
| | | BLK 10 ANG MO KIO INDUSTRIAL PARK 2A #03-17 AMK AUTO POINT . SINGAPORE 568047 | | | | |
| 5a. | Remarks | | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | | |
| 5b. | Estimate Days of Repair | | | | | |
| | ESTIMATED NORM | MAL PERIOD FOR REPAIR: | | 3 Worki | ng Days | |