

ASS. REC. BY:

REF:

1/ANW 22003223/Kg

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

1210

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

10.30am

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection. ✓



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKR 3527C

Yr Regn:

02, 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mercedes

c.c

1595

Colour

M.O. Purple

A/C:

Insured / Std / NI / NA

Sp. Reading

169212

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WDD1173422N137418

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

235/40ZR18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIRY SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

8/12/2019

D.O.I.

11/4/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?



: Prel. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:



: Site Insp (\$



: Interview (\$



Tech Invs (\$



Weekend (\$

Survey Fee:

Transportation:

\$ - RS. \$

Fines

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

AUTO PERFORMANCE APPRAISAL

APA
12

VEHICLE SURVEY REPORTS																																
<p>Goh Tze Kang Anthony C/O Sze Kang Automobile Spraying Services 10 Ang Mo Kio Ind. Park 2A Ang Mo Kio Auto Point #03-17/09 Singapore 568047</p>																																
1	<p>Reference Job Reference No : 19/002059 Claim No : - Claim Type : Third Party Accident Date : 06/12/2019 Survey Date : 09/12/2019 Survey Report Date : 10/01/2020</p>																															
2	<p>Particulars Of Vehicle Vehicle Registration No : SKR3527C Make & Model : Mercedes Benz CLA 180 Vehicle Registration Date : 02/02/2015 Chassis No : wdd1173422n137418 Engine No : Blocked Colour : Purple</p>																															
3	<p>Condition Of Vehicle And Tyres</p> <table border="1"> <thead> <tr> <th><u>Mileage (KM)</u></th> <th><u>Brakes</u></th> <th><u>Steering</u></th> <th><u>Modification</u></th> </tr> </thead> <tbody> <tr> <td>109467</td> <td>Serviceable</td> <td>Serviceable</td> <td>None</td> </tr> </tbody> </table> <table border="1"> <thead> <tr> <th><u>Tyres</u></th> <th><u>Make</u></th> <th><u>Size</u></th> <th><u>Balance (MM)</u></th> </tr> </thead> <tbody> <tr> <td>Front RHS</td> <td>Pirelli</td> <td>245/40ZR18</td> <td>5</td> </tr> <tr> <td>Front LHS</td> <td>Pirelli</td> <td>245/40ZR18</td> <td>5</td> </tr> <tr> <td>Rear RHS</td> <td>Pirelli</td> <td>245/40ZR18</td> <td>6</td> </tr> <tr> <td>Rear LHS</td> <td>Pirelli</td> <td>245/40ZR18</td> <td>6</td> </tr> </tbody> </table>				<u>Mileage (KM)</u>	<u>Brakes</u>	<u>Steering</u>	<u>Modification</u>	109467	Serviceable	Serviceable	None	<u>Tyres</u>	<u>Make</u>	<u>Size</u>	<u>Balance (MM)</u>	Front RHS	Pirelli	245/40ZR18	5	Front LHS	Pirelli	245/40ZR18	5	Rear RHS	Pirelli	245/40ZR18	6	Rear LHS	Pirelli	245/40ZR18	6
<u>Mileage (KM)</u>	<u>Brakes</u>	<u>Steering</u>	<u>Modification</u>																													
109467	Serviceable	Serviceable	None																													
<u>Tyres</u>	<u>Make</u>	<u>Size</u>	<u>Balance (MM)</u>																													
Front RHS	Pirelli	245/40ZR18	5																													
Front LHS	Pirelli	245/40ZR18	5																													
Rear RHS	Pirelli	245/40ZR18	6																													
Rear LHS	Pirelli	245/40ZR18	6																													
4	<p>Description Of Damages The vehicle sustained damages at front left hand portion. (For information of damages please refer to Parts/Labour/Photographs attached)</p>																															
5	<p>Instruction This survey was conducted entirely on a "WITHOUT PREJUDICE" basis, and we have not authorised any repair.</p>																															

AUTO PERFORMANCE APPRAISAL

Annex A

Vehicle Assessment Reports

13

Ref No : 19/002059

Damage And Repair Cost Adjustment

<u>S/No</u>	<u>Qty</u>	<u>Parts Description</u>	<u>Comments/condition</u>	<u>Workshop Estimate (\$)</u>	<u>Our Assessment (\$)</u>
			<u>List Items</u>		
1	1	Front bumper	To repair	1,528.00	-
2	1	Front LH sports rims	Dented/warped	1,314.00	1,314.00 <i>800Jm</i>
3	1	Front LH shock absorber <i>835.60</i>	Bent	881.00	<i>NH</i> 881.00 <i>X</i>
4	1	Front LH shock absorber top mounting	Necessary	322.00	<i>NH</i> 322.00 <i>X</i>
5	1	Front LH lower arm <i>547.30</i>	Bent/loose	592.00	<i>NH</i> 592.00 <i>X</i>
6	1	Front LH knuckle arm	Bent	1,014.00	<i>NH</i> 1,014.00 <i>X</i>
7	1	Front LH wheel hub & bearing	Bent/necessary	207.00	<i>NH</i> 207.00 <i>X</i>
8	1	Front stabilizer bar	Serviceable/reuse	204.00	-
9	1	Front stabilizer bar LH link rod	Bent/loose	84.00	<i>NH</i> 84.00 <i>X</i>
10	1	Steering rack & pinion LH tie rod	Bent/loose	189.00	<i>NH</i> 189.00 <i>X</i>
				6,335.00	4,603.00
Less discount 10%				633.50	460.30
Total :				5,701.50	4,142.70
Total Spare Parts :				5,701.50	4,142.70

AUTO PERFORMANCE APPRAISAL

Vehicle Assessment Reports

Annex B

14

Ref No : 19/002059

Damage And Repair Cost Adjustment

<u>Items</u>	<u>Job Description</u>	<u>Workshop Estimate (\$)</u>	<u>Adjusted Costs (\$)</u>
1	To remove, jack out, straighten, panel beating, align and renew replaced parts.	800.00	500.00 <i>200d</i>
2	To putty and respray painting on affected areas.	800.00	600.00 <i>44d</i>
3	To remove, refix front LH damage under carriages. <i>nn</i>	300.00	250.00 <i>lost X</i>
4	To conduct computerise wheel alignment test.	80.00	60.00
5	To supplied and applied anti rust treatments. <i>nn</i>	50.00	30.00 <i>X</i>
Total Labour :		2,030.00	1,440.00
Total Spare Parts :		5,701.50	4,142.70
Total Labour :		2,030.00	1,440.00
Total Repair Costs :		7,731.50	5,582.70

Assessor's Recommendation

Repairer Estimate : 7,731.50
Our Adjustment : 5,582.70

Remarks

The repairer has agreed to undertake the repair on a lump sum basis of \$4,450.00, with a repair period of 4 working days.

Surveyed By:


Lek Boon Hwee
Automobile Appraiser

Date : 13 February 2020

To : NTUC Income Insurance Co-operative Limited
73 Bras Basah Road #05-01
NTUC Trade Union House
Singapore 189556

Attn : Mr Thio Tse Kiat

AJAX Inspection Services Pte Ltd
120 Lower Delta Road
#08-08, Cendex Centre
Singapore 169208
Tel: +65 6255 0808
Fax: +65 6849 9155
info@ajaxinspection.com

Invoice No - AV23382
Company Reg No - 201318067R
GST Reg No - 201318067R

TAX INVOICE

YOUR REF / CLAIM NUMBER : MT/1075097-001
OUR REF : AVS2019-21891/PN
TP VEHICLE NO : SKR3527C
CLAIM TYPE : PRE-REPAIR SURVEY
DATE OF SURVEY : 11 December 2019

No.	Description	Amount (\$S)
1	Professional fee	100.00
Subtotal		100.00
GST 7.00%		7.00
Total		107.00

Payment Terms: 30 days from date of invoice


Please remit by electronic transfer as follows:

Payee: AJAX Inspection Services Pte Ltd

United Overseas Bank Ltd

Account No: 450-309-276-4

Email remittance advice to: accounts@ajaxadjusters.com



AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R

AJAX

Inspection Services Pte Ltd

PRE-REPAIR SURVEY REPORT

NTUC Income Insurance Co-operative Ltd

73 Bras Basah Road #05-01 NTUC Trade Union House Singapore 189556

Attention: Mr Thio Tse Kiat

Assign Date:	10/12/2019	Survey Date:	11/12/2019	Adjustment Date:	11/02/2020
Accident Date:	06/12/2019	TP Policy No:	2100420355	Our Ref:	AVS2019-21891/PN
Place of Survey:	Sze Kang Automobile Spraying Services 10 Ang Mo Kio Industrial Park 2a, Autopoint #03-17 Singapore 568047			Your Ref:	MT/1075097-001
				Claim Type:	Third Party
				Claimant:	Goh Tze Kang Anthony

Description of Vehicle:

Veh. No:	SKR3527C	Make/Model:	Mercedes-Benz CLA180		
Colour:	Black	Engine No:	27091030498415	Sum Insured (S\$):	Market Value
Engine Capacity:	1595 cc	Chassis No:	WDD1173422N137418	Mkt Value (S\$):	\$75,000.00
Odometer:	109573	Reg. Date:	02/02/2015	Excess (S\$):	NA

Condition of Vehicle:

General:	Fair	Modification:	No	Steering:	Affected
Handbrake:	Affected	Footbrake:	Affected	Paint work:	Fair
Tyre Make:	Pirelli				
Front Tyre Size:	235/40R18	Front Left Side:	6mm	Front Right Side:	6mm
Rear Tyre Size:	235/40R18	Rear Left Side:	6mm	Rear Right Side:	6mm

Description of Damage:

The vehicle sustained damage on the front left portion.

Remarks:

Our recommended amount for the cost of contract lumpsum repair is S\$870.00 with approximately three (3) working days to complete. However, no finalisation was agreed with the repairer.

Special Remarks:

We did not conduct the post-repair survey as the repairer did not notify us.

Adjuster:

Patrick Ng
Motor Appraiser

Date

COMPLETED 12 FEB 2020

Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155

Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R

AJAX

Inspection Services Pte Ltd

Adjustment of Repair Cost for Vehicle: SKR3527C				Our Ref: AVS2019-21891/PN	
No.	Qty	Description of Parts	Condition	Third Party Surveyor's Estimate S\$	Our Recommendation S\$
List Items					
1	1	Front bumper	Repair	--	--
2	1	Front LH sport rim	Grazed	1,314.00	550.00
3	1	Front LH shock absorber	Not necessary	881.00	--
4	1	Front LH shock absorber top mounting	Not necessary	322.00	--
5	1	Front LH lower arm	Not necessary	592.00	--
6	1	Front LH knuckle arm	Not necessary	1,014.00	--
7	1	Front LH wheel hub & bearing	Not necessary	207.00	--
8	1	Front stabilizer bar	Not necessary	--	--
9	1	Front stabilizer bar LH link rod	Not necessary	84.00	--
10	1	Steering rock & pinion tie rod	Not necessary	189.00	--
Sub Total:				4,603.00	550.00
Discount (less 10%):				460.30	55.00
Total Parts Price:				4,142.70	495.00

Labour Cost			
1	To remove, jack out, striahten, panel beating, align and renew replaced parts.	500.00	400.00
2	To putty and respray painting on affected areas.	600.00	200.00
3	To remove, refix front LH damaged undercarriage.	250.00	--
4	To conduct computerise wheel alignment.	60.00	--
5	To supplied and applied anti rust treatment.	30.00	--
Sub Total:		1,440.00	600.00
Grand Total:		5,582.70	1,095.00

Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155

Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R