AJAX Inspection Services Pte Ltd

120 Lower Delta Road #08-08, Cendex Centre Singapore 169208 Tel: +65 6255 0808 Fax: +65 6849 9155

info@ajaxinspection.com

Invoice No - AV23345 Company Reg No -201318067R GST Reg No - 201318067R

Date : 11 February 2020

To : NTUC Income Insurance Co-operative Limited

73 Bras Basah Road #05-01 NTUC Trade Union House

Singapore 189556

Attn : Mr Thio Tse Kiat

TAX INVOICE

YOUR REF / CLAIM NUMBER : MT/1075097-001

OUR REF : AVS2019-21891/PN

TP VEHICLE NO : SKR3527C

CLAIM TYPE : PRE-REPAIR SURVEY

DATE OF SURVEY : 11 December 2019

No. Description Amount (S\$)

1 Professional fee 50.00

Subtotal 50.00 GST 7.00% 3.50 **Total 53.50**

Payment Terms: 30 days from date of invoice

Please remit by electronic transfer as follows:

Payee: AJAX Inspection Services Pte Ltd

United Overseas Bank Ltd Account No: 450-309-276-4

Email remittance advice to: accounts@ajaxadjusters.com





PRE-REPAIR SURVEY REPORT

NTUC Income Insurance Co-operative Ltd

73 Bras Basah Road #05-01 NTUC Trade Union House Singapore 189556

Attention: Mr Thio Tse Kiat

Assign Date:

10/12/2019

Survey Date:

11/12/2019

TP Report Date:

09/12/2019

Accident Date:

06/12/2019

TP Policy No:

2100420355

Our Ref:

AVS2019-21891/PN

Place of Survey:

Sze Kang Automobile Spraying Services

Your Ref:

MT/1075097-001

10 Ang Mo Kio Industrial Park 2a, Autopoint #03-17

Claim Type:

Third Party

Singapore

568047

Claimant:

Goh Tze Kang Anthony

Description of Vehicle:

Veh. No:

SKR3527C

Make/Model:

Mercedes-Benz CLA180

Colour: **Engine Capacity:** Black 1595 cc **Engine No:** Chassis No:

27091030498415 WDD1173422N137418

Sum Insured (S\$): Mkt Value (S\$):

Market Value

Odometer:

109573

Reg. Date:

02/02/2015

Excess (S\$):

\$75,000.00 NA

Condition of Vehicle:

General:

Fair

Modification:

No

Steering:

Affected

Handbrake:

Affected Footbrake: Affected

Paint work:

Fair

Tyre Make:

Pirelli

235/40R18 Front Left Side:

6mm

Front Right Side:

6mm

Front Tyre Size: Rear Tyre Size:

235/40R18

Rear Left Side:

6mm

Rear Right Side:

6mm

Description of Damage:

The vehicle sustained damage on the front left portion.

Remarks:

Based on visual survey of the vehicle without any repair estimate provided, we viewed that the repair cost should not be more than \$\$800.00 and could take approximately three (3) working days to complete.

Special Remarks:

We did not conduct the post-repair survey as the repairer did not notify us.

Adjuster:

Patrick Ng

Motor Appraiser

COMPLETED OF FEB 2020

Date

Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AIAX Inspection Services Pte Ltd

AJAX Inspection Services Pte Ltd


Our Ref:

AVS2019-21891/PN

Your Ref:

MT/1075097-001

Pre-repair survey



Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155 Email: info@ajaxinspection.com Website:www.ajaxadjusters.com Co. Reg. No.: 201318067R

AJAX Inspection Services Pte Ltd

Our Ref:

AVS2019-21891/PN

Your Ref:

MT/1075097-001


Pre-repair survey
Re-survey items













Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

AJAX Inspection Services Pte Ltd

Our Ref: AVS2019-21891/PN Your Ref: MT/1075097-001

Re-survey items



Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis. AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155 Email: info@ajaxinspection.com Website:www.ajaxadjusters.com Co. Reg. No.: 201318067R



Our Ref: Your Ref: AVS2019-21891/PN MT/1075097-001

Re-survey items









Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd