

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road, #16-00 Springleaf Tower  
Singapore 079909

**Our File No:** CS/CTI22003225/TQY3M4**Date:** 01/07/2022**REFERENCE**

Insured/Claimant: NICK LIM KAI SHENG Policy No: DMPCSNW00130222100

Date of Loss: 01/04/2022

Nature of Claim: OD

Claim No: SNM22D202255/C01/IRENE

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SMX3417G**  
 Make & Model: RENAULT SCENIC, 1.6 (A) Engine No: K9KF649D060231  
 Reg. Date: 16/01/2020 (Man. Year: 2019) Chassis No: VF1RFA00963212476  
 Colour: Grey Odometer: 34970 km  
 Engine Capacity: 1461 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

**CONDITION OF TYRES**

Front Tyre Size: 195/55 R20 Rear Tyre Size: 195/55 R20  
 Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm  
 Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	43,746.90	21,174.21	22,572.69	51.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	16,500.00	9,600.00	6,900.00	41.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>60,246.90</b>	<b>30,774.21</b>	<b>29,472.69</b>	<b>48.92</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>4,217.28</b>	<b>2,154.19</b>	<b>2,063.09</b>	<b>48.92</b>
<b>Nett Amount (S\$)</b>	<b>64,464.18</b>	<b>32,928.40</b>	<b>31,535.78</b>	<b>48.92</b>

**INSPECTION**

Date of Assignment: 07/04/2022

Date Inspected: 07/04/2022

Inspected At:

Wearnes automotive Pte Ltd (HQ)  
45 LENG KEE ROAD  
Singapore 159103

Estimated Period of Repair: 14.0 days

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**REPAIR DETAILS****Reference**

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 01 Jul 2022)
<b>Parts:</b> M1-MPV	RENAULT SCENIC 1.6 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SMX3417G)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*NUMBER PLATE & HOLDER	Not Necessary	60.00 F	*- F
2	1		*BUMPER FRT GS4	Deformed	1,457.30 F	*1,311.57 F
3	1		*BUMPER FRT TOW COVER	Not Necessary	117.00 F	*- F
4	1		*BUMPER FRT SUPPORT B	Not Necessary	132.90 F	*- F
5	1		*BUMPER UNDER COVER F	Not Necessary	617.80 F	*- F
6	1		*CONVERGENT AIR GUIDE	Not Necessary	300.90 F	*- F
7	1		*FOG LAMP FRT INNER B	Not Necessary	197.90 F	*- F
8	1		*BUMPER LOWER FRT GS4	Not Necessary	473.80 F	*- F
9	1		*BUMPER FRT CENTER IN	Not Necessary	239.10 F	*- F
10	1		*BUMPER FRT TOP INNER	Not Necessary	458.40 F	*- F
11	1		*FOG LAMP MOULDING OU	Deformed	261.40 F	*235.26 F
12	1		*FOG LAMP COVER CHORM	Cut	261.40 F	*235.26 F
13	2		*SUPPORT BRACKET, HEA	Not Necessary	251.20 F	*- F
14	1		*SUPPORT BRACKET, HEA	Not Necessary	125.60 F	*- F
15	10		*BUMPER MOULDING CLIP	Necessary	40.00 F	*36.00 F
16	1		*BUMPER BRACKET FRT R	Deformed	154.60 F	*139.14 F
17	1		*BUMPER BRACKET FRT L	Deformed	154.60 F	*139.14 F
18	1		*AIR INTAKE HOSE, BUM	Not Necessary	139.40 F	*- F
19	1		*AIR INTAKE GUIDE FRT	Not Necessary	165.30 F	*- F
20	1		*AIR FLAP GUIDE LOWER	Not Necessary	251.60 F	*- F
21	1		*BUMPER FRT TOP GRILL	Cut	473.80 F	*426.42 F
22	1		*GRILLA LINING PANEL	Not Necessary	346.80 F	*- F
23	1		*GRILLA TOP CHROMA ST	Not Necessary	231.60 F	*- F
24	1		*MLDG-GRILLE RAD, S4	Not Necessary	317.80 F	*- F
25	1		*LOGO FRT GRILLE GS4	Cracked	167.00 F	*150.30 F
26	1		*STICKER M4S	Necessary	17.50 F	*15.75 F
27	1		*LABEL TOP PANEL M4H	Necessary	8.80 F	*7.92 F
28	1		*LABEL-DIESEL EXH EMI	Necessary	8.80 F	*7.92 F
29	1		*WHEEL ARCH - FRT LH	Not Necessary	294.60 F	*- F
30	1		*WHEEL ARCH - FRT RH	Not Necessary	294.60 F	*- F
31	17		*WHEEL ARCH CLIP J5AL (20PCS)	Necessary	120.00 F	*91.80 F
32	1		*BONNET FRT GS4	Bent	1,348.00 F	*1,213.20 F
33	1		*BONNET INSULATE GS4	Not Necessary	315.70 F	*- F
34	1		*BONNET HINGE LH GS4	Not Necessary	134.30 F	*- F
35	1		*BONNET HINGE RH GS4	Not Necessary	134.30 F	*- F
36	2		*BONNET DAMPER L&R GS	Not Necessary	240.40 F	*- F
37	1		*BONNET LOCK GS4	Not Necessary	191.10 F	*- F
38	1		*BUMPER FRT REINFORCE	Not Necessary	744.40 F	*- F
39	1		*LOWER RADIATOR PANEL	Not Necessary	569.50 F	*- F
40	1		*GRILLA PANEL INNER A	Cracked	1,214.30 F	*1,092.87 F
41	1		*GRILLA PANEL INNER L	Not Necessary	92.10 F	*- F
42	1		*GRILLA PANEL INNER L	Not Necessary	93.10 F	*- F
43	2		*COOLANT 5 LTR	Necessary	48.40 F	*43.56 F
44	2		*GRILLA PANEL INNER T	Not Necessary	232.40 F	*- F
45	1		*BRACKET, FENDER FRT	Not Necessary	247.30 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
46	1		*BRACKET, FENDER FRT	Not Necessary	261.20 F	*- F
47	1		*FENDER BRACKET FRT L	Not Necessary	130.00 F	*- F
48	1		*BRACKET, FENDER FRT	Not Necessary	130.00 F	*- F
49	1		*RADIATOR AIR GUIDE F	Not Necessary	112.00 F	*- F
50	1		*AIR COOLER GUIDE AIR	Not Necessary	46.60 F	*- F
51	1		*FAN MOTOR GS4M4RS	Not Necessary	937.20 F	*- F
52	1		*AIR INTAKE FLAP GUID	Not Necessary	597.40 F	*- F
53	1		*A/C CONDENSER GS4 M4	Not Necessary	930.00 F	*- F
54	1		*RADIATOR S4 M4S GS4	Not Necessary	725.40 F	*- F
55	1		*AIR COOLER ASSY- GS4	Not Necessary	898.10 F	*- F
56	1		*HEADLAMP RH (PRIVILE	Cracked	1,877.70 F	*1,689.93 F
57	1		*HEADLAMP LH (PRIVILE	Not Necessary	1,877.70 F	*- F
58	1		*FOG LAMP-RH FRT CAP	Not Necessary	248.10 F	*- F
59	1		*FOG LAMP-LH FRT CAP	Not Necessary	248.10 F	*- F
60	1		*BUMPER HARNESS- FRT	Not Necessary	198.40 F	*- F
61	4		*PARK SENSOR BOTH CTR	Not Necessary	2,228.80 F	*- F
62	2		*BLIND SPOT SENSOR GS	Not Necessary	723.40 F	*- F
63	1		*DASHBOARD	Activated	3,674.90 F	*3,307.41 F
64	1		*DASHBOARD COVER GS4	Deformed	1,025.70 F	*923.13 F
65	1		**E* PASSENGER AIR BA	Activated	1,211.00 F	*1,089.90 F
66	1		**E* SEAT BELT FRT LH	Activated	743.40 F	*669.06 F
67	1		**E* SEAT BELT FRT RH	Activated	743.40 F	*669.06 F
68	1		**E* SEAT BELT TENSIO	Activated	210.90 F	*189.81 F
69	1		**E* SEAT BELT TENSIO	Activated	210.90 F	*189.81 F
70	1		*SEAT BELT BUCKLE FRT	Activated	263.50 F	*237.15 F
71	1		*SEAT BELT BUCKLE FRT	Activated	263.50 F	*237.15 F
72	1		**E* BELT-2ND ROW RH	Activated	743.40 F	*669.06 F
73	1		*BELT-2ND ROW LH	Activated	963.30 F	*866.97 F
74	1		*BELT-2ND ROW CTR	Activated	963.30 F	*866.97 F
75	1		*AIRBAG COMPUTER GS4	Activated	1,356.90 F	*1,221.21 F
76	1		**E* STEERING WHEEL A	Activated	1,148.80 F	*1,033.92 F
77	1		*ROTARY SWITCH GS4 KJ	Activated	429.90 F	*386.91 F
78	1		*GRILLA PANEL INNER A	Not Necessary	1,214.30 FS	*- FS
79	1		*BUMPER FRT SUPPORT B	Broken	132.90 FS	*119.61 FS
80	1		*BUMPER LOWER FRT GS4	Not Necessary	473.80 FS	*- FS
81	1		*BUMPER FRT CENTER IN	Broken	239.10 FS	*215.19 FS
82	1		*BUMPER FRT TOP INNER	Broken	458.40 FS	*412.56 FS
83	1		*GRILLA LINING PANEL	Broken	346.80 FS	*312.12 FS
84	1		*GRILLA TOP CHROMA ST	Not Necessary	231.60 FS	*- FS
85	1		*MLDG-GRILLE RAD, S4	Broken	317.80 FS	*286.02 FS
86	1		*BUMPER HARNESS- FRT	Torn	198.40 FS	*178.56 FS
87	1		*BONNET SAFETY HOOK G	Broken	75.10 FS	*67.59 FS
88	1		*RIVET G4, 8- M4S KJ*	Necessary	172.80 FS	*172.80 FS
			(30PCS)			
89	3		*WHEEL ARCH CLIP J5AL*	Necessary	16.20 FS	*16.20 FS

F=Franchise part. S=SpcNett.

<b>Total Parts (\$)</b>	<b>43,746.90</b>	<b>21,174.21</b>
-------------------------	------------------	------------------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REPLACE BONNET, FRT BUMPER, RADIATOR GRILLE, LOGO, HEADLAMP LH/RH, LOWER MESH GRILLE, SPOILER, ETC	New	1,650.00	1,100.00
2	TO SPRAY BONNET, FRT BUMPER, REINFORCEMENT, ETC	New	2,000.00	1,000.00
3	TO REPLACE FRONT SUPPORT PANEL ETC	New	2,200.00	1,650.00
4	TO VACUUM & TOP UP AIRCON GAS	New	600.00	600.00
5	TO REMOVE & REPLACE DASHBOARD, AIRBAG COMPONENTS, ETC	New	4,800.00	2,400.00
6	TO REPLACE SEAT BELT & SEAT BE BUCKLE FRONT & REAR	New	3,600.00	1,800.00
7	TO RESET AIRBAG MODULE SYSTEM	New	1,200.00	600.00
8	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	New	450.00	450.00
<b>Gross Labour Cost (\$)</b>			<b>16,500.00</b>	<b>9,600.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >