



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD  
300 BEACH ROAD  
#17-04/07 THE CONCOURSESINGAPORE 199555

Ref: CS/LPC22003231/Uty3n2

Date: 27/04/2022

Code: LPC2

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	YQ 1026J	<b>Veh. Inspected</b>	GBK 7603H
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	21/22/22/VC05/025639	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	GERALD POH	<b>Assign Date</b>	07/04/2022

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	TOYOTA HIACE (A)	<b>c.c</b>	2754
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2020
<b>Chassis No.</b>	GDH2012014439	<b>Colour</b>	WHITE
<b>Odometer</b>	45344 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	NIL
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	195/80 R15	BRIDGESTONE	7 mm
<b>L/H Front Tyre</b>	195/80 R15	BRIDGESTONE	7 mm
<b>R/H Rear Tyre</b>	195/80 R15	BRIDGESTONE	7 mm
<b>L/H Rear Tyre</b>	195/80 R15	BRIDGESTONE	7 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION AND REAR WINDSCREEN SHATTERED.  
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	05/04/2022	<b>Inspection Date</b>	07/04/2022
<b>Survey held at</b>	BLUWEL AUTOMOTIVE SERVICE PL BLK 1 KAKI BUKIT AVE 6 #01-28/53/55/56 (MAIN OFFICE) SINGAPORE 417883		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**