6/9/23, 9:05 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road, #16-00 Springleaf Tower

Our File No: CS/CTI22003234/VVY3Q2

Singapore 079909 **Date:** 09/06/2023

REFERENCE

Insured/Claimant: Singapore Civil Defence Force Policy No: DMCVSNW00138992101

Date of Loss: 21/03/2022 Nature of Claim: OD Claim No: SNM22D201968/C01/TANKL

65195534794285

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: QX1589J

Make & Model: MERCEDES-BENZ SPRINTER, 2.1 D 316 CDI Engine No:

(W906) (M)

Reg. Date: 14/03/2019 (Man. Year: 2018) Chassis No: WDB9066332P641425

Colour: White Odometer: 0 km

Engine Capacity: 2143 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/65 R16 Rear Tyre Size: 235/65 R16
Front Left Side: Michelin 5 mm Rear Left Side: Michelin 5 mm
Front Right Side: Michelin 5 mm Rear Right Side: Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		9,028.80	8,412.80	616.00	6.82
Miscellaneous Items		0.00	0.00	0.00	
Labour		800.00	540.00	260.00	32.50
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	9,828.80	8,952.80	876.00	8.91
	- Excess (S\$)	1,250.00	1,250.00	0.00	0.00
	(S\$)	8,578.80	7,702.80	876.00	10.21
	+ GST 8.00/8.00% (S\$)	686.30	616.22	70.08	10.21
	Nett Amount (S\$)	9,265.10	8,319.02	946.08	10.21

INSPECTION

Date of Assignment: 07/04/2022

Date Inspected: 08/04/2022 Inspected At: 10 DEFU LANE 8
Repairer:Indeco Engineers Pte Ltd (Defu)

Estimated Period of Repair: 5.0 days

Adjuster: Thevan Thomas Karthikesavan Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS \$\$616.00 NETT) 6/9/23, 9:05 AM Adjuster Report

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 08 Jun 2023)

Parts: N/A MERCEDES-BENZ SPRINTER 2.1 D 316 CDI (W906) (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for QX1589J)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER ASSEMBLY (WCP)	Scratched	1,320.00 F	*1,320.00 F
2	1		*FRONT GRILLE PANEL (WCP)	Dented	1,125.00 F	*1,125.00 F
3	1		*FRONT GRILLE APRON (WCP)	Cut	255.00 F	*255.00 F
4	1		*HEAD LAMP SUPPORT BRACKET (WCP)	*Check	560.00 F	*- F
5	1		*HEAD LAMP RH ASSEMBLY (WCP)	Cracked	1,854.00 F	*1,854.00 F
6	1		*HEAD LAMP LH ASSEMBLY (WCP)	Cracked	1,854.00 F	*1,854.00 F
7	1		*FRONT ENGINE HOOD (WCP)	Dented	840.00 F	*840.00 F
8	1		*STICKER & DECAL FOR ENGINE HOOD (WCP)	Necessary	400.00 F	*400.00 F
F=Fra	anchise	part.		Sub Total (S\$)	8,208.00	7,648.00
			+ Margin on L,N Items 10.00/10.00% (S\$)			764.80
				Total Parts (S\$)	9,028.80	8,412.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	REMOVE & REPLACE FRONT BUMPER	New	180.00	180.00
2	REMOVE & REPLACE FRONT GRILLE ,APRON PANEL & PLATE	& NUMBER New	180.00	100.00
3	REMOVE & REPLACE HEADLAMP & WIRING	New	80.00	30.00
4	REPLACE & SPRAY PAINT ENGINE HOOD	New	180.00	180.00
5	DETAILING FOR ENGINE HOOD STICKERS & DECALS	New	180.00	50.00
		Gross Labour Cost (S\$)	800.00	540.00
	Report was unsubmi	tted during this print-out.		

< END OF ESTIMATES >