



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 33P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT BUMPER	BUCKLED	1,417.44	1,417.44
1	FRONT BUMPER REINFORCEMENT	BUCKLED	569.72	569.72
1	RADIATOR GRILLE	CRACKED	814.17	814.17
1	FRONT BUMPER LOWER GRILLE CARRIER	SERVICEABLE	125.10	-
1	FRONT BUMPER INNER SPONGE ABSORBER	CRACKED	147.37	147.37
1	FRONT BUMPER SIDE SUPPORT BRACKET	TO REPAIR SEE LABOUR	57.83	-
1	FRONT BUMPER REINFORCEMENT BRACKET	TO REPAIR SEE LABOUR	305.34	-
1	FRONT BUMPER FOG LAMP GRILLE LH	SERVICEABLE	50.70	-
1	FRONT BONNET	BENT	2,473.44	2,473.44
1	BONNET HINGE LH	TO REPAIR SEE LABOUR	157.03	-
1	BONNET HINGE RH	TO REPAIR SEE LABOUR	157.03	-
1	FRONT HEADLAMP LH	CRACKED	3,501.15	3,501.15
1	HEADLAMP CONTROL UNIT	SERVICEABLE	1,013.59	-
1	FRONT HEADLAMP PANEL LH	TO REPAIR SEE LABOUR	275.80	-
	LESS 10% DISCOUNT		-1,106.57	-892.33
			9,959.14	8,030.96
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	100.00	60.00
1	SET FRONT BUMPER INNER FRAME CLIP LH (SN)	NOT NECESSARY	90.00	-
1	SET FRONT BUMPER INNER FRAME METAL CLIP LH (SN)	NOT NECESSARY	60.00	-
1	FRONT BUMPER CENTER AIR GRILLE CLIP (SN)	NOT NECESSARY	70.00	-
1	FRONT BUMPER RETAINER CLIP (SN)	NOT NECESSARY	80.00	-
1	FRONT BUMPER RIVET (SN)	NECESSARY	90.00	90.00
1	FRONT BUMPER FOG LAMP GRILLE CLIP (SN)	NOT NECESSARY	65.00	-
			555.00	150.00



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>LABOUR</b>			
	TO TRANSFER OF BUMPER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF FRONT BUMPER SIDE SUPPORT BRACKET, FRONT BUMPER REINFORCEMENT BRACKET, BONNET HINGE LH, BONNET HINGE RH AND FRONT HEADLAMP PANEL LH.		8,500.00	500.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		8,500.00	500.00
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	30.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO RUST-PROOFING OF THE AFFECTED AREAS.	REPEATED	170.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR.	NOT NECESSARY	380.00	-
			18,830.00	1,050.00
	<b>GRAND TOTAL</b>		<b>29,344.14</b>	<b>9,230.96</b>

<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>7,400.00</b>
---	--	--	-----------------

Report Ref No. CS/AGI22003242/Kty3n2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.