

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC4/ASM 22003244/40a3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

7

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

LYA 816172

Date:

Person Contacted:

B 399C

Vehicle: IN / OUT

Veh No:

GBE3882B

Yr Regn:

16/11/15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CM/

Make:

Toyota hiace

c.c

2982

Colour

white

A/C:

Insured / Std / NI / NA

Sp. Reading

25-3293

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

KDH 2010178162

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195-215

R:

Kapsen

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

OHTSU

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

04/04/22

D.O.I.

08/04/22

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear & Frt.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction dep / ok.

30/4/22 4/5 7550 informed Lema. R

Date/Time, File Pass to?

☐

: Preli. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I.: (\$

- Ashur

QUAN DE MOTOR TRADING

1 KAKI BUKIT AVENUE 6, #01-67
AUTOBAY, SINGAPORE 417883
HP: 96709191

not Authorised
Sale
8/4/22
2/c \$7550
7 days.

AXA Insurance Pte Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811
Attn: Motor Claims Department

Date: 8 April 2022

**Accident on 04/04/2022 involving vehicles GBE3882B, SGQ8688R,
SLM9767B along Pasir Ris Drive 6**

Estimate cost of repair to vehicle GBE3882B Toyota Hiace Van

1 pc.	tailgate	Body	\$	1,988.10	✓
1 pc.	tailgate inner lock	to / Ten	\$	398.50	✓
1 pc.	tailgate weatherstrip	twi	\$	361.20	✓
1 pc.	tailgate inner trim board	to / n	\$	315.10	✓
1 pc.	tailgate lock outer cover	Nf	\$	105.00	X
1 pc.	tailgate rear logo	neu	\$	68.50	✓
1 pc.	rear bumper	Dis	\$	651.10	✓
1 pc.	rear bumper step bracket	sent	\$	231.00	✓
2 pcs.	rear bumper side holders @\$69.00	one	\$	138.00	✓
4 pcs.	rear bumper lower brackets @\$25.00	sent	\$	100.00	✓
1 pc.	rear end panel outer	Body	\$	645.20	✓
1 pc.	rear end panel inner	Body	\$	801.10	✓
2 pcs.	taillamps @\$366.00	N/S cra o/s n n	\$	732.00	12 C
2 pcs.	taillamp lower garnishes @\$145.00	N/S twi o/s n n	\$	290.00	12 C
2 pcs.	taillamp housing panels @\$485.00	N/S RD o/s R	\$	970.00	12 C
1 pc.	rear end panel top steel plate	sent	\$	182.30	✓
1 pc.	rear spare tyre bracket	sent	\$	345.20	✓
1 pc.	rear lock actuator	shorted / Daye	\$	288.50	✓
1 pc.	front bumper	to / to / n	\$	688.50	✓
1 pc.	front bumper beam	R	\$	408.50	X
			\$	9,707.80	
			Less 25%	\$	2,426.95
				\$	7,280.85

S. Nett Items:

1 pc.	front licence plate	one	\$	45.00	20
1 set	front bumper clips	neu	\$	50.00	✓
1 set	rear bumper clips	neu	\$	50.00	✓
1 set	tailgate inner trim board clips	neu	\$	50.00	✓
1 set	rear bumper reverse sensor	shorted	\$	280.00	200
1 pc.	rear end panel sealant	neu	\$	50.00	✓
1 pc.	tailgate "70km/h" & 8 pax sticker	n n	\$	30.00	X
1 pc.	rear windscreen sealant	neu	\$	50.00	40

Sub-total \$ 7,885.85

Bal c/f \$ 7,885.85

Labour Charges:

To check wiring	\$ 50.00	30
To remove & refix rear windscreen	\$ 140.00	120
To remove & refix tailgate mechanism	\$ 100.00	60
To spray rust proofing	\$ 100.00	90
To remove & refix reverse sensor	\$ 100.00	50
Labour for panel beating, welding and renew parts	\$ 1,600.00	1300
Spray painting	\$ 1,800.00	1200

Total: \$ 11,775.85

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P-8198.30
 25%
 P-6148.72
 S.N-460
 L-2850
 9458.15
 202
 7566.