

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SML 5533D

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	DEFORMED / TORN	2,171.00	2,171.00
1	FRONT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	652.00	-
1	FRONT BUMPER INNER BRACKET O/S	CRACKED	121.00	121.00
1	FRONT BUMPER FOG LAMP O/S	CRACKED	292.00	292.00
1	FRONT BUMPER FOG LAMP GARNISH O/S	TWISTED	90.00	90.00
1	FRONT BUMPER PDC SENSOR O/S	NOT NECESSARY	185.00	-
1	FRONT BUMPER LOWER UNDER COVER	TORN	288.00	288.00
1	SET FRONT BUMPER LOWER UNDER COVER CLIPS	NECESSARY	50.00	50.00
1	FRONT BUMPER INNER NOZZLE O/S	CRACKED	172.00	172.00
1	SET FRONT BUMPER CLIPS	NECESSARY	50.00	50.00
1	HEADLAMP O/S	CRACKED	2,498.00	2,498.00
1	FRONT FENDER O/S	TO REPAIR SEE LABOUR	685.00	-
1	FRONT SUPPORT PANEL	TO REPAIR SEE LABOUR	566.00	-
1	SET FRONT BUMPER LOWER BLACK STICKER	NECESSARY	180.00	180.00
	LESS 10% DISCOUNT		-800.00	-591.20
			7,200.00	5,320.80
	<u>LABOUR</u>			
	TO CHECK WIRING.		50.00	20.00
	TO DISMANTLE & REPLACED FRONT PDC SENSOR.		80.00	50.00
	TO RESET & DIAGNOSTIC SYSTEM.		150.00	60.00
	TO SPRAY RUST PROOFING.	NOT NECESSARY	50.00	-
	LABOUR FOR PANEL BEATING & REPLACED PARTS.INCLUSIVE OF THE REPAIR OF FRONT BUMPER REINFORCEMENT,FRONT FENDER O/S AND FRONT SUPPORT PANEL.		600.00	400.00
	TO PUTTY & SPRAY PAINTING.		880.00	400.00
			1,810.00	930.00
	GRAND TOTAL		9,010.00	6,250.80

Report Ref No. CS/AGI22003245/Uty3n2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		5,000.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/AGI22003245/Uty3n2

CHUA KANG SENG

Licensed Appraiser