



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FX 898D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	HONDA FRONT SUSPENSION (LEFT)	SERVICEABLE	480.00	-
1	HONDA FRONT SUSPENSION (RIGHT)	SERVICEABLE	480.00	-
1	HONDE TRIPLE CLAMP (TOP)	SERVICEABLE	250.00	-
1	HONDA TRIPLE CLAMP (BOTTOM)	SERVICEABLE	350.00	-
1	HONDA STEERING CONE	SERVICEABLE	110.00	-
1	HONDA FRONT MUDGUARD	GRAZED	180.00	48.00
1	HONDA REAR MUDGUARD	TO REPAIR SEE LABOUR	180.00	-
1	HONDA FRONT HEADLIGHT	CRACKED	280.00	110.00
1	HONDA FRONT HEADLIGHT BULB	SERVICEABLE	20.00	-
1	HONDA FUEL TANK	DENTED / GRAZED	450.00	450.00
1	HONDA HANDLE BAR	BENT	140.00	45.00
1	SET HONDA HANDLE BAR BALANCER	GRAZED	120.00	-
2	HONDA HANDLE BAR CLAMP	TO REPAIR SEE LABOUR	90.00	-
1	HONDA SIDE CHROME COVER-LEFT (BELOW FUEL TANK)	GRAZED	80.00	38.00
1	HONDA METER COVER	DENTED	50.00	50.00
1	HONDA SIDE MIDDLE CHROME COVER WITH HONDA WORDING-LEFT	GRAZED	115.00	42.00
1	HONDA CHAIN SLIDER	SERVICEABLE	35.00	-
1	HONDA GEAR SHIFTER ARM	SERVICEABLE	25.00	-
1	HONDA GEAR SHIFTER RUBBER	SERVICEABLE	10.00	-
1	HONDA GEAR SHIFTER PEDAL	GRAZED / BENT	45.00	45.00
1	HONDA GEAR SHIFTER TIE ROD	SERVICEABLE	20.00	-
1	HONDA THROTTLE TUBE	SERVICEABLE	35.00	-
1	HONA THROTTLE CABLE	SERVICEABLE	40.00	-
1	HONDA METER GEAR	SERVICEABLE	110.00	-
1	HONDA METER CABLE	SERVICEABLE	60.00	-
1	HONDA CLUTCH LEVER	GRAZED	40.00	18.00
1	HONDA CLUTCH LEVER HOLDER PIN	SERVICEABLE	10.00	-
1	HONDA CLUTCH LEVER HOLDER	SERVICEABLE	55.00	-

Report Ref No. CS3/ASM21002655/Gvy3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	HONDA CLUTCH CABLE LENGTH ADJUSTER	SERVICEABLE	10.00	-
1	HONDA CLUTCH CABLE	SERVICEABLE	45.00	-
2	HONDA FRONT SIGNAL LIGHTS	BROKEN / GRAZED (1PC ONLY)	130.00	48.00
1	HONDA REAR SIGNAL LIGHT-LEFT	BROKEN	65.00	65.00
1	HONDA FRONT BRAKE MASTER CYLINDER	SERVICEABLE	280.00	-
1	HONDA FRONT BRAKE LEVER	SERVICEABLE	50.00	-
1	HONDA FRONT BRAKE HOSE	SERVICEABLE	95.00	-
1	HONDA FRONT BRAKE DISC	TO REPAIR SEE LABOUR	120.00	-
1	HONDA ENGINE COVER-LEFT	SERVICEABLE	95.00	-
1	HONDA EXHAUST MUFFLER	SERVICEABLE	450.00	-
1	HONDA SIDE STAND	SERVICEABLE	85.00	-
1	HONDA REAR BRAKE PEDAL	SERVICEABLE	75.00	-
1	HONDA REAR SWINGARM	SERVICEABLE	680.00	-
1	HONDA REAR SWINGARM SHAFT	TO REPAIR SEE LABOUR	180.00	-
1	HONDA REAR SWINGARM BUSHING BEARING	SERVICEABLE	180.00	-
2	HONDA REAR SUSPENSIONS	DENTED / BENT (1PC ONLY)	760.00	210.00
1	HONDA PILLION HOLDER (BACKREST)	SERVICEABLE	80.00	-
2	HONDA MIRRORS	GRAZED (1PC ONLY)	130.00	28.00
1	HONDA RIDER FOOTREST BRACKET-LEFT (STEP BAR)	SERVICEABLE	120.00	-
2	HONDA RIDER FOOTRESTS	DENTED / GRAZED (1PC ONLY)	120.00	45.00
2	HONDA RIDER FOOTREST PINS	SERVICEABLE	20.00	-
2	HONDA RIDER FOOTREST SPRINGS	SERVICEABLE	30.00	-
1	HONDA REAR SIGNAL HOLDER-LEFT	SERVICEABLE	65.00	-
1	HONDA PILLION FOOTREST BRACKET-LEFT	SERVICEABLE	85.00	-
1	HONDA PILLION FOOTREST-RIGHT	SERVICEABLE	50.00	-
1	HONDA PILLION FOOTREST-LEFT	MISSING	50.00	50.00
2	HONDA PILLION FOOTREST PINS	SERVICEABLE	30.00	-
2	HONDA PILLION FOOTREST BEARINGS	SERVICEABLE	20.00	-
1	HONDA REAR NUMBER PLATE HOLDER	SERVICEABLE	120.00	-

Report Ref No. CS3/ASM21002655/Gvy3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	HONDA REAR NUMBER PLATE LIGHT ASSEMBLY	SERVICEABLE	80.00	-
	LESS 10% DISCOUNT		-	-129.20
			8,160.00	1,162.80
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT NUMBER PLATE (SN)	BENT / CRACKED	15.00	15.00
1	REAR NUMBER PLATE (SN)	BENT	20.00	20.00
1	SET PLAYLIFE GRIP (SN)	SERVICEABLE	35.00	-
1	IU BRACKET (SN)	SERVICEABLE	20.00	-
1	IU UNIT (SN)	BROKEN	175.00	156.00
1	REAR BOX (SN)	GRAZED	180.00	180.00
1	REAR BOX BASE PLATE (SN)	SERVICEABLE	85.00	-
1	REAR BOX RACK (SN)	SERVICEABLE	120.00	-
1	SEAT (USED) (SN)	SERVICEABLE	80.00	-
			730.00	371.00
	<u>LABOUR</u>			
	TO REMOVE & REPLACE FRONT SUSPENSION, AXLE SHAFT, TRIPPLE CLAMPS, STEERING CONE, REAR SHOCK ABSORBER, SWING ARM ETC.		300.00	100.00
	TO REMOVE & REPLACE ABOVE BODY DAMAGED PARTS, CHECK WIRING & LIGHTING SYSTEM. INCLUSIVE OF THE REPAIR OF HONDA REAR MUDGUARD, HONDA HANDLE BAR CLAMP, HONDA FRONT BRAKE DISC AND HONDA REAR SWINGARM SHAFT.		550.00	200.00
	TO CONDUCT CHASSIS ALIGNMENT.	NOT NECESSARY	480.00	-
	TOWING-WORKSHOP TO ACCIDENT REPORTING CENTER.		60.00	25.00
	TOWONG-ACCIDENT REPORTING CENTER TO WORKSHOP.		60.00	25.00
			1,450.00	350.00
GRAND TOTAL			10,340.00	1,883.80



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,500.00
---------------------------------------------------------------------------------	--	--	-----------------

Report Ref No. CS3/ASM21002655/Gvy3e2-1

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.