

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 4338J**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT BUMPER	TO REPAIR SEE LABOUR	481.10	-
10	FRONT BUMPER CLIPS @ \$2.20	NECESSARY	22.00	22.00
1	FRONT BUMPER UPPER MOULDING	SCRATCHED	368.50	368.50
1	RADIATOR GRILLE	SCRATCHED	1,409.10	1,409.10
1	HEADLAMP RH	SERVICEABLE	2,110.30	-
1	DAYLIGHT RH	SERVICEABLE	642.50	-
1	DAYLIGHT GRILLE RH	SCRATCHED	93.45	93.45
	LESS 20% DISCOUNT		-1,025.39	-378.61
			<b>4,101.56</b>	<b>1,514.44</b>
<b><u>LABOUR</u></b>				
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRONT BUMPER.		400.00	350.00
	SPRAY PAINTING.		300.00	250.00
	CHECK WIRINGS.		40.00	20.00
			<b>740.00</b>	<b>620.00</b>
<b>GRAND TOTAL</b>			<b>4,841.56</b>	<b>2,134.44</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>				<b>1,700.00</b>

Report Ref No. NS/INC22003246/Vvcn2



**THEVAN THOMAS KARTHIKESAVAN**



**K.K.LAU CPT(RET)**

**BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE**

**REGD Auto Consultant-SAE, Licensed Appraiser**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.**

**No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.**