

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 406M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	CUT	459.40	459.40
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	394.80	-
2	REAR BUMPER REINFORCEMENT BRACKET LH/RH @ \$138.10	SERVICEABLE	276.20	-
1	REAR BUMPER CENTRE MOULDING	CUT	451.25	451.25
1	REAR BUMPER LOWER CENTRE MOULDING	SERVICEABLE	155.00	-
10	REAR BUMPER COVER CLIPS @\$2.20	NECESSARY	22.00	22.00
1	REAR BUMPER TOW COVER	SERVICEABLE	98.80	-
1	REAR FOGLAMP	SERVICEABLE	201.50	-
	LESS 20% DISCOUNT		-411.79	-186.53
			1,647.16	746.12
	NETT ITEMS			
1	REVERSE SENSORS (N)	SERVICEABLE	180.00	-
1	REAR NO.PLATE WITH TRIM COVER (N)	CRACKED	55.00	55.00
	LESS 10% DISCOUNT		-23.50	-5.50
			211.50	49.50
	SPECIAL NETT ITEMS			
2	REAR FENDER ADV.STICKER RH/LH @\$100 (SN)	NECESSARY	200.00	200.00
1	REAR BUMPER MAT (SN)	NECESSARY	50.00	50.00
			250.00	250.00
	<u>LABOUR</u>			
	PANEL BEATING.		400.00	350.00
	SPRAY PAINTING CHARGE.		300.00	250.00
	REMOVE/REFIX REVERSE SENSOR.		120.00	30.00
			820.00	630.00
	GRAND TOTAL		2,928.66	1,675.62





Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		1,350.00
(TO ITS PRE-ACCIDENT CONDITION)		·
(CONFIRMED)		

Report Ref No. NS/INC22003247/Vqcn2



THEVAN THOMAS KARTHIKESAVAN



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

**REGD Auto Consultant-SAE, Licensed Appraiser**