

Our Job Ref No : 305511505
Date : 11.04.22

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK
Attn : THEVAN


Fax :

Vehicle Reg No. : SHA 406M

Date of Accident : 05.04.22

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC --- FBH8995K
2. The finalized amount shall be:
 - (a) Spare Parts after List discount
 - (b) Labour Charges (include advertisement stickers etc, if any)
 - Total for Part-By-Part Repair Cost**
 - (c.) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20% \$1,350.00
Final Lumpsum Repair cost \$1,350.00
3. Estimated normal period for repairs: 2 working days.
4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days
5. Thank you for your assistance. We confirm the estimates and finalized amount

Signature : 
Name : LIM T S
Tel : 62148398
Fax : 65468156

Signature : 
Name : THEVAN
Date : 21/4/22

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	---	N		
3. Survey Fees	-----	--		
4. LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Effective Date: 1 Nov 2020

DATE: 20-Jan-22MODEL: Hyundai IoniqINSURANCE: NTUC CLSVEHICLE NO.: SHA 406M - CityCabMVA: LIMITS

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT	
	Rear Bumper	1		\$ 459.40	cut
	Rear Bumper Reinforcement	1		\$ 394.80	X Svc
	Rear Bumper Reinforcement Bracket LH/RH	2	\$ 138.10	\$ 276.20	X Svc
	Rear Bumper Centre Moulding	1		\$ 451.25	cut
	Rear Bumper Lower Centre Moulding	1		\$ 155.00	X Svc
	Rear Bumper Cover Clips	10	\$ 2.20	\$ 22.00	Nic
	Rear Bumper Tow Cover	1		\$ 98.80	X Svc
	Rear Foglamp	1		\$ 201.50	X Svc
	SUB TOTAL			\$ 2,058.95	
	LESS 20%			\$ 411.79	
	DISCOUNTED TOTAL			\$ 1,647.16	
	Reverse Sensors	1		\$ 180.00	X Svc
	Rear No. Plate With Trim Cover	1		\$ 55.00	Crn
	S/NETT SUB			\$ 235.00	
	LESS 10%			\$ 23.50	
	S/NETT TOTAL			\$ 211.50	
	Rear Fender Adv. Sticker RH/LH	2	\$ 100.00	\$ 200.00	Nett / Nic
	Rear Bumper Mat	1		\$ 50.00	Nett / Nic
	SPARE PARTS TOTAL			\$ 2,108.66	
	Labour Charge				
	Panel Beating			\$ 400.00	350
	Spray Painting Charge			\$ 300.00	250
	Remove/Refix Reverse Sensor			\$ 120.00	30
	TOTAL LABOUR			\$ 820.00	
	ESTIMATE TOTAL			\$ 2,928.66	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Thavan

82235769

6/4/22 1700

4/5 repair delays w/p