

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22003249/EVY3E2

Date: 05/07/2022

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00004052203		
Claimant Vehicle No :	SLL6938A	Insured Vehicle No :	GBJ886J		
Date of Loss:	07/04/2022	Nature of Claim:	TP	Claim No:	SNM22D202378/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLL6938A	Engine No:	F175K712B48B20A
Make & Model:	BMW X3, 2.0 SDRIVE 20I ADAPTIVE HL LED FL (A)	Chassis No:	WBATS720X09G94401
Reg. Date:	27/09/2021 (Man. Year: 2021)	Odometer:	9953 km
Colour:	White		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/50 R19	Rear Tyre Size:	245/50 R19
Front Left Side:	Bridgestone 4 mm	Rear Left Side:	Bridgestone 4 mm
Front Right Side:	Bridgestone 4 mm	Rear Right Side:	Bridgestone 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,613.70	3,826.80	786.90	17.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,765.00	2,429.00	1,336.00	35.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,378.70	6,255.80	2,122.90	25.34
+ GST 7.00/7.00% (S\$)	586.51	437.91	148.60	25.34
Nett Amount (S\$)	8,965.21	6,693.71	2,271.50	25.34

INSPECTION

Date of Assignment:	08/04/2022	Performance Motors Limited (Alexandra)
Date Inspected:	22/04/2022 Inspected At:	303 Alexandra Road, Sime Darby Performance Centre
Estimated Period of Repair:	4.0 days	Singapore 159941

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Jul 2022)
Parts:	M1-SUV	BMW X3 2.0 SDRIVE 20I ADAPTIVE HL LED FL (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLL6938A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*80.00 FS
2	1		*FRT LH DOOR MOULDING (X LINE)	Not Necessary	182.35 FS	*- FS
3	1		*LH SUPPORTING RING (SHADOW LINE)	Not Necessary	70.45 FS	*- FS
4	1		*LH LOWER HOUSING SECTION (SHADOW LI	Not Necessary	75.35 FS	*- FS
5	1		*LH HEATED OUTSIDE MIRROR MEMORY BUS	Broken	1,276.05 FS	*1,276.05 FS
6	1		*LH COVER CAP PRIMED	Missing	179.35 FS	*179.35 FS
7	1		*LH MIRROR GLASS HEATED WIDE ANGLE	Broken	416.95 FS	*416.95 FS
8	1		*FRT LH DOOR SIDE WINDOW GLASS	Not Necessary	306.65 FS	*- FS
9	1		*FRT LH DOOR SHAFT COVER (ALU)	Cut	161.10 FS	*161.10 FS
10	1		*LH AUXILIARY TURN INDICATOR MIRROR	Not Necessary	82.10 FS	*- FS
11	1		*FRT LH DOOR	Dented	1,545.85 FS	*1,545.85 FS
12	1		*(S/L) DOOR WEATHERSTRIP	Necessary	167.50 FS	*167.50 FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					4,613.70	3,826.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE LEFT FRONT SIDE MIRROR ASSEMBLY, LEFT DOOR FRONT WINDOW GLASS INCLUDE REMOVE ATTACHMENT ETC TO CARRY OUT NECESSARY REPAIRS	New	2,125.00	1,275.00
2	PAINTING FRONT LEFT DOOR	New	1,038.00	986.00
3	TO CONDUCT CHECK ON ALL DOORS AND BOOTLID CENTRAL LOCKING SYSTEM FOR PROPER FUNCTION	New	177.00	168.00
4	TO SUPPLY AND INSTALL FRONT LEFT WINDOW GLASS SOLAR FILM	New	425.00	0.00
Gross Labour Cost (\$\$)			3,765.00	2,429.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >