

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

HL Assurance Pte Ltd
11 Keppel Road, #11-01 ABI Plaza
Singapore 089057

Our File No: CS/HLA22003267/KNY3E2

Date: 18/08/2022

REFERENCE

Insured/Claimant: TAN TECK TUAN VINCENT Policy No: MP309831
Date of Loss: 02/04/2022 Nature of Claim: OD Claim No: MPC03281/ANA

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLC7052X**
Make & Model: NISSAN NOTE, 1.2 CVT ABS D/AIRBAG 2WD 5DR DIG-S (A) Engine No: HR12185733B
Reg. Date: 24/05/2016 (Man. Year: 2016) Chassis No: JN1TAAE12Z0972272
Colour: Metallic Grey Odometer: 97309 km
Engine Capacity: 1198 cc
Market Value/New Car Price: S\$44,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/65 R15 Rear Tyre Size: 185/65 R15
Front Left Side: Yokohama 9 mm Rear Left Side: Yokohama 8 mm
Front Right Side: Yokohama 9 mm Rear Right Side: Yokohama 8 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,710.70	2,154.70	1,556.00	41.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,050.00	1,300.00	750.00	36.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,760.70	3,454.70	2,306.00	40.03
Approved Total (Overridden) (S\$)		2,750.00		
- Excess (S\$)	0.00	250.00	-250.00	
(S\$)	5,760.70	2,500.00	3,260.70	56.60
+ GST 0.00/7.00% (S\$)	0.00	175.00	-175.00	
Nett Amount (S\$)	5,760.70	2,675.00	3,085.70	53.56

INSPECTION

Date of Assignment: 08/04/2022 Present Location: Chew Goon Motor (AMK)
Chew Goon Motor (AMK)
Date Inspected: 08/04/2022 Inspected At: Blk 10 Ang Mo Kio Industrial Park 2A, #01-15/16 & 17, AMK Autopoint
Singapore 568047
Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Aug 2022)
Parts:	144	NISSAN NOTE 1.2 CVT ABS D/AIRBAG 2WD 5DR DIG-S (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's (Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SLC7052X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Front Bumper (WCP)	Bent	250.00 F	*250.00 F
2	12		*Front Bumper Clips (WCP)	Necessary	24.00 F	*24.00 F
3	1		*Front Bumper Bracket (WCP)	Repair	150.00 F	*- F
4	1		*Front Bumper Top Retainers (WCP)	N/S Cracked	40.00 F	*20.00 F
5	1		*Front Bumper Top Reinforcement (50%)	Bent	185.00 F	*92.50 FS
6	2		*Front Bumper Corner Retainers (WCP)	N/S Distorted	50.00 F	*50.00 F
7	1		*Front Bumper Top Nose Panel (WCP)	Buckled	135.00 F	*135.00 F
8	1		*Front Bumper Sponge (WCP)	Cracked	120.00 F	*120.00 F
9	1		*Grille (WCP)	Mtg Cracked	155.00 F	*155.00 F
10	1		*Grille Emblem (WCP)	Necessary	45.00 F	*45.00 F
11	2		*Headlamp Assy (WCP)	Mtg Cracked	700.00 F	*700.00 F
12	1		*Front Fender LH (WCP)	Bent	265.00 F	*265.00 F
13	1		*Front Fender Shield (WCP)	Cracked	65.00 F	*65.00 F
14	1		*Front Fender Quart Glass Moulding (WCP)	Serviceable	185.00 F	*- F
15	1		*Support Panel (WCP)	Repair	250.00 F	*- F
16	1		*Radiator (WCP)	Serviceable	400.00 F	*- F
17	1		*Radiator Expansion Tank (WCP)	Dented	65.00 F	*65.00 F
18	1		*Air Con Condenser (WCP)	Serviceable	380.00 F	*- F
19	1		*Air Con Condenser Side Air Guide LH (WCP)	Cracked	35.00 F	*35.00 F
20	1		*Air Con Condenser Lower Air Guide LH (WCP)	Cracked	35.00 F	*35.00 F

F=Franchise part. S=SpcNett.

Sub Total (S\$)	3,534.00	2,056.50
+ Margin on L,N Items 5.00/5.00% (S\$)	176.70	98.20
Total Parts (S\$)	3,710.70	2,154.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	To Conduct Electrical Check, Focus Headlamp	New	30.00	20.00
2	To Remove / Refit Air Con Condenser & Refill Air Con Gas	New	120.00	0.00
3	To Conduct Computerize Wheel Alignmant Test	New	80.00	60.00
4	To Provide Transpotation (Towing)	New	120.00	0.00
5	Labour Charge - Penel Beating, Repairing of Bonnet, Front Chassis Member, Front RH Fender, LH Fender Inner Panel etc. Cnt, Weld Support & Part Replacement	New	800.00	500.00
6	To Respray Affected Areas	New	900.00	720.00
Gross Labour Cost (\$\$)			2,050.00	1,300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >