

趙源摩哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: HL Assurance Pte Ltd

Accident Date : 02.04.2022

Not Authorised
11pm @ 2750h
Penny Alan Paim
Ex @ 250h

5day

Policy No: MP309831

Date: 07.04.2022

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost Of Repair To "Nissan Note" Reg. No SLC7052X		
1pc	Front Bumper		250.00
12pcs	Front Bumper Clips	2.00	24.00
1pc	Front Bumper Bracket		150.00
2pcs	Front Bumper Top Retainers	20.00	40.00
1pc	Front Bumper Reinforcement	92.50	185.00
2pcs	Front Bumper Corner Retainers	25.00	50.00
1pc	Front Bumper Top Nose Panel		135.00
1pc	Front Bumper Sponge		120.00
1pc	Grille		55.00
1pc	Grille Emblem		45.00
2pcs	Headlamp Assy	350.00	700.00
1pc	Front Fender LH		265.00
1pc	Front Fender Shield		65.00
1pc	Front Fender Quart Glass Moulding		185.00
1pc	Support Panel		250.00
1pc	Radiator		400.00
1pc	Radiator Expansion Tank		65.00
1pc	Air Con Condenser		380.00
1pc	Air Con Condenser Side Air Guide LH		35.00
1pc	Air Con Condenser Lower Air Guide		35.00
	Cost Plus 5%		3,534.00
			176.70
			3,710.70
	To Conduct Electrical Check, Focus Headlamp		30.00
	To Remove / Refit Air Con Condenser & Refill Air Con Gas		120.00
	To Conduct Computerize Wheel Alignment Test		80.00
	To Provide Transportation (Towing)		120.00
	Labour Charge - Panel Beating, Repairing of Bonnet, Front Chassis Member, Front RH Fender, LH Fender Inner Panel etc.Cnt, Weld Support & Part Replacement		800.00
	To Respray Affected Areas		900.00
	Total :		5,760.70