

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG22003273/GPA3Q2**Date:** 11/10/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070161710
Claimant Vehicle No :	SHB1169K	Insured Vehicle No :	SMA1181U
Date of Loss:	10/04/2022	Nature of Claim:	TP
		Claim No:	3928882131SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB1169K		
Make & Model:	M.G. MG5, EV EXCITE T (M)	Engine No:	HIDDEN
Reg. Date:	16/09/2021 (Man. Year: 2021)	Chassis No:	LSJE24038MG051341
Colour:	Green	Odometer:	39764 km
Engine Capacity:	0 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Sincera 6 mm	Rear Left Side:	Sincera 6 mm
Front Right Side:	Sincera 6 mm	Rear Right Side:	Sincera 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,581.38	207.61	2,373.77	91.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,738.00	760.00	1,978.00	72.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	5,319.38	967.61	4,351.77	81.81
+ Loss of Use (2.5 x S\$50.00/day) (S\$)		125.00		
+ Car Rental (2.5 x S\$108.07/day) (S\$)		270.18		
	Nett Liability (S\$)	1,362.79		
	Global Sum Settlement (S\$)	1,360.00		

INSPECTION

Date of Assignment:	12/04/2022	
Date Inspected:	12/04/2022	Inspected At: Strides Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705
Estimated Period of Repair:	2.0 days	

Adjuster: XING GUO QIANG**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FASCIA -RR BPR LWR (DISC 10%)	Cut	230.68 F	*207.61 F
2	1		*FASCIA-RR BPR	Repair	758.47 F	*- F
3	1		*FINISHER -RR BPR ,RH	Not Necessary	47.42 F	*- F
4	1		*FINISHER -RR BPR ,LH	Not Necessary	47.42 F	*- F
5	1		*BRACKET ASM -RR BPR FASCIA SI -RH	Not Necessary	29.84 F	*- F
6	1		*BRACKET ASM -RR BPR FASCIA SI -L	Not Necessary	29.85 F	*- F
7	1		*BRACKET -RR BPR FASCIA MTG	Not Necessary	46.07 F	*- F
8	1		*BRACKET -RR BPR FASCIA MTG	Not Necessary	46.07 F	*- F
9	1		*BAR ASM -RR BPR IMP	Not Necessary	339.76 F	*- F
10	1		*COVER -RR TOW HOOK OPG	Not Necessary	6.76 F	*- F
11	1		*SENSOR -RR PARK DIST CONT	Not Necessary	65.00 F	*- F
12	1		*LAMP ASM -RR FOG -RH	Not Necessary	189.08 F	*- F
13	1		*LAMP ASM -RR FOG -LH	Not Necessary	36.30 F	*- F
14	1		*PANEL ASM -RR END	Not Necessary	708.66 F	*- F
F=Franchise part.						
					Total Parts (S\$)	2,581.38 207.61

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODY WORK	New	1,200.00	200.00
2	SPRAY PAINT	New	658.00	220.00
3	TO WASH AND VACUUM	New	60.00	0.00
4	TO REPLACE SUNDRY PARTS	New	100.00	0.00
5	TO APPLY RUST-PROOFING ON AFFECTED AREA	New	100.00	0.00
6	TO CHECK & RESET SYSTEM FUNCTION	New	350.00	150.00
7	ISOLATED OF (EV)	New	150.00	150.00
8	TO TEST AND REFIX REVERSE SENSOR SYSTEM	New	120.00	40.00
Gross Labour Cost (\$)			2,738.00	760.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >