

ASS. REC. BY:

REF:

LPC/22003274/KC

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SMH 7091K Regn: 01, 19Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Fit c.c. 1317Colour: Black A/C: Insured / Std / NI / NASp. Reading: 222822 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: GP5 1336962Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: M11 / S/Rim / STD A/Rim orTyre Size: F: 185/60R15R: ArivoBS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal. 8 mmL/Bal. 8 mmD.O.A. 8/4/22

Survey held at _____

Rear

R/Bal. 4 mmL/Bal. 4 mmD.O.I. 11/4/2022Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop orN/S body

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

18/4/22 21:20 26501 Cash

Date/Time, File Pass to?

☐ : Prell. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S + RS. \$

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

Date: 08/04/2022

Vehicle No: SMH7091U

Model: HONDA FIT HYBRID 1.5

Chassis: GP51336962-2018

Reg.Year: 2019

*Not Notified
L1 Rep @ 26501
Presumably After Party
5 days*

Third Party Insurer: LONPAC

Third Party Veh No: GBC4326U

Date of Accident: 07/04/2022

Estimator: TING AN

Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT SIDE MIRROR ASSY LH	1	<i>Ref/Gr</i>	\$715.40 ✓
2	FRONT DOOR LH	1	<i>Ry</i>	\$881.20 —
3	FRONT DOOR PROTECTIVE STICKER LH	1	<i>na</i>	\$45.90 —
4	FRONT DOOR INNER TRIM BOARD LH	1	<i>Sn</i>	\$796.20 X
5	REAR DOOR LH	1	<i>Ry</i>	\$765.20 ✓
6	REAR DOOR PROTECTIVE STICKER LH	1	<i>na</i>	\$36.20 —
7	REAR DOOR INNER TRIM BOARD LH	1	<i>Sn</i>	\$766.10 X
8	REAR DOOR RUBBER SEAL LH	1	<i>Dis</i>	\$46.80 ✓
9	REAR DOOR UPPER HINGE LH	1	<i>R</i>	\$46.60 X
10	REAR DOOR LOWER HINGE LH	1	<i>R</i>	\$46.60 X
11	REAR DOOR CHECKER LH	1	<i>Sn</i>	\$48.50 X
12	REAR DOOR REGULATOR LH	1	<i>Sn</i>	\$191.60 X
13	REAR FENDER LH	1	<i>R</i>	\$887.80 X
SUB TOTAL				\$5,274.10
LESS 20%				-\$1,054.82
PARTS TOTAL				\$4,219.28

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT DOOR INNER TRIM BOARD CLIPS LH	1	<i>na</i>	\$50.00 X
2	REAR DOOR INNER TRIM BOARD CLIPS LH	1	<i>na</i>	\$50.00 X
3	REAR QUARTER GLASS SEALANT LH	1	<i>na</i>	\$70.00 X
S/N TOTAL				\$170.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX & READJUST ACCIDENT AREAS & ETC.

5001
\$800.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT DOOR LH, REAR DOOR LH, REAR FENDER LH & ETC.

6501
\$800.00

LABOUR CHARGES TO REMOVE & REINSTALLED FRONT DOOR INNER MECHANISM & ETC. TO EFFECT REPLACE OF FRONT DOOR LH.

601
\$120.00

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 08/04/2022
Vehicle No: SMH7091U
Model: HONDA FIT HYBRID 1.5
Chassis: GP51336962-2018
Reg.Year: 2019

Third Party Insurer: LONPAC
Third Party Veh No: GBC4326U
Date of Accident: 07/04/2022
Estimator: TING AN
Surveyor:

LABOUR CHARGES TO REMOVE & REINSTALLED ^{na} FRONT DOOR INNER MECHANISM & ETC. TO EFFECT REPLACE OF REAR DOOR LH.

\$120.00 ^{60%}

LABOUR CHARGES TO REMOVE & REFIX REAR FENDER INNER TRIM , ROOF LINING & ETC. TO EFFECT REPLACE OF REAR FENDER LH.

^{na} \$200.00 ^X

TO TUFF KOTE & UNDERSEAL MATERIALS.

^{60%} \$120.00

TO CHECK WIRING & LOCKING SYSTEM.

\$100.00 ^{20%}

LABOUR TOTAL \$2,260.00

TING AN

TOTAL

\$6,649.28

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

