

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22003275/UPA3Q2**Date:** 05/07/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993544
Claimant Vehicle No :	SLH1026K	Insured Vehicle No :	GBC7085U
Date of Loss:	07/04/2022	Nature of Claim:	TP
		Claim No:	5661111906SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLH1026K	Engine No:	L15B4405532
Make & Model:	HONDA VEZEL, 1.5 X CVT (A)	Chassis No:	RU11205532
Reg. Date:	24/10/2016 (Man. Year: 2016)	Odometer:	126993 km
Colour:	Blue		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,234.94	632.50	2,602.44	80.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,540.00	720.00	820.00	53.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,774.94	1,352.50	3,422.44	71.68
+ GST 7.00/7.00% (S\$)	334.25	94.68	239.57	71.67
Nett Amount (S\$)	5,109.19	1,447.18	3,662.01	71.67
+ Car Rental (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		1,754.63		

INSPECTION

Date of Assignment:	19/04/2022	Hock Wah Motor Workshop Pte Ltd (Bedok)
Date Inspected:	19/04/2022 Inspected At:	Blk 3011, Bedok Industrial Park E,, #01-2008/2010/2012
Estimated Period of Repair:	3.0 days	Singapore 489977

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER FOGLAMP COVER RH	Not Necessary	38.00 FL	*- FL
2	1		*FRONT BUMPER FOGLAMP RH	Not Necessary	330.50 FL	*- FL
3	1		*HEADLAMP RH	Serviceable	1,997.60 FL	*- FL
4	1		*FRONT FENDER INNER SHIELD RH	Not Necessary	112.30 FL	*- FL
5	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	259.40 FL	*- FL
6	1		*WASHING TANK	Not Necessary	87.90 FL	*- FL
7	1		*WASHING TANK MOTOR	Not Necessary	65.90 FL	*- FL
8	1		*FRONT BUMPER	Dented	350.00 F	*350.00 F
9	1		*FRONT BUMPER RETAINER RH	Bent	15.00 F	*15.00 F
10	1		*FRONT BUMPER LOWER SPOILER	Distorted	150.00 F	*150.00 F
11	1		*FRONT FENDER PROTECTOR RH	Distorted	60.00 F	*60.00 F
12	1		*FRONT FENDER RH (NPA)	Repair	0.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,466.60	575.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	578.32	0.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	346.66	57.50
Total Parts (\$\$)	3,234.94	632.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO REMOVE & REFIT NECESSARY PARTS	New	700.00	300.00
2	SPRAY PAINT ON THE AFFECTED AREAS	New	700.00	400.00
3	ANTI-RUST COATING	New	100.00	0.00
4	WIRING	New	40.00	20.00
Gross Labour Cost (\$\$)			1,540.00	720.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >