

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/III22003277/UEA3Q2**Date:** 23/06/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D22MPC0002118
Claimant Vehicle No : SLR6082L **Insured Vehicle No :** SMY581D
 Date of Loss: 31/03/2022 Nature of Claim: TP Claim No: MPC2022D0001808

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLR6082L**
 Make & Model: NISSAN PULSAR, 1.2 (A) Engine No: HRA2466822A
 Reg. Date: 21/08/2017 (Man. Year: 2017) Chassis No: VSKDDAC13U0111089
 Colour: Red Odometer: 146158 km
 Engine Capacity: 1197 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/50 R17 Rear Tyre Size: 205/50 R17
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,417.90	3,448.81	3,969.09	53.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,260.00	1,320.00	940.00	41.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,677.90	4,768.81	4,909.09	50.72
Approved Total (Overridden) (S\$)		3,800.00		
(S\$)	9,677.90	3,800.00	5,877.90	60.74
+ GST 7.00/7.00% (S\$)	677.45	266.00	411.45	60.74
Nett Amount (S\$)	10,355.35	4,066.00	6,289.35	60.74
+ Loss of Use (4.0 x S\$60.00/day) (S\$)		240.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,308.00		
Global Sum Settlement (S\$)		4,300.00		

INSPECTION

Date of Assignment: 05/05/2022
 Date Inspected: 05/05/2022 Inspected At: Hock Wah Motor Workshop Pte Ltd (Bedok)
 2008/2010/2012
 Singapore 489977
 Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Jun 2022)
Parts:	144	NISSAN PULSAR 1.2 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLR6082L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Badly Dented	1,485.70 FL	*1,372.90 FL
2	1		*TAILGATE EMBLEM	Necessary	74.60 FL	*74.60 FL
3	1		*TAILGATE LOGO -PULSAR	Necessary	91.80 FL	*91.80 FL
4	1		*TAILGATE OUTER HANDLE	Cracked	330.40 FL	*330.40 FL
5	1		*REAR NUMBER PLATE LAMP	Not Necessary	92.20 FL	*- FL
6	1		*REVERSE CAMERA	Not Necessary	862.50 FL	*- FL
7	1		*TAILGATE DAMPER	Not Necessary	308.50 FL	*- FL
8	1		*TAILGATE REFLECTOR RH	Not Necessary	570.20 FL	*- FL
9	1		*TAILGATE REFLECTOR LH	Not Necessary	570.20 FL	*- FL
10	1		*TAILLAMP N/S	Cracked	798.30 FL	*466.50 FL
11	1		*TAILGATE INNER LOCK	Bent / Shorted	199.10 FL	*109.60 FL
12	1		*REAR BUMPER	Dented / Deformed	1,228.70 FL	*886.00 FL
13	1		*REAR BUMPER RETAINER RH	Bent	75.70 FL	*45.00 FL
14	1		*REAR BUMPER RETAINER LH	Bent	75.70 FL	*45.00 FL
15	1		*REAR BUMPER LOWER STICKER	No such part	124.20 FL	*- FL
16	3		*REAR BUMPER CLIP	Necessary	19.20 FL	*19.20 FL
17	1		*REAR BUMPER REINFORCEMENT	Repair	630.90 FL	*- FL
18	1		*TAILGATE WINDSCREEN MOULDING	Necessary	79.90 FL	*79.90 FL
19	1		*TAILGATE INNER RUBBER	Not Necessary	193.20 FL	*- FL
20	2		*WINDSCREEN SEALANT	Necessary	48.00 FS	*40.00 FS
21	1		*REAR NUMBER PLATE }	Bent	30.00 FS	*40.00 FS
22	1		*REAR NUMBER PLATE HOLDER }	Bent	30.00 FS	*- FS
23	1		*REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
24	1		*END PANEL (NPA)	Repair	0.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,199.00	3,800.90
- List Item Discount on L Items 10.00/10.00% (\$\$)	781.10	352.09

Total Parts (\$\$)	7,417.90	3,448.81
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO REMOVE & REFIT NECESSARY PARTS	New	900.00	500.00
2	SPRAY PAINT ON THE AFFECTED AREAS	New	800.00	600.00
3	ANTI-RUST COATING	New	150.00	30.00
4	WIRING	New	80.00	20.00
5	TO REMOVE & REFIT WINDSCREEN	New	180.00	120.00
6	TO REMOVE & REFIT REVERSE SENSOR	New	150.00	50.00
Gross Labour Cost (\$)			2,260.00	1,320.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >