

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC6/11122003277/Uea3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / (TP) / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLR6082L
hockwob

at Workshop m/s

of

Insured:

SMY581D

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

\$58k.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4
20

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

610j
Vehicle: IN / OUT

Date:

Person Contacted:

274 30392

Date / Time

Action / Instruction

Rep 1 OK.

tailay 466-80

10/5/22 4/5 3800 informed Anyse

Veh No:

SLR6082L

Yr Regn:

21/08/17

Type: (M).Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA/

Make:

Nissan Pulsar

c.c

1197

Colour:

Red

A/C:

Insured / Std / NI / NA

Sp. Reading

14615-8

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

VSKDDAC1340711089

Gen. Cond: (Good) / Fair / Poor / BurntSteering: (In order) / Jammed / Leaked / Burnt orBrake: (In order) / Jammed / Leaked / Burnt orModi: Nil / (S)Rim / STD A/Rim or

Tyre Size:

F:

R:

205/50 R 17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

6

mm

Rear

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

31/03/22

D.O.I.

5/5/22

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

HOCK WAH MOTOR WORKSHOP PTE LTD

3LK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : SXXXX6101
TEO CHEW CHUAN
NO

SINGAPORE
TEL : FAX :
PH : 97245771
ATTN :

Term:

ESTIMATE BILL

Number : EB00005934
Date : 08/04/2022
Case No : AD00012564
Vehicle No : SLR6082L
Chassis : VSKDDAC13U0111089
Year of Mfr : 2017
Policy No : 5110906392-02
Model : NISSAN PULSAR

not Allowed
2/5/22
3800/
4 days
Whip it After my

net hitan

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	TAILGATE 305625 137290	1.0	1,485.70	10	1,337.13
2	TAILGATE EMBLEM neu	1.0	74.60	10	67.14
3	TAILGATE LOGO - PULSAR neu	1.0	91.80	10	82.62
4	TAILGATE OUTER HANDLE 1/2	1.0	330.40	10	297.36
5	REAR NUMBER PLATE LAMP ^	1.0	92.20	10	82.98
6	REVERSE CAMERA ^	1.0	862.50	10	776.25
7	TAILGATE DAMPER ^	1.0	308.50	10	277.65
8	TAILGATE REFLECTOR RH ^	1.0	570.20	10	513.18
9	TAILGATE REFLECTOR LH ^	1.0	570.20	10	513.18
10	REAR FENDER LAMP LH 7011amp nts cra 466.50	1.0	798.30	10	718.47
11	TAILGATE INNER LOCK 3011/12 108.60	1.0	199.10	10	179.19
12	REAR BUMPER 120/12 886.00	1.0	1,228.70	10	1,105.83
13	REAR BUMPER RETAINER RH 3011 45	1.0	75.70	10	68.13
14	REAR BUMPER RETAINER LH 3011 45	1.0	75.70	10	68.13
15	REAR BUMPER LOWER STICKER n/s	1.0	124.20	10	111.78
16	REAR BUMPER CLIP neu	3.0	6.40	10	17.28
17	REAR BUMPER REINFORCEMENT R	1.0	630.90	10	567.81
18	TAILGATE WINDSCREEN MOULDING neu	1.0	79.90	10	71.91
19	TAILGATE INNER RUBBER ^	1.0	193.20	10	173.88
Nett Price - Parts Sub Total					7,029.90
20	WINDSCREEN SEALANT neu	2.0	24.00	0	48.00
21	REAR NUMBER PLATE 3011	1.0	30.00	0	30.00
22	REAR NUMBER PLATE HOLDER 3011	1.0	30.00	0	30.00
23	REVERSE SENSOR 3011	1.0	280.00	0	280.00
24	END PANEL - REPAIR R X	1.0			
Special Nett Price - Parts Sub Total					388.00
Parts Total					7,417.90
25	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	900.00	0	900.00
26	SPRAY PAINT ON THE AFFECTED AREAS	1.0	800.00	0	800.00
27	ANTI-RUST COATING	1.0	150.00	0	150.00
28	WIRING	1.0	80.00	0	80.00
29	TO REMOVE & REFIT WINDSCREEN	1.0	180.00	0	180.00
30	TO REMOVE & REFIT REVERSE SENSOR	1.0	150.00	0	150.00

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

2-3520.80
102
3168.81
260
1320
4768.81

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : SXXXX610I
TEO CHEW CHUAN
NO

SINGAPORE
TEL : FAX :
PH : 97245771
ATTN :

ESTIMATE BILL

Number : EB00005934
Date : 08/04/2022
Case No : AD00012564
Vehicle No : SLR6082L
Chassis: VSKDDAC13U0111089
Year of Mfr 2017
Policy No 5110906392-02
Model : NISSAN PULSAR

Term:

Sn	DESCRIPTION	QTY	U_PRICE	DISC	AMOUNT
	Labour 1 Sub Total				2,260.00
<u>LKK Auto Consultants hence notify the Repairer of the following:</u> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:					
SINGAPORE DOLLARS : TEN THOUSAND THREE HUNDRED FIFTY-FIVE AND CENTS THIRTY-FIVE ONLY			Less Excess		0.00
			SUBTOTAL		9,677.90
			GST 7.00%		677.45
			TOTAL		10,355.35

Date of accident : 31/03/2022 06:30 PM. Place : TPE > SENGKANG BEFORE EXIT 9

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE