

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG22003278/BGA3Q2**Date:** 15/06/2022REFERENCE

|                              |                                      |                             |              |
|------------------------------|--------------------------------------|-----------------------------|--------------|
| Handling Insurer:            | AIG Asia Pacific Insurance Pte. Ltd. | Policy No:                  | 7210044978   |
| <b>Claimant Vehicle No :</b> | SJS3999E                             | <b>Insured Vehicle No :</b> | GBH8030U     |
| Date of Loss:                | 06/04/2022                           | Nature of Claim:            | TP           |
|                              |                                      | Claim No:                   | 7805815811SG |

DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                                  |             |                   |
|-----------------------------|--------------------------------------------------|-------------|-------------------|
| Reg No:                     | <b>SJS3999E</b>                                  |             |                   |
| Make & Model:               | KIA CERATO FORTE, 1.6 SX AT ABS D/AB 2WD 4DR (A) | Engine No:  | G4FC9H263385      |
| Reg. Date:                  | 29/06/2009 (Man. Year: 2009)                     | Chassis No: | KNAFH221395086464 |
| Colour:                     | White                                            | Odometer:   | 194724 km         |
| Engine Capacity:            | 1591 cc                                          |             |                   |
| Market Value/New Car Price: | N/A                                              |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b>                |             |                   |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

CONDITION OF TYRES

|                   |               |                  |               |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size:  | 215/45 R17    | Rear Tyre Size:  | 215/45 R17    |
| Front Left Side:  | Michelin 4 mm | Rear Left Side:  | Michelin 4 mm |
| Front Right Side: | Michelin 4 mm | Rear Right Side: | Michelin 4 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                            | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|--------------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                            | 6,670.60          | 2,545.96          | 4,124.64          | 61.83         |
| Miscellaneous Items                              | 0.00              | 0.00              | 0.00              |               |
| Labour                                           | 4,200.00          | 1,600.00          | 2,600.00          | 61.90         |
| Paintwork Labour                                 | 0.00              | 0.00              | 0.00              |               |
| Towing                                           | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>              | <b>10,870.60</b>  | <b>4,145.96</b>   | <b>6,724.64</b>   | <b>61.86</b>  |
| <b>Approved Total (Overridden) (S\$)</b>         |                   | <b>3,300.00</b>   |                   |               |
| <b>(S\$)</b>                                     | 10,870.60         | 3,300.00          | 7,570.60          | 69.64         |
| <b>+ GST 7.00/7.00% (S\$)</b>                    | 760.94            | 231.00            | 529.94            | 69.64         |
| <b>Nett Amount (S\$)</b>                         | <b>11,631.54</b>  | <b>3,531.00</b>   | <b>8,100.54</b>   | <b>69.64</b>  |
| <b>+ Car Rental (12.0 x S\$100.00/day) (S\$)</b> |                   | 1,200.00          |                   |               |
| <b>+ Doc/Search Fee (S\$)</b>                    |                   | 7.45              |                   |               |
| <b>Nett Liability (S\$)</b>                      |                   | <b>4,738.45</b>   |                   |               |
| <b>Global Sum Settlement (S\$)</b>               |                   | <b>4,700.00</b>   |                   |               |

INSPECTION

|                             |                          |                                              |
|-----------------------------|--------------------------|----------------------------------------------|
| Date of Assignment:         | 08/04/2022               | Team Autopro Pte Ltd (sin Ming) (HQ)         |
| Date Inspected:             | 08/04/2022 Inspected At: | 160 SIN MING DRIVE, #01-14 SIN MING AUTOCITY |
| Estimated Period of Repair: | 7.0 days                 | Singapore 575722                             |

**Adjuster:** Lim Teow Guan

**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                   | Condition     | Repairer's  | Amount     |
|-----|-----|----------|-------------------------------|---------------|-------------|------------|
| 1   | 1   |          | *BONNET                       | Dented        | 985.00 FL   | *830.50 FL |
| 2   | 1   |          | *BONNET INSULATOR             | No such part  | 145.00 FL   | *- FL      |
| 3   | 1   |          | *BONNET LOCK ASSY             | Jammed        | 98.20 FL    | *98.20 FL  |
| 4   | 2   |          | *BONNET HINGE                 | Bent          | 172.60 FL   | *138.00 FL |
| 5   | 1   |          | *FRONT BUMPER (FIBRE)         | Broken        | 1,458.00 FL | *562.00 FL |
| 6   | 1   |          | *FRONT BUMPER REINFORCEMENT   | Not Damaged   | 410.60 FL   | *- FL      |
| 7   | 2   |          | *FRONT BUMPER FOG LAMP        | Not Damaged   | 428.00 FL   | *- FL      |
| 8   | 1   |          | *FRONT SUPPORT PANEL          | Bent          | 861.00 FL   | *500.00 FL |
| 9   | 1   |          | *FRONT FENDER                 | Repair        | 541.00 FL   | *- FL      |
| 10  | 2   |          | *HEADLAMP                     | Broken        | 1,370.40 FL | *860.00 FL |
| 11  | 1   |          | *HEADLAMP LOWER BRACKET       | O/S Broken    | 172.20 FL   | *32.50 FL  |
| 12  | 1   |          | *A/C CONDENSER                | Not Damaged   | 758.00 FL   | *- FL      |
| 13  | 1   |          | *SUNDRIES                     | No such part  | 80.00 FS    | *- FS      |
| 14  | 1   |          | *BONNET SEALANT               | Necessary     | 80.00 FS    | *30.00 FS  |
| 15  | 1   |          | *BONNET INSULATOR CLIPS       | Not Necessary | 50.00 FS    | *- FS      |
| 16  | 1   |          | *FRONT BUMPER CLIPS           | Necessary     | 50.00 FS    | *30.00 FS  |
| 17  | 2   |          | *FRONT BUMPER SIDE RETAINER   | Necessary     | 170.60 FS   | *69.00 FS  |
| 18  | 1   |          | *FRONT NUMBER PLATE W/COWLING | Not Damaged   | 80.00 FS    | *- FS      |
| 19  | 1   |          | *FRONT FENDER SEALANT         | Not Necessary | 80.00 FS    | *- FS      |
| 20  | 1   |          | *A/C FLUID                    | Not Necessary | 80.00 FS    | *- FS      |
| 21  | 1   |          | *RADIATOR COOLANT             | Not Necessary | 80.00 FS    | *- FS      |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                            |                 |                 |
|------------------------------------------------------------|-----------------|-----------------|
| <b>Sub Total (\$\$)</b>                                    | <b>8,150.60</b> | <b>3,150.20</b> |
| <b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b> | 1,480.00        | 604.24          |
| <b>Total Parts (\$\$)</b>                                  | <b>6,670.60</b> | <b>2,545.96</b> |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No                              | Particulars       | Lab.Type | Repairer's      | Amount          |
|---------------------------------|-------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>             |                   |          |                 |                 |
| 1                               | R&R RADIATOR      | New      | 150.00          | 0.00            |
| 2                               | R&R A/C CONDENSER | New      | 150.00          | 0.00            |
| 3                               | CHECK WIRING      | New      | 100.00          | 0.00            |
| 4                               | PANEL BEATING     | New      | 1,800.00        | 800.00          |
| 5                               | RUST PROOFING     | New      | 200.00          | 0.00            |
| 6                               | SPRAY PAINTING    | New      | 1,800.00        | 800.00          |
| <b>Gross Labour Cost (\$\$)</b> |                   |          | <b>4,200.00</b> | <b>1,600.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >