

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI22003282/ENY3E2

**Date:** 23/08/2022

### REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMB1SNW00001062201  
Claimant Vehicle No: GBB793K Insured Vehicle No: CB6334B  
Date of Loss: 30/03/2022 Nature of Claim: TP Claim No: SNM22D202235/C02/LEWLC

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBB793K  
Make & Model: TOYOTA DYNA 1.5T, 3.0 (A) Engine No: 1KD1826518  
Reg. Date: 26/06/2008 (Man. Year: 2008) Chassis No: JTFAT35Y903001858  
Colour: White Odometer: 354009 km  
Engine Capacity: 2982 cc  
Market Value/New Car Price: N/A  
Sum Insured (\$\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 195 R15C Rear Tyre Size: 195 R15C  
Front Left Side: Goodyear 4 mm Rear Left Side: Goodyear 4 mm  
Front Right Side: Goodyear 4 mm Rear Right Side: Goodyear 4 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,360.00	6,660.00	1,700.00	20.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,650.00	2,000.00	2,650.00	56.99
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>13,010.00</b>	<b>8,660.00</b>	<b>4,350.00</b>	<b>33.44</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>6,950.00</b>		
<b>(\$\$)</b>	13,010.00	6,950.00	6,060.00	46.58
<b>+ GST 7.00/7.00% (\$\$)</b>	910.70	486.50	424.20	46.58
<b>Nett Amount (\$\$)</b>	<b>13,920.70</b>	<b>7,436.50</b>	<b>6,484.20</b>	<b>46.58</b>

### INSPECTION

Date of Assignment: 08/04/2022  
Date Inspected: 14/04/2022 Inspected At: Systematic Airconditioning Pte Ltd (HQ)  
29 Senoko Way  
Singapore 758059  
Estimated Period of Repair: 9.0 days

**Adjuster:** CHEN TSUE YEE

**Manager:** HUEY YON

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 23 Aug 2022)	
Parts:	N/A	TOYOTA DYNA 1.5T 3.0 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBB793K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR STAINLESS STEEL FRAME	Dented	4,500.00 F	*4,000.00 F
2	1		*SIDE ALUMINIUM CAPPING	Broken	780.00 F	*780.00 F
3	10		*SEALANT TUBE	Necessary	250.00 F	*250.00 F
4	4		*STAINLESS STEEL HINGES	Necessary	1,120.00 F	*600.00 F
5	2		*STAINLESS STEEL DOOR HANDLE	Necessary	180.00 F	*180.00 F
6	1		*REAR METAL BUMPER	Dented	480.00 F	*480.00 F
7	1		*SET BRACKET FOR METAL BUMPER	Bent	120.00 F	*120.00 F
8	2		*REAR RUBBER STOPPER (BUMPER)	Torn	250.00 F	*250.00 F
9	1		*ARTWORK STICKER (REAR DOORS)	Not Necessary	680.00 F	*- F
					Total Parts (S\$)	
					8,360.00	6,660.00

F=Franchise part.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO SUPPLY LABOUR AND MATERIAL TO FIBERGLASS REPAIR	New	600.00	300.00
2	TO SUPPLY LABOUR AND MATERIAL TO PAINT BLACK THE REAR METAL BUMPER AND BRACKET	New	400.00	200.00
3	TO SUPPLY LABOUR AND MATERIAL TO TIG WELDING REAR METAL BUMPER WITH BRACKET	New	350.00	0.00
4	TO REMOVE, REFIX AND TO RENEW AFFECTED PARTS	New	2,500.00	1,500.00
5	TO REALIGNMENT REF BOX	New	800.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>4,650.00</b>	<b>2,000.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >