LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS22003286/RQY3E2

764247 km

Date: 20/09/2022

Odometer:

REFERENCE

Handling Insurer: ECICS Limited

CS Limited Policy No:

Claimant Vehicle

PC797D

Insured Vehicle No: SMD7933L

Date of Loss: 06/04/2022 Nature of Claim: TP Claim No: DMCF2200008H/02/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: PC797D

Make & Model: TOYOTA HIACE, 3.0 (A) Engine No: 1KD2107916

Reg. Date: 01/08/2011 (Man. Year: 2011) Chassis No: JTFST22P100011084

Colour: White

Engine Capacity: 2982 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15C Rear Tyre Size: 195 R15C
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,677.90	2,393.97	3,283.93	57.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,010.00	1,470.00	1,540.00	51.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,687.90	3,863.97	4,823.93	55.52
Approved Total (Overridden) (S\$)		3,100.00		
(S\$)	8,687.90	3,100.00	5,587.90	64.32
+ GST 7.00/7.00% (S\$)	608.15	217.00	391.15	64.32
Nett Amount (S\$)	9,296.05	3,317.00	5,979.05	64.32

INSPECTION

Date Inspected:

Date of Assignment: 11/04/2022

My Car Consultant Pte Ltd (Jalan Lam Huat)

14/06/2022 Inspected At: (HQ)

60 Jalan Lam Huat, Carros Centre #05-21

Singapore 737869

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 19 Sep 2022)

Parts: N/A TOYOTA HIACE 3.0 (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for PC797D)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	2,459.00 FL	*2,151.10 FL
2	1		*TAILGATE INNER LOCK	Serviceable	387.20 FL	*- FL
3	1		*TAILGATE WEATHERSTRIP	Not Necessary	259.00 FL	*- FL
4	2		*TAILGATE NUMBER PLATE LAMP	Not Necessary	90.00 FL	*- FL
5	1		*TAILGATE LOGO	Necessary	65.00 FL	*65.00 FL
6	1		*TAILGATE WINDSCREEN MOULDING	Necessary	157.00 FL	*157.00 FL
7	2		*TAILAMP LOWER GARNISH	Serviceable	318.00 FL	*- FL
8	1		*REAR BUMPER	Deformed	698.00 FL	*632.20 FL
9	2		*REAR BUMPER SIDE RETAINER	Serviceable	242.00 FL	*-FL
10	3		*REAR BUMPER LOWER BRACKET	Serviceable	132.00 FL	*-FL
11	1		*REAR END PANEL OUTER	Repair	514.00 FL	*-FL
12	1		*REAR END PANEL TOP PLATE	Serviceable	251.00 FL	*-FL
13	1		*REAR FLOOR PANEL MAT	Not Necessary	1,025.00 FL	*-FL
14	1		*SET REAR BUMPER CLIP	Necessary	80.00 FS	*40.00 FS
15	1		*REAR REVERSE SENSOR	Not Necessary	250.00 FS	*-FS
16	1		*TAILGATE STICKER 70KM	Necessary	30.00 FS	*10.00 FS
17	1		*TAILGATE STICKER EMERGENCY	Necessary	30.00 FS	*10.00 FS
18	1		*TAILGATE WINDSCREEN INNER SEAL	Necessary	80.00 FS	*40.00 FS
19	1		*TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
20	1		*REAR END PANEL GARNISH CLIP	Not Necessary	30.00 FS	*-FS
21	1		*END PANEL SEALANT OUTER	Not Necessary	150.00 FS	*-FS
F=Fra	nchise	part. S=SpcN	ett. L=ListItemDisc.	_		
				Sub Total (S\$)	7,327.20	3,145.30
			- List Item Discount on	L Items 25.00/25.00% (S\$)	1,649.30	751.33
				Total Parts (S\$)	5,677.90	2,393.97

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO CHECK ELECTRICAL WIRING	New	200.00	0.00
2	TO REMOVE AND REFIT REVERSE SENSOR	New	150.00	60.00
3	REMOVE AND REFIX TAILGATE MECHANISM	New	120.00	60.00
4	REMOVE AND REFIX UPHOLSTERY SEAT	New	300.00	0.00
5	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	120.00	120.00
6	APPLY ANTI RUST ON AFFECTED AREAS	New	120.00	30.00
7	SPRAY PAINTING ON AFFECTED AREAS	New	1,000.00	600.00
8	PANEL BEATING ON AFFECTED AREAS	New	1,000.00	600.00
		Gross Labour Cost (S\$)	3,010.00	1,470.00
	Report was unsub	mitted during this print-out.		

< END OF ESTIMATES >