



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJP 831R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BUMPER (SN)	DEFORMED	2,093.33	2,093.33
2	RIVET (SN)	NECESSARY	9.62	9.62
1	CTR BASIC MOUNTING FOR BUMPER (SN)	NOT NECESSARY	131.66	-
1	REAR BUMPER CHROME MOULDING (SN)	NOT NECESSARY	355.64	-
1	REAR LOWER BUMPER (SN)	NOT NECESSARY	329.97	-
3	GROMMET (SN)	NECESSARY	7.92	7.92
1	MERCEDES STAR (SN)	NECESSARY	53.84	53.84
1	BOOT CHROME MOULDING (SN)	NOT NECESSARY	168.28	-
1	E250 MODEL PLATE (SN)	NECESSARY	94.08	94.08
1	TRUNK LID (SN)	TO REPAIR SEE LABOUR	2,663.84	-
1	REAR CROSS MEMBER (SN)	NOT NECESSARY	925.24	-
1	SUNDRIES (SN)	NECESSARY	15.00	15.00
			6,848.42	2,273.79
	<b><u>LABOUR</u></b>			
	USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT.RESET MEMORY TO IDENTIFICATION STANDARD.		380.00	380.00
	DISASSEMBLE AND REPLACE ON REAR BUMPER,BOOT AND ACCIDENT AFFECTED AREA.INCLUSIVE OF THE REPAIR OF TRUNK LID.		1,920.00	960.00
	RESPRAY ON REAR BUMPER,BOOT AND ACCIDENT AFFECTED AREA.		1,800.00	1,500.00
			4,100.00	2,840.00
	<b>GRAND TOTAL</b>		<b>10,948.42</b>	<b>5,113.79</b>
	<b>RECOMMENDED COST OF REPAIRS</b>			<b>5,113.79</b>

Report Ref No. CS/AIS22003287/Rty3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.